



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info														
MSIG INSURANCE (SINGAPORE) PTE LTD 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 Contact No 62209644	<table> <tr> <td>Cust No/Name</td><td>/Mr Tan En Lai Kevin (chen Enlai</td></tr> <tr> <td>Reg No/Reg Date</td><td>ES6611M / 18/04/2018</td></tr> <tr> <td>Date In/Mileage</td><td>04/11/2019/ 43923</td></tr> <tr> <td>Chassis No</td><td>KNAHU815VJ7193577</td></tr> <tr> <td>Engine No</td><td>D4FDHH109602</td></tr> <tr> <td>Make/Model</td><td>KIA/CARENS 1.7 A D SX FL DY6</td></tr> <tr> <td>Colour/Trim</td><td>K7N / WK</td></tr> </table>	Cust No/Name	/Mr Tan En Lai Kevin (chen Enlai	Reg No/Reg Date	ES6611M / 18/04/2018	Date In/Mileage	04/11/2019/ 43923	Chassis No	KNAHU815VJ7193577	Engine No	D4FDHH109602	Make/Model	KIA/CARENS 1.7 A D SX FL DY6	Colour/Trim	K7N / WK
Cust No/Name	/Mr Tan En Lai Kevin (chen Enlai														
Reg No/Reg Date	ES6611M / 18/04/2018														
Date In/Mileage	04/11/2019/ 43923														
Chassis No	KNAHU815VJ7193577														
Engine No	D4FDHH109602														
Make/Model	KIA/CARENS 1.7 A D SX FL DY6														
Colour/Trim	K7N / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000017	Credit	15/11/2019/ 14:07	DS	218 / MarsLer	34739			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC / SCANNING						250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						80.00
S	MIPNT88088	TO REPLACE TAILGATE GLASS						300.00
M	SUNDRY	SEALANT KIT ON TAILGATE GLASS						100.00
S	MIPNT88088	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS						220.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						300.00
S	MIPNT88088	TO REPLACE TAILGATE PNL,RR BUMPER,REINFORCEMENT,ETC -INCLUDE TRANSFER TAILGATE COMPONENT & MECHANISM PARTS -REPAIR REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS						2100.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL						100.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						1260.00
S	MIPNT88088	APPLY PRIVATE-HIRE CAR DECAL INSTALLATION (AFTER REPLACEMENT TAILGATE GLASS)						(A) 20.00
X	KS 86611 A4 010	COVER - REAR BUMPER,			1.00	576.00	0.00	576.00
X	KS 86612 A4 810	COVER - REAR BUMPER			1.00	201.00	0.00	201.00
X	KS 86617 A4 800	CAP-RR HOOK			1.00	4.00	0.00	4.00
X	KS 86682 A4 010	HOLDER - BACK WARNIN			2.00	4.00	0.00	8.00
X	KS 86682 A4 020	HOLDER - BACK WARNIN			2.00	4.00	0.00	8.00
X	KS 86665 A4 800	SKID PLATE-RR BUMPER			1.00	179.00	0.00	179.00
X	KS 95720 A4 100K 7N	ULTRASONIC SENSOR AS			1.00	162.00	0.00	162.00

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.