LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Pang Xiu Shi Date: 07 Nov 2019

Preliminary Advice

Vehicle No : SLT1715S **Accident Date** : 12/10/2019 : VOLKSWAGEN TIGUAN R-LINE Make Policy No. : 29038734AVW Assignment Date : 16/10/2019 **Excess** : S\$2,000.00 Date of Inspection : 17/10/2019 Est. Duration of Repair : 7 days

Inspection At : Volkswagen Group Singapore Pte Ltd (Alexandra)

247 ALEXANDRA ROAD Singapore 159934

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,828.47 (Inclusive supp)
Revised Amount	:S\$	8,580.29 (Inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,580.29

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	148,000.00
COE / PARF Rebate	:S\$	76,035.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,965.00

Remarks

(X)	The vehicle is economical for repair. We have received supplementary from repairer. Our surveyor had
	since checked and verified the supplementary parts and is of the view that the supplementary parts are
	consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 71.83.

() The above survey was conducted on a 'without prejudice' basis.