

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 18 Oct 2019

Preliminary Advice

Vehicle No	: SLT1715S	Accident Date	: 12/10/2019
Make	: VOLKSWAGEN TIGUAN R-LINE	Policy No.	: 29038734AVW
Assignment Date	: 16/10/2019	Excess	: S\$1,500.00
Date of Inspection	: 17/10/2019	Est. Duration of Repair	: 7 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (Alexandra) 247 ALEXANDRA ROAD Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,756.64
Revised Amount	:S\$	9,804.60
Check Items (Estimated)	:S\$	1,800.17
Total	:S\$	11,604.77

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	148,000.00
COE / PARF Rebate	:S\$	76,035.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,965.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.