

200000

ASS. REC. BY:

REF: CS/CT119018311/Tlyf302

Special Instruction:

photo 0.x

Surveyor: Tan Kah

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CTI

Date/Time: 16.10.2019 16.45p.m

Estimated Cost:

Bill to:

OD TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 1397K

Insured: SJV 3158E

at Workshop m/s: Kah Motor

Tel: 68425671 / 90721769

of 15 Ubi Road 4

Policy No: DMHCSN19212819000

Claim No: SNM 19020487902

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.10.19 9.05a.m

Person Contacted: Syg Hai

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate by: 2515 Alexandra Road
	SJR 1397K - MBA / CTI 190183229 / 4 DOA - 14/10/2019
	SJV 3158E - MBA / CTI 190183229 / 4 DOA - 15/10/2019

REV 10/11

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Tuesday, November 05, 2019 9:54 AM
To: Ng Sin Hai; Taufikh (LKKAuto); SUR
Subject: RE: Submission Pre-Invoice for vehicle SJR1397K

Morning Sin Hai

Confirm P/P \$47,424.76 @ 20 working days

Kindly send final invoice and all supporting documents directly to CHINA TAIPING Insurance.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne Wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]
Sent: Thursday, October 31, 2019 3:53 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SJR1397K

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$47,424.76 (before GST)

No of working days : 20 days. (LOU)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Oct 2019		16 Oct 2019 16:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: BEH SWAN GIN , ID: S2605937B									
Vehicle Reg. No.:		SJR1397K	Date of Loss:	15/10/2019 12:00 - :59					
Claim Type:		TP / SNM19D204879C02	Policy/Cover Note No.:	DMHCSN19212819000					
Vehicle Reg. No. (Insured):		SJV3156E	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]							
Claimant's Insurer:		Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/10/2019]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2019 19:15
Date Of Accident	15/10/2019 12:30
Exact Location Of Accident	CHIN SWEE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR1397K
Insured/Policyholder	
Name Of Registered Owner	BEH SWAN GIN
NRIC No	S2605937B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97649928
Alternative Phone No	OFFICE-97649928

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MAISY KOH
NRIC No	S7336273C
Date Of Birth	05/10/1973
Occupation	INDOOR
Date Of Driving Pass	27/11/1997
Driving Experience	21 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97649928
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address S

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 4

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV3156E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLP8141Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SHA1761E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

Vehicle Number: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

File Number: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

It was along Chin Swee Road around 12:30pm.
The weather was clear.

The car ^C in front of me stopped, and rather suddenly, I
floored the brakes but could not avoid colliding into
it. My vehicle A was hit by vehicle B too.

When I got down of my vehicle A, I realised
it was a 4-car chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

15 Oct 2019
3:20 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	937B
Vehicle Details	
Vehicle No.:	SJR1397K
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	K24W72461173
Chassis No.:	JHMRC1890KC202533
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,072.00
Original Registration Date:	24 May 2019
First Registration Date:	24 May 2019
Transfer Count:	0
Actual ARF Paid:	\$35,501.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 May 2029
PARF Rebate Amount:	\$26,625.00
Intended COE Rebate Details	
COE Expiry Date:	23 May 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,010.00
COE Rebate Amount:	\$46,087.00
Total Rebate Amount:	\$72,712.00

The information contained herein is correct as at 17 Oct 2019

OK



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

A

Customer: CU0066184 / CHINA TAIPING
Chassis No: JHMRC1890KC202533
License No: SJR1397K
Mileage: 1406
Engine No: K24W72461173

Document No: SVO19067261
Printed By: SHNG
Order Date: 17. October 2019
Order Time: 12:04:17 PM
Service Advisor: NG SIN HAI

71122-T6A-N01	UPPER MOLDING,FR.GRILLE	1	121.60	5	115.52	8.09	123.61
71123-T6A-N01	LOWER MOLDING,FR.GRILLE	1	291.90	5	277.30	19.41	296.71
75700-SZW-000	EMBLEM MARK	1	29.50	5	28.02	1.96	29.98
90301-ST0-003	NUTPUSH 3MM	1	2.10	5	1.99	0.14	2.13
71107-T6A-N01	MOLDING,FR.BUMPER LOWER	1	101.40	5	96.33	6.74	103.07
77930-T6A-J21	SENSOR ASSYFR.CRASH	2	131.70	5	250.23	17.52	267.75
72841-SH3-315	OILSHEET	3	40.70	5	115.99	8.12	124.11
	SUM PARTS:				22,764.76	1,593.47	24,358.23
BOSUN	0701	1	50.00		50.00	3.50	53.50
	SUNDRIES						
BA02R	0669	1	180.00		180.00	12.60	192.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	SEALANT FOR REAR END PANEL						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	SEALANT FOR TAILGATE						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	SEALANT FOR REAR FLOOR PANEL						
BML02I	1610	1	180.00		180.00	12.60	192.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BMF00D	1757	1	560.00		560.00	39.20	599.20
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)						
BMI02D	1757	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)						
BKTG02R	0669	1	560.00		560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BG02D	1757	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BODAMKIT	1757	1	80.00		80.00	5.60	85.60
	WINDSCREEN DAM KIT.						
BMI03D	1757	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKRP02M	0669	1	4,480.00		4,480.00	313.60	4,793.60
	CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.						
BP06R	1610	1	2,700.00		2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION						
BKOT00R	1610	1	450.00		450.00	31.50	481.50
	REMOVE & RENEW RR FLOOR INSULATOR.(N)						
BKBU01R	1757	1	560.00		560.00	39.20	599.20
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA						

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

A

Customer: CU0066184 / CHINA TAIPING
 Chassis No: JHMRC1890KC202533
 License No: SJR1397K
 Mileage: 1406
 Engine No: K24W72461173

Document No: SVO19067261
 Printed By: SHNG
 Order Date: 17. October 2019
 Order Time: 12:04:17 PM
 Service Advisor: NG SIN HAI

BP00R	1757	1	450.00	450.00	31.50	481.50
	APPLY BODY UNDERSIDE COATING (N).					
BC03R	1757	1	560.00	560.00	39.20	599.20
	TO PERFORM FR MULTI SENSING CAMERA AIMING AND RESET SYSTEM.					
BC012R	1757	1	560.00	560.00	39.20	599.20
	RESET VEHICLE SMART ENTRY SYSTEM					
BML01I	1757	1	180.00	180.00	12.60	192.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)					
BA00R	0669	1	450.00	450.00	31.50	481.50
	REMOVE & TRANSFER FR. CAMERA.(N)					
BMI00D	0669	1	1,680.00	1,680.00	117.60	1,797.60
	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL AUDIO WIRING HARNESS & ETC.(N)					
BMS00R	0669	1	1,120.00	1,120.00	78.40	1,198.40
	RENEW PASSENGER AIRBAG ASSY ECU & RESET SRS SYSTEM.(N)					
BMS02R	1757	1	560.00	560.00	39.20	599.20
	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN RESET SYSTEM.					
BMA01D	1757	1	380.00	380.00	26.60	406.60
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS, VACUUM & RECHARGE A/C GAS.(N)					
BMC01D	1757	1	330.00	330.00	23.10	353.10
	REMOVE & INSTALL RADIATOR WITH FITTINGS, PRESSURE TEST COOLING SYSTEM.(N)					
BA01R	1757	1	150.00	150.00	10.50	160.50
	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)					
BKBH11M	0669	1	2,800.00	2,800.00	196.00	2,996.00
	CUT OFF & RENEW BULKHEAD FR L WHEELHOUSE. STRAIGHTEN ALIGN FR L FRAME & RENEW DAMAGE PARTS.					
BP08R	1610	1	3,600.00	3,600.00	252.00	3,852.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(8P)					
BO-TOW		1	120.00	120.00	8.40	128.40
	TOWING SERVICES (MBBS)					

SUM LABOUR: 24,660.00 1,726.20 26,386.20

TOTAL SGD 47,424.76 3,319.67 50,744.43

Total Payable (SGD) 50,744.43

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0066184 / CHINA TAIPING
Chassis No: JHMRC1890KC202533
License No: SJR1397K
Mileage: 1406
Engine No: K24W72461173

Document No: SVO19067261
Printed By: SHNG
Order Date: 17. October 2019
Order Time: 12:04:17 PM
Service Advisor: NG SIN HAI

A

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:BEH SWAN GIN						
	OWNER INSURER:TOKIO						
	ACC DATE:15/10/2019						
	SURVEYED BY:TAUFIKH						
	DATE:17/10/2019						
	REF NO:						
	TP INSURER:CHINA						
	TP VEH:SVJ3156E						
	SUPPLEMENTARY PART						
34150-T6A-J51	LIGHT ASSY,R.LID	1	386.20	5	366.89	25.68	392.57
34155-T6A-J51	LIGHT ASSY,L.LID	1	378.60	5	359.67	25.18	384.85
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	5	1,017.26	71.21	1,088.47
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40	5	111.53	7.81	119.34
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.50	5	166.72	11.67	178.39
91513-T6A-003	CLIPTAILGATE SPOILER	6	2.50	5	14.25	1.00	15.25
75701-T6A-000	EMBLEMH	1	26.30	5	24.98	1.75	26.73
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER	1	557.20	5	529.34	37.05	566.39
71507-T6A-003ZG	FACELRR.BUMPER GARNISH	1	76.80	5	72.96	5.11	78.07
71517-T6A-901ZF	SPOILER ASSY,L.RR.	1	98.70	5	93.76	6.56	100.32
71593-T6A-003	SPACERRR.BUMPER SIDE	1	19.10	5	18.14	1.27	19.41
71596-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	5	18.14	1.27	19.41
91505-TM8-003	CLIP,BUMPER	7	2.30	5	15.29	1.07	16.36
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	460.80	5	437.76	30.64	468.40
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	337.90	5	321.00	22.47	343.47
84865-T6A-N72ZB	LINING COMP,L.RR.SIDE	1	705.40	5	670.13	46.91	717.04
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	5	34.20	2.39	36.59
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	5	16.05	1.12	17.17
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	5	16.05	1.12	17.17
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	5	14.82	1.04	15.86
73225-TM8-000	RUBBER A/WINDSHIELD DAM	1	3.70	5	3.51	0.25	3.76
73226-SZW-000	DAMPERSTD 5X5	2	8.50	5	16.15	1.13	17.28
76711-T6A-003	CAPPVOT	1	4.80	5	4.56	0.32	4.88
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
33150-T6A-Q31	LIGHT ASSY,L.HEAD	1	1,479.70	5	1,405.71	98.40	1,504.11
33100-T6A-Q31	LIGHT ASSY,R.HEAD	1	1,479.70	5	1,405.71	98.40	1,504.11
04711-T6A-N13ZZ	FACE ASSY,FR.BUMPER	1	686.20	5	651.89	45.63	697.52
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.90	5	33.15	2.32	35.47
71198-T6A-N01	SPACER L,FR BPR SLLE	1	11.80	5	11.21	0.78	11.99
71108-T6A-N00	LOWER PLATE,FR.BUMPER	1	147.10	5	139.74	9.78	149.52
71105-T6A-N00	LOWER GRILLE,FR.BUMPER	1	62.10	5	58.99	4.13	63.12
60260-T6A-300ZZ	FENDER COMPL.FR.	1	548.60	5	521.17	36.48	557.65
60210-T6A-300ZZ	FENDER COMPR.FR.	1	548.60	5	521.17	36.48	557.65
91501-TR0-003	CLIP,INNER FENDER	6	2.80	5	15.96	1.12	17.08
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER	1	879.80	5	835.81	58.51	894.32
77820-T6A-N80	MODULE ASSYPASSENGER	1	2,785.60	5	2,646.32	185.24	2,831.56
04814-T6A-M00ZA	TONGUE SETR.FR.SEATBELT OUTER	1	408.70	5	388.26	27.18	415.44
60400-T6A-310ZZ	BULKHEAD COMPR.	1	460.80	5	437.76	30.64	468.40
80111-T6A-003	CONDENSER COMP	1	681.90	5	647.80	45.35	693.15

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0066184 / CHINA TAIPING
 Chassis No: JHMRC1890KC202533
 License No: SJR1397K
 Mileage: 1406
 Engine No: K24W72461173

Document No: SVO19067261
 Printed By: SHNG
 Order Date: 17. October 2019
 Order Time: 12:04:17 PM
 Service Advisor: NG SIN HAI

19010-5X6-J02	RADIATOR COMP	1	1,347.30	5	1,279.93	89.60	1,369.53
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	5	132.24	9.26	141.50
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
75722-T6A-901	EMBLEM,RR. <i>del</i>	1	31.00	5	29.45	2.06	31.51
90682-SEA-003	CLIP ABUMPER <i>del</i>	4	2.60	5	9.88	0.69	10.57
91501-S04-003	CLIPINNER FENDER <i>del</i>	12	3.90	5	44.46	3.11	47.57
71112-T6A-901ZF	SPOILER ASSY,R.FR. <i>del</i>	1	79.00	5	75.05	5.25	80.30
71130-T6A-310ZZ	BEAM COMP,FR BUMPER <i>del</i>	1	291.80	5	277.21	19.40	296.61
71140-T6A-003	BEAMR.FR BUMPER UPPER <i>del</i>	1	34.90	5	33.15	2.32	35.47
71151-T6A-N41	BASE,MID GRILLE P <i>del</i>	1	222.90	5	211.75	14.82	226.57
71152-T6A-N01	MOLDING,R.FR.MID GRILLE BPR <i>del</i>	1	60.80	5	57.76	4.04	61.80
71153-T6A-N01	MOLDING A,FR.MID GRILLE BPR <i>del</i>	1	178.40	5	169.48	11.86	181.34
71154-T6A-N01	MOLDING B,FR.MID GRILLE BPR <i>del</i>	1	162.20	5	154.09	10.79	164.88
71155-T6A-N01	MOLDING C,FR.MID GRILLE BPR <i>del</i>	1	60.80	5	57.76	4.04	61.80
71157-T6A-N01	MOLDING L,FR.MID GRILLE BPR <i>del</i>	1	60.80	5	57.76	4.04	61.80
71158-T6A-N01	MOLDING D,FR.MID GRILLE BPR <i>del</i>	1	152.00	5	144.40	10.11	154.51
71171-T6A-N00	GARNISH,R.FR.FOG <i>del</i>	1	70.90	5	67.35	4.71	72.06
71176-T6A-N00	GARNISH,L.FR.FOG <i>del</i>	1	70.90	5	67.35	4.71	72.06
91578-T0A-003	CLIPFR.GRILLE <i>del</i>	4	2.30	5	8.74	0.61	9.35
71159-T6A-N01	MOLDING C,L.FR.MID GR BPR <i>del</i>	1	60.80	5	57.76	4.04	61.80
32131-T6A-N00	SUB CORD,RR BUMPE <i>del</i>	1	54.70	5	51.96	3.64	55.60
74940-TR0-003	BUZZER ASSYSMART <i>del</i>	1	60.10	5	57.09	4.00	61.09
60100-T6A-000ZZ	HOOD COMP <i>del</i>	1	671.40	5	637.83	44.65	682.48
60120-T6A-000ZZ	HINGE COMPR.HOOD <i>del</i>	1	47.40	5	45.03	3.15	48.18
60170-T6A-000ZZ	HINGE COMPL.HOOD <i>del</i>	1	47.40	5	45.03	3.15	48.18
74141-T6C-010	INSULATOR,HOOD <i>del</i>	1	116.00	5	110.20	7.71	117.91
80050-SP0-000	LABEL AIR CONDITIONER CAUTION <i>del</i>	1	1.80	5	1.71	0.12	1.83
19043-PNB-A00	LABELCOOLANT INFORMATION <i>del</i>	1	5.00	5	4.75	0.33	5.08
39680-T0A-R12A6	SENSOR ASSY,PARKING BACK SENSOR <i>del</i>	2	267.80	5	508.82	35.62	544.44
39680-T0A-R42B2	SENSOR ASSY,PARKING BACK SENSOR <i>del</i>	2	267.80	5	508.82	35.62	544.44
39681-T6A-N01	RETAINER,PARKING <i>del</i>	1	41.80	5	39.71	2.78	42.49
39681-T6A-N11	RETAINER,PARKING BACK SENSOR <i>del</i>	1	41.80	5	39.71	2.78	42.49
39683-T6A-N11ZF	RETAINER,PARKING <i>del</i>	1	41.80	5	39.71	2.78	42.49
39684-T6A-N01ZF	RETAINER,PARKING D <i>del</i>	1	41.80	5	39.71	2.78	42.49
39680-T0A-R02B5	SENSOR ASSY,PARKING BACK SENSOR <i>del</i>	1	267.80	5	254.41	17.81	272.22
60433-T6D-H00ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE <i>del</i>	1	33.60	5	31.92	2.23	34.15
60483-T6D-H00ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE <i>del</i>	1	33.60	5	31.92	2.23	34.15
18121-SB0-Y10	COVER COMPPRIMARY CONVERTER <i>del</i>	1	74.60	5	70.87	4.96	75.83
17230-5X6-J00	CHAMBER ASSYRESONATOR <i>del</i>	1	109.70	5	104.21	7.29	111.50
17253-5X6-J00	TUBE ASSY BAIR INTAKE <i>del</i>	1	66.00	5	62.70	4.39	67.09
71124-T6A-N00	STAY,R.FR.GRILLE <i>del</i>	1	9.10	5	8.64	0.60	9.24
71129-T6A-N00	STAY,L.FR.GRILLE <i>del</i>	1	8.90	5	8.45	0.59	9.04
38611-5A4-H02	FAN COMPCOOLING <i>del</i>	1	54.20	5	51.49	3.60	55.09
38615-5X6-J01	SHROUD COMP <i>del</i>	1	83.80	5	79.61	5.57	85.18
38616-5X6-J02	MOTOR,COOLING FAN <i>del</i>	1	322.60	5	306.47	21.45	327.92
80311-T6A-003	HOSE COMPSUCTION <i>del</i>	1	184.30	5	175.08	12.26	187.34
80315-T6A-003	HOSE COMPDISCHARGE <i>del</i>	1	160.20	5	152.19	10.65	162.84
80341-T6A-003	PIPE COMPRECEIVER <i>del</i>	1	176.70	5	167.86	11.75	179.61
71193-T6A-N01	SPACER,R.FR.BPR SLLE <i>del</i>	1	11.80	5	11.21	0.78	11.99
77960-T6A-J12	UNIT ASSY,SRS <i>del</i>	1	968.00	5	919.60	64.37	983.97
71121-T6A-N01	BASE,FR.GRILLE BUMPER <i>del</i>	1	156.10	5	148.29	10.38	158.67



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SJR1397K

Chassis No : JHMRC1890KC202533

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : BEH SWAN GIN

Ins Policy No. :

Date of Accident : 15/10/2019

Document No. : SQT19004517

Date : 15. Oct 2019

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72461173

Date | Time : 15. Oct 2019 3:32:29 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES ✓	1	100.00 50		100.00	7.00	107.00 ✓
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N) ✓	1	180.00 ✓		180.00	12.60	192.60 ✓
BOJSE	SEALANT FOR REAR END PANEL ✓	1	80.00 ✓		80.00	5.60	85.60 ✓
BOJSE	SEALANT FOR TAILGATE ✓	1	80.00 ✓		80.00	5.60	85.60 ✓
BOJSE	SEALANT FOR REAR FLOOR PANEL ✓	1	80.00 ✓		80.00	5.60	85.60 ✓
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER ✓	1	180.00 ✓		180.00	12.60	192.60 ✓
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N) ✓	1	560.00 ✓		560.00	39.20	599.20 ✓
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK ✓	1	560.00 ✓		560.00	39.20	599.20 ✓
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST ✓	1	560.00 ✓		560.00	39.20	599.20 ✓
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N) ✓	1	560.00 ✓		560.00	39.20	599.20 ✓
BODAMKIT	WINDSCREEN DAM KIT. ✓	1	80.00 ✓		80.00	5.60	85.60 ✓
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS ✓	1	560.00 ✓		560.00	39.20	599.20 ✓
BKRP02M	CUT OFF & RENEW RR PANEL. ✓	1	5000.00 2800 Repair 4480 Repair		5000.00	350.00	5350.00 ✓
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) ✓	1	3000.00 2700		3000.00	210.00	3210.00 ✓
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N) ✓	1	450.00 ✓		450.00	31.50	481.50 ✓
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA ✓	1	560.00 ✓		560.00	39.20	599.20 ✓
BP00R	APPLY BODY UNDERSIDE COATING (N). ✓	1	450.00 ✓		450.00	31.50	481.50 ✓

Printed on 15/10/2019 7:22:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SJR1397K
Chassis No : JHMRC1890KC202533
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : BEH SWAN GIN
Ins Policy No. :
Date of Accident : 15/10/2019

Document No. : SQT19004517 **Page** 2
Date : 15. Oct 2019
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : K24W72461173
Date | Time : 15. Oct 2019 3:32:29 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC03R	TO PERFORM FR MULTI SENSING CAMERA AIMING	1	560.00	✓	560.00	39.20	599.20 ✓
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	✓	560.00	39.20	599.20 ✓
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	✓	180.00	12.60	192.60 ✓
BA00R	REMOVE & TRANSFER FR. CAMERA (N)	1	450.00	✓	450.00	31.50	481.50 ✓
BMI00D	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	1	1800.00	1680.	1800.00	126.00	1926.00 ✓
BMS00R	RENEW PASSENGER AIRBAG ASSY ECU &	1	1200.00	1000/120	1200.00	84.00	1284.00 ✓
BMS02R	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	1	1000.00	560.	1000.00	70.00	1070.00 ✓
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	380.00	? ne ✓	380.00	26.60	406.60 ✓
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	330.00	? ne ✓	330.00	23.10	353.10 ✓
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	150.00	✓	150.00	10.50	160.50 ✓
BKBH11M	CUT OFF & RENEW BULKHEAD FR L WHEELHOUSE	1	4000.00	2800.	4000.00	280.00	4280.00 ✓
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P)	1	4000.00	3600.	4000.00	280.00	4280.00 ✓
BO-TOW	TOWING SERVICES (MBBS)	1	120.00	✓	120.00	8.40	128.40 ✓
Sum Labor					27770.00	1,943.90	29,713.90
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00	X ne	320.00	22.40	342.40 X
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00	X ne	45.00	3.15	48.15 X
33500-T6A-003	TAILLIGHT ASSYR.	1	838.10	Run 5	796.19	55.73	851.92 X
33550-T6A-003	TAILLIGHT ASSYL	1	838.10	Run 5	796.19	55.73	851.92 X
34150-T6A-003	LIGHT ASSYR.LID	1	366.20	ne 5	366.89	25.68	392.57 ✓
34155-T6A-003	LIGHT ASSYL.LID	1	366.20	ne 5	366.89	25.68	392.57 ✓
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	230.40	X ne 5	218.88	15.32	234.20 X
68100-T6A-Q10ZZ	TAILGATE COMP	1	1070.80	bt 5	1017.26	71.21	1088.47 ✓
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40	twi 5	111.53	7.81	119.34 ✓
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.50	cut 5	166.72	11.67	178.39 ✓
74900-T6A-003ZB	GARNISH ASSYTAILGATE SPOILER	1	614.30	X ne 5	583.58	40.85	624.43 X
91513-T6A-003	CLIPTAILGATE SPOILER	6	2.50	ne 5	14.25	1.00	15.25 ✓
75701-T6A-000	EMBLEMH	1	26.30	ne 5	24.98	1.75	26.73 ✓

Printed on 15/10/2019 7:22:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SJR1397K

Chassis No : JHMRC1890KC202533

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : BEH SWAN GIN

Ins Policy No. :

Date of Accident : 15/10/2019

Document No. : SQT19004517

Date : 15. Oct 2019

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72461173

Date | Time : 15. Oct 2019 3:32:29 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
04715-T6A-900ZZ	FACERR.BUMPER ✓	1	568.30	5	539.88	37.79	577.67 ✓
33505-SLJ-013	REFLECTOR ASSYR.RR. ✓	1	45.40	5	43.13	3.02	46.15 ✓
33555-SLJ-013	REFLECTOR ASSYL.RR. ✓	1	45.40	5	43.13	3.02	46.15 ✓
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH ✓	1	76.80	5	72.96	5.11	78.07 ✓
71507-T6A-003ZB	FACEL.RR.BUMPER GARNISH ✓	1	76.80	5	72.96	5.11	78.07 ✓
71512-T6A-921ZB	SPOILER ASSYR.RR.SIDE ✓	1	114.10	5	108.39	7.59	115.98 ✓
71517-T6A-921ZB	SPOILER ASSYL.RR.SIDE ✓	1	114.10	5	108.39	7.59	115.98 ✓
71593-T6A-003	SPACERR.RR.BUMPER SIDE ✓	1	19.10	5	18.14	1.27	19.41 ✓
71598-T6A-003	SPACERL.RR.BUMPER SIDE ✓	1	19.10	5	18.14	1.27	19.41 ✓
91505-TM8-003	CLIP.BUMPER ✓	7	2.30	5	15.29	1.07	16.36 ✓
66100-T6A-300ZZ	PANEL COMPRR. ✓	1	460.80	5	437.76	30.64	468.40 ✓
04656-T6A-300ZZ	PAN SET3RD SEAT ✓	1	337.90	5	321.00	22.47	343.47 ✓
72841-SH3-315	OILSHEET ✓	3	40.70	5	115.99	8.12	124.11 ✓
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER - photo ✓	1	208.30	5	195.98	13.72	209.70 ✓
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL ✓	1	10.70	5	10.16	0.71	10.87 ✓
84615-T6A-N71ZD	LINING COMPR.RR.SIDE ✓	1	763.60	5	725.42	50.78	776.20 ✓
84640-T6A-003ZA	LINING ASSYRR.PANEL - photo ✓	1	103.60	5	98.42	6.89	105.31 ✓
84643-T6A-Q01ZA	COMP LIDTOOL ✓	1	61.40	5	58.33	4.08	62.41 ✓
84665-T6A-N71ZD	LINING COMPL.RR.SIDE - photo ✓	1	763.60	5	725.42	50.78	776.20 ✓
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE ✓	2	18.00	5	34.20	2.39	36.59 ✓
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER ✓	1	16.90	5	16.05	1.12	17.17 ✓
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER ✓	1	16.90	5	16.05	1.12	17.17 ✓
73221-SR4-000	SPACERRR.W/SHIELD ✓	4	3.90	5	14.82	1.04	15.86 ✓
73225-TM8-000	RUBBER A WINDSHIELD DAM ✓	1	3.70	5	3.51	0.25	3.76 ✓
73226-SZW-000	DAMPERSTD 5X5 ✓	2	8.50	5	16.15	1.13	17.28 ✓
76711-T6A-003	CAPPVOT ✓	1	4.80	5	4.56	0.32	4.88 ✓
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓	2	60.00		120.00	8.40	128.40 ✓
33150-T6A-Q11	HEADLIGHT ASSY,L WITH LED ✓	1	2281.90	5	2167.80	151.75	2319.55 ✓
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED ✓	1	2281.90	5	2167.80	151.75	2319.55 ✓

Printed on 15/10/2019 7:22:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$33.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SJR1397K

Chassis No : JHMRC1890KC202533

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : BEH SWAN GIN

Ins Policy No. :

Date of Accident : 15/10/2019

Document No. : SQT19004517

Date : 15. Oct 2019

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72461173

Date | Time : 15. Oct 2019 3:32:29 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
33950-TY0-003	LIGHT ASSY, L FR.FOG	1	267.10	5	253.74	17.76	271.50 X
33955-T6A-003	BRACKETL.FR.FOGLIGHT	1	63.20	5	60.04	4.20	64.24 X
04711-T6A-900ZZ	FACE.FR.BUMPER	1	700.00	5	665.00	46.55	711.55 /
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.90	5	33.15	2.32	35.47 /
71196-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.80	5	11.21	0.78	11.99 /
71117-T6A-921ZB	SPOILER ASSYL.FR.SIDE	1	94.40	5	89.68	6.28	95.96 X
71108-T6A-P00	LOWER PLATEFR.BUMPER	1	147.10	5	139.74	9.78	149.52 /
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	67.10	5	63.74	4.46	68.20 /
71109-T6A-921	GARNISHL.FR.BUMPER	1	46.10	5	43.79	3.07	46.86 X
60713-T6A-300ZZ	MEMBERL.FR.WHEELHOUSE UPPER	1	109.70	5	104.21	7.29	111.50 X
60260-T6A-300ZZ	FENDER COMPL.FR.	1	548.60	5	521.17	36.48	557.65 /
60210-T6A-300ZZ	FENDER COMPR.FR.	1	548.60	5	521.17	36.48	557.65 /
74155-T6A-000	ENCLOSUREL.FR.FENDER	1	26.30	5	24.98	1.75	26.73 X
74206-T6A-000	GARNISHL.FR.FENDER	1	33.10	5	31.44	2.20	33.64 X
74150-T6A-000	FENDER ASSYL.FR.INNER	1	120.70	5	114.66	8.03	122.69 X
91501-TR0-003	CLIP,INNER FENDER	6	2.80	5	15.96	1.12	17.08 /
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER	1	879.80	5	835.81	58.51	894.32 /
77820-T6A-N80	MODULE ASSYPASSENGER	1	2785.60	5	2646.32	185.24	2831.56 /
04814-T6A-M00ZA	TONGUE SETR.FR.SEATBELT OUTER	1	408.70	5	388.26	27.18	415.44 /
60400-T6A-310ZZ	BULKHEAD COMPR.	1	460.80	5	437.76	30.64	468.40 /
80111-T6A-003	CONDENSER COMP	1	681.90	5	647.80	45.35	693.15 /
19010-5X6-J02	RADIATOR COMP	1	1347.30	5	1279.93	89.60	1369.53 /
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	5	132.24	9.26	141.50 /
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00	5	45.00	3.15	48.15 /
Sum Item					22224.99	1,555.76	23,780.75

Survey By _____

Date & Time _____

Excess _____

Total Amount 49,994.99 3,499.66 53,494.65

Total (Inclusive of GST) 53,494.65

Printed on 15/10/2019 7:22:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

92118.73



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SJR1397K
Chassis No : JHMRC1890KC202533
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : BEH SWAN GIN
Ins Policy No. :
Date of Accident : 15/10/2019

Document No. : SQT19004517
Date : 15. Oct 2019
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : K24W72461173
Date | Time : 15. Oct 2019 3:32:29 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 5

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
Status							
Signature							

Tanpin 97495749
wp
17/10/19 @ 11:50 am
Resurvey before paint
sur@lkkauto.com
(20)-24 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 15/10/2019 7:22:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0066184 / BEH SWAN GIN
 Chassis No: JHMRC1890KC202533
 License No: SJR1397K
 Mileage: 1406
 Engine No: K24W72461173

Document No: SVO19067261
 Printed By: ARINI
 Order Date: 17. October 2019
 Order Time: 12:04:17 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	SUPPLEMENTARY PART						
75722-T6A-901	EMBLEM,RR. <i>new</i>	1	31.00	5	29.45	2.06	31.51
90682-SEA-003	CLIP ABUMPER <i>new</i>	4	2.60	5	9.88	0.69	10.57
91501-S04-003	CLIPINNER FENDER <i>new</i>	12	3.90	5	44.46	3.11	47.57
71112-T6A-901ZF	SPOILER ASSY,R.FR. <i>de</i>	1	79.00	5	75.05	5.25	80.30
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER <i>bt</i>	1	291.80	5	277.21	19.40	296.61
71140-T6A-003	BEAMR.FR.BUMPER UPPER <i>bt</i>	1	34.90	5	33.15	2.32	35.47
71151-T6A-N41	BASE,MID GRILLE P <i>new</i>	1	222.90	5	211.75	14.82	226.57
71152-T6A-N01	MOLDING,R.FR.MID GRILLE BPR <i>new</i>	1	60.80	5	57.76	4.04	61.80
71153-T6A-N01	MOLDING A,FR.MID GRILLE BPR <i>new</i>	1	178.40	5	169.48	11.86	181.34
71154-T6A-N01	MOLDING B,FR.MID GRILLE BPR <i>new</i>	1	162.20	5	154.09	10.79	164.88
71155-T6A-N01	MOLDING C,FR.MID GRILLE BPR <i>new</i>	1	60.80	5	57.76	4.04	61.80
71157-T6A-N01	MOLDING L,FR.MID GRILLE BPR <i>new</i>	1	60.80	5	57.76	4.04	61.80
71158-T6A-N01	MOLDING D,FR.MID GRILLE BPR <i>new</i>	1	152.00	5	144.40	10.11	154.51
71171-T6A-N00	GARNISH,R.FR.FOG <i>de</i>	1	70.90	5	67.35	4.71	72.06
71176-T6A-N00	GARNISH,L.FR.FOG <i>de</i>	1	70.90	5	67.35	4.71	72.06
91578-T0A-003	CLIPFR.GRILLE <i>new</i>	4	2.30	5	8.74	0.61	9.35
71159-T6A-N01	MOLDING C,L.FR.MID GR BPR <i>new</i>	1	60.80	5	57.76	4.04	61.80
32131-T6A-N00	SUB CORD,RR BUMPE <i>dis</i>	1	54.70	5	51.98	3.64	55.60
74940-TR0-003	BUZZER ASSYSMART <i>new</i>	1	60.10	5	57.09	4.00	61.09
60100-T6A-000ZZ	HOOD COMP <i>bt</i>	1	671.40	5	637.83	44.65	682.48
60120-T6A-000ZZ	HINGE COMPR.HOOD <i>bt</i>	1	47.40	5	45.03	3.15	48.18
60170-T6A-000ZZ	HINGE COMPL.HOOD <i>bt</i>	1	47.40	5	45.03	3.15	48.18
74141-T6C-010	INSULATOR,HOOD <i>dis</i>	1	116.00	5	110.20	7.71	117.91
80050-SP0-000	LABEL AIR CONDITIONER CAUTION <i>new</i>	1	1.80	5	1.71	0.12	1.83
19043-PNB-A00	LABELCOOLANT INFORMATION <i>new</i>	1	5.00	5	4.75	0.33	5.08
39680-T0A-R12A6	SENSOR ASSY,PARKING BACK SENSOR <i>new</i>	2	267.80	5	508.82	35.62	544.44
39680-T0A-R42B2	SENSOR ASSY,PARKING BACK SENSOR <i>new</i>	2	267.80	5	508.82	35.62	544.44
39681-T6A-N01	RETAINER,PARKING <i>new</i>	1	41.80	5	39.71	2.78	42.49
39681-T6A-N11	RETAINER,PARKING BACK SENSOR <i>new</i>	1	41.80	5	39.71	2.78	42.49
39683-T6A-N11ZF	RETAINER,PARKING <i>new</i>	1	41.80	5	39.71	2.78	42.49
39684-T6A-N01ZF	RETAINER,PARKING D <i>new</i>	1	41.80	5	39.71	2.78	42.49
39680-T0A-R02B5	SENSOR ASSY,PARKING BACK SENSOR <i>new</i>	1	267.80	5	254.41	17.81	272.22
60433-T6D-H00ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE <i>bt</i>	1	33.60	5	31.92	2.23	34.15
60483-T6D-H00ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE <i>bt</i>	1	33.60	5	31.92	2.23	34.15
18121-5B0-Y10	COVER COMPPRIMARY CONVERTER <i>dis</i>	1	74.60	5	70.87	4.96	75.83
17230-5X6-J00	CHAMBER ASSYRESONATOR <i>de</i>	1	109.70	5	104.21	7.29	111.50
17253-5X6-J00	TUBE ASSY BAIR INTAKE <i>de</i>	1	66.00	5	62.70	4.39	67.09
71124-T6A-N00	STAY,R.FR.GRILLE <i>dis</i>	1	9.10	5	8.64	0.60	9.24
71129-T6A-N00	STAY,L.FR.GRILLE <i>dis</i>	1	8.90	5	8.45	0.59	9.04
38611-5A4-H02	FAN COMPCOOLING <i>new</i>	1	54.20	5	51.49	3.60	55.09
38615-5X6-J01	SHROUD COMP <i>new</i>	1	83.80	5	79.61	5.57	85.18
38616-5X6-J02	MOTOR,COOLING FAN <i>dis</i>	1	322.60	5	306.47	21.45	327.92
80311-T6A-003	HOSE COMPSUCTION <i>bt</i>	1	184.30	5	175.08	12.26	187.34
80315-T6A-003	HOSE COMPDISCHARGE <i>bt</i>	1	160.20	5	152.19	10.65	162.84
80341-T6A-003	PIPE COMPRECEIVER <i>bt</i>	1	176.70	5	167.86	11.75	179.61
71193-T6A-N01	SPACER,R.FR.BPR SLLE <i>new</i>	1	11.80	5	11.21	0.78	11.99
77960-T6A-J12	UNIT ASSY,SRS <i>dis</i>	1	968.00	5	919.60	64.37	983.97
71121-T6A-N01	BASE,FR.GRILLE BUMPER <i>new</i>	1	156.10	5	148.29	10.38	158.67



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0066184 / BEH SWAN GIN
Chassis No: JHMRC1890KC202533
License No: SJR1397K
Mileage: 1408
Engine No: K24W72461173

Document No: SVO19067261
Printed By: ARINI
Order Date: 17. October 2019
Order Time: 12:04:17 PM
Service Advisor: NG SIN HAI

71122-T6A-N01	UPPER MOLDING,FR.GRILLE <i>car</i>	1	121.60	5	115.52	8.09	123.61	✓
71123-T6A-N01	LOWER MOLDING,FR.GRILLE <i>car</i>	1	291.90	5	277.30	19.41	296.71	✓
75700-SZW-000	EMBLEM MARK <i>rel</i>	1	29.50	5	28.02	1.96	29.98	✓
90301-ST0-003	NUTPUSH 3MM <i>rel</i>	1	2.10	5	1.99	0.14	2.13	✓
71107-T6A-N01	MOLDING,FR.BUMPER LOWER <i>ds</i>	1	101.40	5	96.33	6.74	103.07	✓
77930-T6A-J21	SENSOR ASSYFR.CRASH <i>act</i>	2	131.70	5	250.23	17.52	267.75	✓
SUM PARTS:					7,007.79	490.48	7,498.27	
72841-SH3-315 O:1 sheet / acc		3	TOTAL SGD		7,007.79	490.48	7,498.27	
			40-70	3	115-99	8-12	124-11	✓
			Total Payable (SGD)				7,498.27	

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Oct 2019		16 Oct 2019 16:44 Edit Adj Rpt	\$547,424.76 Edit Estimates	\$547,424.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	BEH SWAN GIN, ID: S26059378								
Vehicle Reg. No.:	SJR1397K	Date of Loss:	15/10/2019 12:00 - :59 [4 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204879C02	Policy/Cover Note No.:	DMHCSN19212819000						
Vehicle Reg. No. (Insured):	SJV3156E	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR1397K (SNM19D204879C02)
 [SJV3156E]
 TP
 BEH SWAN GIN
 Oct 15 2019 12:00PM
 [-]
 Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	15/10/19 19:23	Accident Statement		 Load HTML	
Photos/Images				3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	15/10/19 19:23	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
2	15/10/19 19:23	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/11/19 10:09	General View		 Load JPG	☒
2	05/11/19 10:09	General View		 Load JPG	☒
3	05/11/19 10:09	General View		 Load JPG	☒
4	05/11/19 10:09	General View		 Load JPG	☒
5	05/11/19 10:09	General View		 Load JPG	☒
6	05/11/19 10:09	General View		 Load JPG	☒
7	05/11/19 10:09	General View		 Load JPG	☒
8	05/11/19 10:09	General View		 Load JPG	☒
9	05/11/19 10:09	General View		 Load JPG	☒
10	05/11/19 10:09	General View		 Load JPG	☒
11	05/11/19 10:09	General View		 Load JPG	☒
12	05/11/19 10:09	General View		 Load JPG	☒
13	05/11/19 10:09	General View		 Load JPG	☒
14	05/11/19 10:09	General View		 Load JPG	☒
15	05/11/19 10:09	General View		 Load JPG	☒
16	05/11/19 10:09	General View		 Load JPG	☒
17	05/11/19 10:09	General View		 Load JPG	☒
18	05/11/19 10:09	General View		 Load JPG	☒
19	05/11/19 10:09	General View		 Load JPG	☒
20	05/11/19 10:09	General View		 Load JPG	☒
21	05/11/19 10:09	General View		 Load JPG	☒
22	05/11/19 10:09	General View		 Load JPG	☒
23	05/11/19 10:09	General View		 Load JPG	☒
24	05/11/19 10:09	General View		 Load JPG	☒
25	05/11/19 10:09	General View		 Load JPG	☒
26	05/11/19 10:09	General View		 Load JPG	☒
27	05/11/19 10:09	General View		 Load JPG	☒
28	05/11/19 10:09	General View		 Load JPG	☒
29	05/11/19 10:09	General View		 Load JPG	☒
30	05/11/19 10:09	General View		 Load JPG	☒
31	05/11/19 10:09	General View		 Load JPG	☒
32	05/11/19 10:09	General View		 Load JPG	☒
33	05/11/19 10:09	General View		 Load JPG	☒
34	05/11/19 10:09	General View		 Load JPG	☒
35	05/11/19 10:09	General View		 Load JPG	☒
36	05/11/19 10:09	General View		 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
37	05/11/19 10:09	General View	 Load JPG	☒
38	05/11/19 10:09	General View	 Load JPG	☒
39	05/11/19 10:09	General View	 Load JPG	☒
40	05/11/19 10:09	General View	 Load JPG	☒
41	05/11/19 10:09	General View	 Load JPG	☒
42	05/11/19 10:09	General View	 Load JPG	☒
43	05/11/19 10:09	General View	 Load JPG	☒
44	05/11/19 10:09	General View	 Load JPG	☒
45	05/11/19 10:09	General View	 Load JPG	☒
46	05/11/19 10:09	General View	 Load JPG	☒
47	05/11/19 10:09	General View	 Load JPG	☒
48	05/11/19 10:09	General View	 Load JPG	☒
49	05/11/19 10:09	General View	 Load JPG	☒
50	05/11/19 10:09	General View	 Load JPG	☒
51	05/11/19 10:09	General View	 Load JPG	☒
52	05/11/19 10:09	General View	 Load JPG	☒
53	05/11/19 10:09	General View	 Load JPG	☒
54	05/11/19 10:09	General View	 Load JPG	☒
55	05/11/19 10:09	General View	 Load JPG	☒
56	05/11/19 10:09	General View	 Load JPG	☒
57	05/11/19 10:09	General View	 Load JPG	☒
58	05/11/19 10:09	General View	 Load JPG	☒
59	05/11/19 10:09	General View	 Load JPG	☒
60	05/11/19 10:09	General View	 Load JPG	☒
61	05/11/19 10:09	General View	 Load JPG	☒
62	05/11/19 10:09	General View	 Load JPG	☒
63	05/11/19 10:09	General View	 Load JPG	☒
64	05/11/19 10:09	General View	 Load JPG	☒
65	05/11/19 10:09	General View	 Load JPG	☒
66	05/11/19 10:09	General View	 Load JPG	☒
67	05/11/19 10:09	General View	 Load JPG	☒
68	05/11/19 10:09	General View	 Load JPG	☒
69	05/11/19 10:09	General View	 Load JPG	☒
70	05/11/19 10:09	General View	 Load JPG	☒
71	05/11/19 10:09	General View	 Load JPG	☒
72	05/11/19 10:09	General View	 Load JPG	☒
73	05/11/19 10:09	General View	 Load JPG	☒
74	05/11/19 10:09	General View	 Load JPG	☒
75	05/11/19 10:09	General View	 Load JPG	☒
76	05/11/19 10:09	General View	 Load JPG	☒
77	05/11/19 10:09	General View	 Load JPG	☒
78	05/11/19 10:09	General View	 Load JPG	☒
79	05/11/19 10:09	General View	 Load JPG	☒
80	05/11/19 10:09	General View	 Load JPG	☒
81	05/11/19 10:09	General View	 Load JPG	☒
82	05/11/19 10:09	General View	 Load JPG	☒
83	05/11/19 10:09	General View	 Load JPG	☒
84	05/11/19 10:09	General View	 Load JPG	☒
85	05/11/19 10:09	General View	 Load JPG	☒
86	05/11/19 10:09	General View	 Load JPG	☒
87	05/11/19 10:09	General View	 Load JPG	☒
88	05/11/19 10:09	General View	 Load JPG	☒
89	05/11/19 10:09	General View	 Load JPG	☒
90	05/11/19 10:09	General View	 Load JPG	☒
91	05/11/19 10:09	General View	Load JPG	☒
92	05/11/19 10:09	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
93	05/11/19 10:09	General View	 Load JPG	☒
94	05/11/19 10:09	General View	 Load JPG	☒
95	05/11/19 10:09	General View	 Load JPG	☒
96	05/11/19 10:09	General View	 Load JPG	☒
97	05/11/19 10:09	General View	 Load JPG	☒
98	05/11/19 10:09	General View	 Load JPG	☒
99	05/11/19 10:09	General View	 Load JPG	☒
100	05/11/19 10:09	General View	 Load JPG	☒
101	05/11/19 10:09	General View	 Load JPG	☒
102	05/11/19 10:09	General View	 Load JPG	☒
103	05/11/19 10:09	General View	 Load JPG	☒
104	05/11/19 10:09	General View	 Load JPG	☒
105	05/11/19 10:09	General View	 Load JPG	☒
106	05/11/19 10:09	General View	 Load JPG	☒
107	05/11/19 10:09	General View	 Load JPG	☒
108	05/11/19 10:09	General View	 Load JPG	☒
109	05/11/19 10:09	General View	 Load JPG	☒
110	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
111	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
112	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
113	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
114	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
115	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
116	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
117	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
118	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
119	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
120	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
121	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
122	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
123	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
124	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
125	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
126	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
127	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
128	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
129	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
130	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
131	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
132	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
133	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
134	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
135	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
136	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
137	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
138	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
139	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
140	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
141	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
142	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
143	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
144	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
145	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
146	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
147	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
148	05/11/19 10:11	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
149	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
150	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
151	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
152	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
153	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
154	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
155	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
156	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
157	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
158	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
159	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
160	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
161	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
162	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
163	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
164	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
165	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
166	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
167	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
168	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
169	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
170	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
171	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
172	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
173	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
174	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
175	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
176	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
177	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
178	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
179	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
180	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
181	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
182	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
183	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
184	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
185	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
186	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
187	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
188	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
189	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
190	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
191	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
192	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
193	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
194	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
195	05/11/19 10:11	Reinspection Photo	Load JPG	☒
196	05/11/19 10:11	Reinspection Photo	Load JPG	☒
197	05/11/19 10:11	Reinspection Photo	Load JPG	☒
198	05/11/19 10:11	Reinspection Photo	Load JPG	☒
199	05/11/19 10:11	Reinspection Photo	Load JPG	☒
200	05/11/19 10:11	Reinspection Photo	Load JPG	☒
201	05/11/19 10:11	Reinspection Photo	Load JPG	☒
202	05/11/19 10:11	Reinspection Photo	Load JPG	☒
203	05/11/19 10:11	Reinspection Photo	Load JPG	☒
204	05/11/19 10:11	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
205	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
206	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
207	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
208	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
209	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
210	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
211	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
212	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
213	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
214	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
215	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
216	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
217	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
218	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
219	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
220	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
221	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
222	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
223	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
224	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
225	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
226	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
227	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
228	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
229	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
230	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
231	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
232	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
233	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
234	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
235	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
236	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
237	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
238	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
239	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
240	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
241	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
242	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
243	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
244	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
245	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
246	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
247	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
248	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
249	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
250	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
251	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
252	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
253	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
254	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
255	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
256	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
257	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
258	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
259	05/11/19 10:11	Reinspection Photo	 Load JPG	☒
260	05/11/19 10:11	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
261	05/11/19 10:11	Reinspection Photo	1	Load JPG	☒
262	05/11/19 10:11	Reinspection Photo	1	Load JPG	☒
263	05/11/19 10:11	Reinspection Photo	1	Load JPG	☒
264	05/11/19 10:11	Reinspection Photo	1	Load JPG	☒
265	05/11/19 10:11	Reinspection Photo	1	Load JPG	☒
266	05/11/19 10:11	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/10/19 16:45	PRS - SJR1397K	1	Load PDF	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	15/10/19 19:23	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/19 15:36	Supplementary	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	15/10/19 19:23	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	15/10/19 19:23	Accident Photo	1	Load JPG	☒
2	15/10/19 19:23	Accident Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	15/10/19 19:23	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018311/T1YF3E2

Date: 13/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN19212819000
Claimant Vehicle No :	SJR1397K	Insured Vehicle No :	SJV3156E
Date of Loss:	15/10/2019	Nature of Claim: TP	Claim No: SNM19D204879C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR1397K	Engine No:	K24W72461173
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRC1890KC202533
Reg. Date:	24/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,448.77	22,814.76	6,634.01	22.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	27,670.00	24,610.00	3,060.00	11.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	57,118.77	47,424.76	9,694.01	16.97
+ GST 7.00/7.00% (S\$)	3,998.31	3,319.73	678.58	16.97
Nett Amount (S\$)	61,117.08	50,744.49	10,372.59	16.97

INSPECTION

Date of Assignment:	16/10/2019	
Date Inspected:	17/10/2019	Inspected At: 255 Alexandra Road Repairer : Kah Motor Co Sdn Bhd
Estimated Period of Repair:	20.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2019)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR1397K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*VPC 4PCS REAR SENSORS	Not Necessary	320.00 FS	*- FS
3	1		*NUMBER PLATE WITH CASING - L	Not Necessary	45.00 FS	*- FS
4	1		*TAILLIGHT ASSYR	Not Necessary	796.19 FS	*- FS
5	1		*LIGHT ASSYR.LID	Cracked	366.89 FS	*366.89 FS
6	1		*LIGHT ASSYL.LID	Cracked	366.89 FS	*359.67 FS
7	1		*GARNISH ASSYRR.LICENSE	Not Necessary	218.88 FS	*- FS
8	1		*TAILGATE COMP	Bent	1,017.26 FS	*1,017.26 FS
9	1		*WEATHERSTRIPTAILGATE	Twisted	111.53 FS	*111.53 FS
10	1		*MOLDING ASSYRR.LICENSE GARN	Cut	166.72 FS	*166.72 FS
11	1		*GARNISH ASSYTAILGATE SPOILER	Not Necessary	583.58 FS	*- FS
12	1		*CLIPTAILGATE SPOILER (6PCS)	Necessary	14.25 FS	*14.25 FS
13	1		*EMBLEMH	Necessary	24.98 FS	*24.98 FS
14	1		*FACERR.BUMPER	Deformed	539.88 FS	*529.34 FS
15	1		*REFLECTOR ASSYR.RR.	Not Necessary	43.13 FS	*- FS
16	1		*REFLECTOR ASSYL.RR.	Not Necessary	43.13 FS	*- FS
17	1		*FACER.RR.BUMPER GARNISH	Not Necessary	72.96 FS	*- FS
18	1		*FACEL.RR.BUMPER GARNISH	Deformed	72.96 FS	*72.96 FS
19	1		*SPOILER ASSYR.RR.SIDE	Not Necessary	108.39 FS	*- FS
20	1		*SPOILER ASSYL.RR.SIDE	Cut	108.39 FS	*93.76 FS
21	1		*SPACERR.RR.BUMPER SIDE	Necessary	18.14 FS	*18.14 FS
22	1		*SPACERL.RR.BUMPER SIDE	Necessary	18.14 FS	*18.14 FS
23	1		*CLIP, BUMPER (7PCS)	Necessary	15.29 FS	*15.29 FS
24	1		*PANEL COMPRR.	Bent	437.76 FS	*437.76 FS
25	1		*PAN SET3RD SEAT	Distorted	321.00 FS	*321.00 FS
26	3		*OILSHEET	Not Necessary	115.99 FS	*- FS
27	1		*LINING ASSYTAILGATE LOWER	Not Necessary	195.98 FS	*- FS
28	1		*POCKETTAILGATE LINING PULL	Not Necessary	10.16 FS	*- FS
29	1		*LINING COMPR.RR.SIDE	Not Necessary	725.42 FS	*- FS
30	1		*LINING ASSYRR.PANEL	Not Necessary	98.42 FS	*- FS
31	1		*COMP LIDTOOL	Not Necessary	58.33 FS	*- FS
32	1		*LINING COMPL.RR.SIDE	Deformed	725.42 FS	*670.13 FS
33	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	34.20 FS	*34.20 FS
34	1		*MOLDINGL.RR.WINDSHIELD CORNER	Necessary	16.05 FS	*16.05 FS
35	1		*SPACERRR.W/SHIELD (4PCS)	Necessary	14.82 FS	*14.82 FS
36	1		*RUBBER AWINDSHIELD DAM	Necessary	3.51 FS	*3.51 FS
37	1		*DAMPERSTD 5X5 (2PCS)	Necessary	16.15 FS	*16.15 FS
38	1		*CAPPIVOT	Necessary	4.56 FS	*4.56 FS
39	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
40	1		*HEADLIGHT ASSY,L.WITH LED	Cracked	2,167.80 FS	*1,405.71 FS
41	1		*HEADLIGHT ASSYR.WITH LED	Cracked	2,167.80 FS	*1,405.71 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*LIGHT ASSY,L.FR.FOG	Not Necessary	253.74 FS	*- FS
43	1		*BRACKETL.FR.FOGLIGHT	Not Necessary	60.04 FS	*- FS
44	1		*FACE,FR.BUMPER	Deformed	665.00 FS	*651.89 FS
45	1		*BEAML.FR.BUMPER UPPER	Deformed	33.15 FS	*33.15 FS
46	1		*SPACERL.FR.BUMPER SIDE	Necessary	11.21 FS	*11.21 FS
47	1		*SPOILER ASSYL.FR.SIDE	Not Necessary	89.68 FS	*- FS
48	1		*LOWER PLATEFR.BUMPER	Deformed	139.74 FS	*139.74 FS
49	1		*GRILLEFR.BUMPER LOWER	Deformed	63.74 FS	*58.99 FS
50	1		*GARNISHL.FR.BUMPER	Not Necessary	43.79 FS	*- FS
51	1		*MEMBERL.FR.WHEELHOUSE UPPER	Not Necessary	104.21 FS	*- FS
52	1		*FENDER COMPL.FR.	Bent	521.17 FS	*521.17 FS
53	1		*FENDER COMPR.FR.	Bent	521.17 FS	*521.17 FS
54	1		*ENCLOSUREL.FR.FENDER	Not Necessary	24.98 FS	*- FS
55	1		*FENDER ASSYL.FRINNER	Not Necessary	114.66 FS	*- FS
56	6		*CLIP, INNER FENDER	Necessary	15.96 FS	*15.96 FS
57	1		*PANEL COMPINSTRUMENT UPPER	Deformed	835.81 FS	*835.81 FS
58	1		*TONGUE SETR.FR.SEATBELT OUTER	Activated	388.26 FS	*388.26 FS
59	1		*BULKHEAD COMPFR	Bent	437.76 FS	*437.76 FS
60	1		*CONDENSER COMP	Bent	647.80 FS	*647.80 FS
61	1		*RADIATOR COMP	Bent	1,279.93 FS	*1,279.93 FS
62	6		*COOLANT ANTI-FREEZE TYPE 2	Necessary	132.24 FS	*132.24 FS
63	1		*NUMBER PLATE WITH CASING-S	Bent	45.00 FS	*45.00 FS
64	1		*GARNISHL.FR.FENDER	Not Necessary	31.44 F	*- F
65	1		*EMBLEM,RR	Necessary	29.45 FS	*29.45 FS
66	4		*CLIP ABUMPER	Necessary	9.88 FS	*9.88 FS
67	1		*CLIPINNER FENDER (12PCS)	Necessary	44.46 FS	*44.46 FS
68	1		*SPOILER ASSY,R.FR.	Deformed	75.05 FS	*75.05 FS
69	1		*BEAM COMP,FR.BUMPER	Bent	277.21 FS	*277.21 FS
70	1		*BEAMR.FR.BUMPER UPPER	Bent	33.15 FS	*33.15 FS
71	1		*BASE,MID GRILLE P	Cracked	211.75 FS	*211.75 FS
72	1		*MOLDING,R.FR.MID GRILLE BPR	Cracked	57.76 FS	*57.76 FS
73	1		*MOLDING A,FR.MID GRILLE BPR	Cracked	169.48 FS	*169.48 FS
74	1		*MOLDING B,FR.MID GRILLE BPR	Cracked	154.09 FS	*154.09 FS
75	1		*MOLDING C,FR.MID GRILLE BPR	Cracked	57.76 FS	*57.76 FS
76	1		*MOLDING L,FR.MID GRILLE BPR	Cracked	57.76 FS	*57.76 FS
77	1		*MOLDING D,FR.MID GRILLE BPR	Cracked	144.40 FS	*144.40 FS
78	1		*GARNISH,R.FR.FOG	Deformed	67.35 FS	*67.35 FS
79	1		*GARNISH,L.FR.FOG	Deformed	67.35 FS	*67.35 FS
80	1		*CLIPFR.GRILLE (4PCS)	Necessary	8.74 FS	*8.74 FS
81	1		*MOLDING C,L.FR.MID GR BPR	Cracked	57.76 FS	*57.76 FS
82	1		*SUB CORD,RR BUMPE	Distorted	51.96 FS	*51.96 FS
83	1		*BUZZER ASSYSMART	Cracked	57.09 FS	*57.09 FS
84	1		*HOOD COMP	Bent	637.83 FS	*637.83 FS
85	1		*HINGE COMPR.HOOD	Bent	45.03 FS	*45.03 FS
86	1		*HINGE COMPL.HOOD	Bent	45.03 FS	*45.03 FS
87	1		*INSULATOR, HOOD	Deformed	110.20 FS	*110.20 FS
88	1		*LABEL AIR CONDITIONER CAUTION	Necessary	1.71 FS	*1.71 FS
89	1		*LABELCOOLANT INFORMATION	Necessary	4.75 FS	*4.75 FS
90	2		*SENSOR ASSY, PARKING BACK SENSOR	Not Working	508.82 FS	*508.82 FS
91	2		*SENSOR ASSY, PARKING BACK SENSOR	Not Working	508.82 FS	*508.82 FS
92	1		*RETAINER, PARKING	Necessary	39.71 FS	*39.71 FS
93	1		*RETAINER, PARKING BACK SENSOR	Necessary	39.71 FS	*39.71 FS
94	1		*RETAINER, PARKING	Necessary	39.71 FS	*39.71 FS
95	1		*RETAINER, PARKING D	Necessary	39.71 FS	*39.71 FS
96	1		*SENSOR ASSY, PARKING BACK SENSOR	Not Working	254.41 FS	*254.41 FS
97	1		*SUPPORTR.FR.BULKHEAD UPP SIDE	Bent	31.92 FS	*31.92 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*SUPPORT,L.FR.BULKHEAD UPP SIDE	Bent	31.92 FS	*31.92 FS
99	1		*COVER COMPPRIMARY CONVERTER	Distorted	70.87 FS	*70.87 FS
100	1		*CHAMBER ASSYRESONATOR	Deformed	104.21 FS	*104.21 FS
101	1		*TUBE ASSY BAIR INTAKE	Deformed	62.70 FS	*62.70 FS
102	1		*STAY,R.FR.GRILLE	Distorted	8.64 FS	*8.64 FS
103	1		*STAY,L.FR.GRILLE	Distorted	8.45 FS	*8.45 FS
104	1		*FAN COMPCOOLING	Cracked	51.49 FS	*51.49 FS
105	1		*SHROUD COMP	Cracked	79.61 FS	*79.61 FS
106	1		*MOTOR, COOLING FAN	Distorted	306.47 FS	*306.47 FS
107	1		*HOSE COMPSUCTION	Bent	175.08 FS	*175.08 FS
108	1		*HOSE COMPDISCHARGE	Bent	152.19 FS	*152.19 FS
109	1		*PIPE COMPRECEIVER	Bent	167.86 FS	*167.86 FS
110	1		*SPACER,R.FR.BPR SLLE	Necessary	11.21 FS	*11.21 FS
111	1		*UNIT ASSY,SRS	Distorted	919.60 FS	*919.60 FS
112	1		*BASE,FR.GRILLE BUMPER	Cracked	148.29 FS	*148.29 FS
113	1		*UPPER MOLDING,FR.GRILLE	Cracked	115.52 FS	*115.52 FS
114	1		*LOWER MOLDING,FR.GRILLE	Cracked	277.30 FS	*277.30 FS
115	1		*EMBLEMH MARK	Necessary	28.02 FS	*28.02 FS
116	1		*NUTPUSH 3MM	Necessary	1.99 FS	*1.99 FS
117	1		*MOLDING,FR.BUMPER LOWER	Distorted	96.33 FS	*96.33 FS
118	1		*SENSOR ASSYFR.CRASH (2PCS)	Activated	250.23 FS	*250.23 FS
119	1		*OILSHEET (3PCS)	Necessary	115.99 FS	*115.99 FS
120	1		*TAILLIGHT ASSYL	Not Necessary	796.19 FS	*- FS
121	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	16.05 FS	*16.05 FS
122	1		*MODULE ASSYPASSENGER	Activated	2,646.32 FS	*2,646.32 FS
Total Parts (\$\$)					29,448.77	22,814.76

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS-4PCS	New	180.00	180.00
2	SEALANT FOR REAR END PANEL	New	80.00	80.00
3	SEALANT FOR TAILGATE	New	80.00	80.00
4	SEALANT FOR REAR FLOOR PANEL	New	80.00	80.00
5	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	180.00	180.00
6	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	560.00
7	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
8	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST&	New	560.00	560.00
9	REMOVE & INSTALL RR.WINDSCREEN	New	560.00	560.00
10	WINDSCREEN DAM KIT	New	80.00	80.00
11	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	560.00	560.00
12	CUT OFF & RENEW RR PANEL	New	5,000.00	4,480.00
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	2,700.00
14	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	450.00
15	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	New	560.00	560.00
16	APPLY BODY UNDERSIDE COATING	New	450.00	450.00
17	TO PERFORM FR MULTI SENSING CAMERA AIMING	New	560.00	560.00
18	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	560.00
19	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	180.00
20	REMOVE & TRANSFER FR.CAMERA	New	450.00	450.00
21	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	New	1,800.00	1,680.00
22	RENEW PASSENGER AIRBAG ASSY ECU &	New	1,200.00	1,120.00
23	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	New	1,000.00	560.00
24	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	380.00	380.00
25	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	330.00	330.00
26	REMOVE & RENEW REVERSE SENSORS-2 PCS	New	150.00	150.00
27	CUT OFF & RENEW BULKHEAD FR L WHEELHOUSE	New	4,000.00	2,800.00
28	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P)	New	4,000.00	3,600.00
29	TOWING SERVICES (MBBS)	New	120.00	120.00
Gross Labour Cost (\$\$)			27,670.00	24,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >