



§ ZOOM AUTOW

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

16 October 2019

Not Allowed
W/W
17/10/19
4/5 @ 3700
H/O

REG NO. : SKR 3120 S
 MAKE/MODEL : NISSAN QASHQAI *SJN7EA*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
NETT ITEMS		
1	Front headlamp	1,617.00
1	Front grille	322.40 X
1	Front grille logo	58.40 X
1	Front bumper <i>646</i>	1,855.00
1	Front bumper fog lamp rim	102.00 X
1	Front bumper inner sponge	207.20
1	Front bumper reinforcement -top	591.90 X
2	Front bumper side retainers <i>27.30</i>	54.60 <i>IPC</i>
1	Front fender -L/H	622.70
1	Front fender arch garnish	541.40
1	Front knuckle arm	676.70 X
1	Front lower arm	248.60 X
		<hr/> 6,897.90
	Less 10%	689.79
		<hr/> 6,208.11

SPECIAL NETT ITEMS		
1	Front bumper clip (1 set)	35.00 ✓
1	Front bumper fog lamp	279.20 ✓
1	Front tyre	400.00 X
1	Front wheel rim -L/H	850.00 X
1	Front shock absorber	453.20 X
		<hr/> 2,017.40

S/N	LABOUR CHARGES	AMT(\$)
1	To check wiring and resetting headlamps focusing.	80.00 <i>20</i>
2	To remove and refit front undercarriage.	300.00 X
3	To conduct wheel alignment.	150.00 <i>60</i>
4	To apply undercoating.	100.00 <i>30</i>
5	Panel beating.	1,400.00 <i>400</i>
6	To re-spray painting on the affected areas.	1,200.00 <i>600</i>
		<hr/> 3,230.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

GRAND TOTAL: is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

\$ 11,455.51

3661.6
103
3285.44
4719.64

3775

P-3661-60
5020
P-1870-80
S.N 31420
L-1110-00

3255