

STANDARD

ASS. REC. BY:

SAI Veyan

REF

es3/lpc19000203/ETB-1ⁿ²

Special Instruction

ASSIGNMENT (Office)

From (Person)

Gerald Poh

of

lpc

Date/Time

17.10.2019

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH 4000Z

Insured:

GV 271K

at Workshop n/s

Continental Klasse

Tel:

9724 3110

of

68 kaki Bukit Ave 6 #04-07

Policy No:

Claim No:

18/18/18/VC05/021241

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

15/12/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time

10:13am 4/11/19

Person Contacted

Demick

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SGH 4000Z - NA / LPC 18022804 / 24
	GV 271K - NA / LPC 18022804 / 24
	Submit PRS Report.
	Original Document return to tempoc.

lump Sum \$2400 cred. 5600: 70%

18/10/2019

18/10 - File pass to typist

3 days


RECEIVED 10 OCT 2019

Steve

REF: 4PC

ASSIGNMENT

From: _____ Date: 09/01/2019
Estimated Cost: _____
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No. SGH 4000Z
at Workshop n/s Continental Klasse
of 68 koki Bkt Ave 6 # 04-07
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: 10am-12pm



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS ^{up}
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. SGH 4000Z 13/12/2011
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Audi A5 C.C. 2.0 1984
Colour: White A/C Insured / Std / NI / NA
Sp Reading: 109428 T/Radio: Insured / Std / NI / NA
Eng/No: _____
Ch/No: WAUZZZ8T0BA110332
Gen. Cond: Good / Fair / Poor / Burnt
Steering: ☒ Order / Jammed / Leaked / Burnt or
Brake: ☒ Order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 275/30ZR20
R: 275/30ZR20
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Kinforest
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 15/12/2019 D.O.I. 9/1/2019 12:31pm
Survey held at Continental Klasse
Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	3K - 4K repair large 3 day repair
	MV - 60,000
	PV - 51,776
	INV - 8,224

RECEIVED 28 JAN 2019

Date/Time. File Pass to? ☐ : Preli. Report
12/28/11 Typist ☒ : Final Report
Date/Time. File Return to?
Report Format: PRE-TP
Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)
Survey Fee: _____
Transportation: _____
Photos: _____
TOTAL: _____
450



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 18/18/18/VC05/021241

Your Ref : CS3/LPC19000203/Etd3n2

15 October 2019

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SGH4000Z

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SGH4000Z
- b) GIA report SGH4000Z
- c) GIA report and photos of GV271K

Kindly study the documents and let us have your report by 29 October 2019.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/12/2018 18:33
 Date Of Accident 15/12/2018 10:00
 Exact Location Of Accident CP HOUGANG STREET 31 CARPARK EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGH4000Z
Insured/Policyholder
 Name Of Registered Owner CHENG JING QIN
 NRIC No S7831172Z
 Email Address CHRISJQCHENG@YAHOO.COM.SG
 Mobile Phone No (LOCAL) +65-90686950
 Alternative Phone No OFFICE-90686950

Vehicle Particulars

Manufacturer AUDI
 Model A5 2.0L
 Exact Purpose for which vehicle was being used at time of accident PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company FWD SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number PNPV2017-00008754
 Cover Note Number

Driver

Name of Driver CHENG JING QIN
 NRIC No S7831172Z
 Date Of Birth 22/10/1978
 Occupation INDOOR
 Date Of Driving Pass 30/05/2006
 Driving Experience 12 YEARS AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90686950
 Fax Number
 Contact Number OFFICE-90686950
 Email Address CHRISJQCHENG@YAHOO.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Carpark exit, was queuing behind a van to exit the carpark. Suddenly this van started to reversed and when I saw, I honked to warn the driver. The van continued reversing and as a result bumped directly onto my vehicle front portion. Refer to the video footage.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV271K
Vehicle Make/Model/Colour	TOYOTA/LITEACE D./BLUE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TUNG, DERRICK
NRIC/Passport Number	S9238940E
Contact Number	91120247
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Person.
3. Information provided must be truthful and accurate as possible to allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form is subject to the terms and conditions of the policy.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded to the relevant authorities for their use.
7. By the lodgement of this report to the relevant authorities, the information provided is being made available to them.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data (including information set out in this form) and any other personal information provided by me or possessed by my insurer collectively my "Personal Information" and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Ministry of Transport of Singapore and any relevant government agency or agencies (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claim (including the information the Insurers, my workshop, my insurer, my lawyer/law firm, the police, etc.);
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or request and/or any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all Insurers who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

Carpark exit, was queuing behind a van to exit the carpark. Suddenly this van started to reversed and when I saw,I honked to warn the driver. The van continued reversing and as a result bumped directly onto my vehicle front portion. Refer to the video footage.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

17 December 2018 at 1:00 PM

Date/Time:

17 December 2018 at 1:00 PM

68 KAKI BUKIT AVE 6
#04-07 ARK@KB SINGAPORE 417896
TEL : 9724 3110

Our Reference:	A5/SGH4000Z
Date:	20-Feb-2019
Vehicle Num:	SGH 4000 Z
Make/Model:	AUDI A5 2.0L TFSI QUATTRO
Chassis No.:	WAUZZZ8T0BA110332
Engine No.:	CDN230969
Accident Date:	15-Dec-2018

	Amount
TOTAL LUMP SUM REPAIR FOR SGH 4000 Z	\$8,000.00
TOTAL :	\$ 8,000.00
E. & O.E	

CONTINENTAL KLASSE PTE LTD

AUTOMOBILE ASSESSMENT REPORT

TO: CHENG JING QIN
C/O: CONTINENTAL KLASSE PTE LTD
68 KAKI BUKIT AVE 6
#04-07 ARK@KB
SINGAPORE 417896

Our Reference: 119/CK027
Date: 20-Feb-2019

ASSESSMENT OF VEHICLE NO. SGH 4000 Z
DATE OF LOSS: 15-Dec-2018

We have carried out a physical assessment at CONTINENTAL KLASSE PTE LTD,
68 Kaki Bukit Ave 6 #04-07 ARK@KB, Singapore 417896, according to your instruction
on 09-Jan-2019 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SGH 4000 Z
Make & Model: AUDI A5 2.0L TFSI QUATTRO
Year of Registration: 2011
Engine Capacity: 1984
Chassis No.: WAUZZZ8T0BA110332
Engine No.: CDN230969
Colour: WHITE
Mileage (km): 109428

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: KINFOREST 275/30 R20 - 75%
LH Make/Size/Thread: KINFOREST 275/30 R20 - 75%


Rear
RH Make/Size/Thread: RADAR 275/30 R20 - 75%
LH Make/Size/Thread: RADAR 275/30 R20 - 75%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$18,076.27
Adjusted Amount:	\$10,676.33
Lump Sum:	\$8,000.00
Estimated Repair Days:	5 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

Mark here

ASSESSMENT REPORT FOR VEHICLE NO. SGH 4000 Z

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET X R	Repair	4,700.93	-
2	FRONT BONNET MECHANISM LOCK CATCH L/R X SVC	Repair	181.54	-
2	FRONT BONNET MECHANISM LOCK L/R X SVC	Repair	479.20	-
1	FRONT RH HEADLAMP X SVC	Cracked	1,900.93	1,900.93
4	FRONT RH HEADLAMP CLIPS X SVC	Necessary	26.00	26.00
1	FRONT RH HEADLAMP LOWER BRACKET X SVC	Bent	123.47	123.47
1	FRONT GRILLE (RS5) / CUT	Cracked	1,680.80	1,680.80 ✓
1	FRONT GRILLE 'LOGO' EMBLEM / CUT	Necessary	96.30	96.30 ✓
1	FRONT GRILLE CLIP X SVC	Cracked	6.50	6.50
1	FRONT GRILLE 'RS5' EMBLEM / CUT	Cracked	88.60	88.60 ✓
1	FRONT BUMPER X R	Cracked	2,200.93	2,200.93
1	FRONT BUMPER INNER SPONGE Y SVC	Cracked	120.77	120.77
1	FRONT BUMPER REINFORCEMENT X SVC	Bent	820.93	820.93
2	FRONT BUMPER REINFORCEMENT BRACKET L/R X SVC	Bent	401.94	401.94
2	FRONT BUMPER FOGLAMP GARNISH L/R X SVC	Cracked	422.93	422.93
2	FRONT BUMPER FOGLAMP COVER BRACKET L/R X SVC	Bent	96.89	96.89
2	FRONT BUMPER NOZZLE COVER L/R X SVC	Necessary	146.70	146.70
2	FRONT BUMPER NOZZLE COVER SPRING L/R X SVC	Bent	42.17	42.17
2	FRONT BUMPER SIDE RETAINER L/R / BR	Bent	99.54	99.54 ✓
2	FRONT BUMPER HEADLAMP NOZZLE L/R X SVC	Repair	440.97	-
1	FRONT SUPPORT PANEL INNER TOP GARNISH /	Cracked	210.93	210.93 ✓
1	FRONT SUPPORT PANEL X SVC	Repair	1,207.30	-
			15,496.27	8,486.33
Less 0% discount			-	-
Parts Total:			15,496.27	8,486.33

2176.17
 - 5%
 2067.36

ASSESSMENT REPORT FOR VEHICLE NO. SGH 4000 Z

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE / <i>cut</i>	Cracked	<i>50/</i> 80.00	80.00
1	FRONT NUMBER PLATE HOLDER <i>x</i> <i>SVK</i>	Cracked	50.00	50.00
1	FRONT BUMPER CLIPS - SET / <i>AK</i>	Necessary	30.00 /	30.00
Special Nett Total :			160.00	160.00

LABOUR


S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting.	120.00 <i>30/</i>	100.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 <i>500/</i>	850.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00 <i>300/</i>	1,000.00
4	To apply anti-rust chemical on repaired and replaced panel.	100.00 <i>30/</i>	80.00
Labour Total :		2,420.00	2,030.00
TOTAL (PARTS & LABOUR) \$		18,076.27	10,676.33

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$8,000.00

(SINGAPORE DOLLARS EIGHT THOUSAND ONLY)



Amas Ong
Automobile Assessor

P- 2067.36
NI- 80
L- 860
3097.36
L/S- 2405.88
= 2490

3 repair days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC19000203/Etf3n2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 21-10-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GV 271K	Veh. Inspected	SGH 4000Z	
Policy No.	Z/18/VC05/000780-001	Coverage (\$)	0.00	
Claim No.	18/18/18/VC05/021241	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	17/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A5	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WAUZZZ8T0BA110332	Colour	WHITE	
Odometer	109428	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 ZR20	KINFOREST	6 mm	
L/H Front Tyre	275/30 ZR20	KINFOREST	6 mm	
R/H Rear Tyre	275/30 ZR20	KINFOREST	6 mm	
L/H Rear Tyre	275/30 ZR20	KINFOREST	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2018	Inspection Date	09/01/2019	
Survey held at	68 KAKI BUKIT AVE 6# 04-07			
Repairer	CONTINENTAL KLASSE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 4000Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	TO REPAIR SEE LABOUR	4,700.93	-
2	FRONT BONNET MECHANISM LOCK CATCH L/R	SERVICEABLE	181.54	-
2	FRONT BONNET MECHANISM LOCK L/R	SERVICEABLE	479.20	-
1	FRONT RH HEADLAMP	SERVICEABLE	1,900.93	-
4	FRONT RH HEADLAMP CLIPS	SERVICEABLE	26.00	-
1	FRONT RH HEADLAMP LOWER BRACKET	SERVICEABLE	123.47	-
1	FRONT GRILLE (RS5)	CUT	1,680.80	1,680.80
1	FRONT GRILLE "LOGO" EMBLEM	CUT	96.30	96.30
1	FRONT GRILLE CLIP	SERVICEABLE	6.50	-
1	FRONT GRILLE "RS5" EMBLEM	CUT	88.60	88.60
1	FRONT BUMPER	TO REPAIR SEE LABOUR	2,200.93	-
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	120.77	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	820.93	-
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	SERVICEABLE	401.94	-
2	FRONT BUMPER FOGLAMP GARNISH L/R	SERVICEABLE	422.93	-
2	FRONT BUMPER FOGLAMP COVER BRACKET L/R	SERVICEABLE	96.89	-
2	FRONT BUMPER NOZZLE COVER L/R	SERVICEABLE	146.70	-
2	FRONT BUMPER NOZZLE COVER SPRING L/R	SERVICEABLE	42.17	-
2	FRONT BUMPER SIDE RETAINER L/R	BROKEN	99.54	99.54
2	FRONT BUMPER HEADLAMP NOZZLE L/R	SERVICEABLE	440.97	-
1	FRONT SUPPORT PANEL INNER TOP GARNISH	CRACKED	210.93	210.93
1	FRONT SUPPORT PANEL	SERVICEABLE	1,207.30	-
	LESS 5% DISCOUNT		-	-108.81
			15,496.27	2,067.36
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	CUT	80.00	50.00
1	FRONT NUMBER PLATE HOLDER (SN)	SERVICEABLE	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			160.00	80.00

Report Ref No. CS3/LPC19000203/Etf3n2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING. TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT. TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT BUMPER. TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00 1,000.00 1,200.00 100.00 2,420.00	30.00 500.00 300.00 30.00 860.00
	GRAND TOTAL		18,076.27	3,007.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS3/LPC19000203/Etf3n2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.