

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15835

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1243/2019/KK
Date : 15-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yip Weng Hong
Address : Blk 113 Whampoa Road
#10-93
Singapore 320113
Telephone : (HP) +65 98447574
Type of Claim : Own Damage Claims
Policy No. : 2100495679-02
Vehicle No : **SLJ 8441 M**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : 28/12/2016
Engine No : CVN 024610
Chassis No : WAUZZZF44HA069319
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Oct-19
Place of Accident : Jalan Bahagia(Outside Blk 27)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 8441 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00 X nn	X
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00 ? plate? X nn	
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy,	S/N \$ 360.00 ✓	✓
4	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 X nn	X
5	To remove and reinstall engine assy with gearbox assy to facillitate car o-liner repairs.	S/N \$ 2,800.00 ?	X nn
SUB LABOUR CHARGES		: \$ 5,440.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 8441 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Reccomendations
6	To remove and reinstall front suspension assy with subframe to facillitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00 ?	X nn
7	To renew front windscreen.	S/N \$ 480.00 /	✓
8	To insatall solar film for front windscreen.	S/N \$ 400.00 /	✓
9	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00 X	X nn
10	To place vehicle on car o-liner.	S/N \$ 2,400.00 ?	X nn
SUB LABOUR CHARGES		: \$ 5,980.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 8441 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Reccomendations
11	To dismantle and renew front bumper, bonnet, lhs front fender, and lhs headlight. Cut out and reweld lhs fender support and closing element. To repair lhs front door. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	(5.5) \$ 7,700.00 2750	2250 ✓
12	To respray front bumper, lhs front fender, bonnet, hinges, engine compartment, lhs front fender top support, lhs stone chip guard and lhs front door. To carry out joint sealant work and stone chip treatment.	(3.5) \$ 6,300.00 1925	✓
13	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	✓
14	To carry out diagnostic checks.	S/N \$ 384.00	✓ 192
TOTAL LABOUR CHARGES		: <u>\$26,084.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8441 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>TORN</i> ✓	\$ ✓ 1,946.00	1556.80
2	FRONT BUMPER FIXING PARTS <i>? nn</i>	\$ 258.00	X
3	FRONT BUMPER SECURING STRIP <i>nn</i> ✓	\$ ✓ 32.00	25.44
4	FRONT BUMPER LOWER GRILLE - CENTER <i>? X SVC</i>	\$ 178.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>? SVC</i>	\$ 191.00	X
6	FRONT BUMPER AIR GUIDE - LH <i>cra</i> ✓	\$ 56.00	44.40
7	RADIATOR GRILLE <i>? cra</i> ✓	\$ ✓ 2,115.00	1692
8	FRONT BUMPER FOAM FILLER PIECE <i>cra</i> ✓	\$ 113.00	90.40
9	FRONT BUMPER CARRIER <i>? X SVC</i>	\$ 733.00	X
10	FRONT BUMPER TOP COVER <i>X cut</i> ✓	\$ 116.00	92.40
11	FRONT BUMPER GUIDE SECTION - LH <i>? de</i> ✓	\$ ✓ 33.00	26.08
12	CAUTION SIGN STICKER <i>X nec</i> ✓	NEC \$ ✓ 13.00	9.76
13	AIR CONDITIONER STICKER <i>X nec</i> ✓	NEC \$ ✓ 7.00	5.12
14	FRONT BUMPER BRACKET <i>cra</i> <i>? SVC</i>	\$ 207.00	X
15	FRONT BUMPER LOCK CARRIER BRACKET <i>? SVC</i>	\$ 125.00	X
16	FRONT BUMPER SUPPORT <i>LH/RH</i> <i>? SVC</i>	2 \$ 52.00	X
17	HORN - LH HIGH TONE <i>X SVC</i>	\$ 37.00	X
18	SPRING SHACKLE - LH <i>X SVC</i>	\$ 26.00	X
19	FRONT FENDER - LH <i>bm</i> ✓	\$ ✓ 700.00	559.60
20	FRONT FENDER ATTACHMENT PARTS <i>? nn</i>	\$ 183.00	
SUB TOTAL SPARE PARTS		: \$ <u>7,121.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8441 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER CLOSING ELEMENT - LH ?cut	\$ 45.00	36
22	FRONT FENDER BRACKET - LH ?bt	\$ 32.00	25.20
23	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH ?de	\$ 45.00	35.60
24	FRONT BUMPER REAR BRACKET ?nec	\$ 29.00	22.64
25	FRONT BUMPER UPPER BRACKET ?nec	\$ 31.00	24.16
26	FRONT FENDER BRACE - LH ?bt	\$ 107.00	85.60
27	FRONT FENDER CLOSING ELEMENT - LH ?SVC	\$ 30.00	X
28	FRONT FENDER END COVER - LH de SVC	\$ 11.00	X
29	FRONT WHEEL HOUSING LINER - LH de	\$ 223.00	178.40
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?nn	\$ 82.00	X
31	FRONT WHEEL SPOILER ?bro	\$ 66.00	52.32
32	FRONT WHEEL END PLATE Mis	\$ 32.00	25.04
33	STONE CHIP GUARD ?nec	\$ 46.00	36.64
34	BONNET bf	\$ 2,554.00	2043.20
35	BONNET ATTACHMENT PARTS ?nn	\$ 111.00	X
36	BONNET LID HINGE - LH/RH X SVC	2 \$ 554.00	X
37	BONNET IMPACT PROTECTION - CENTER/LH/RH ?nn	\$ 75.00	59.44
38	FRONT FENDER LEDGE COVER OUTER - LH ?SVC	\$ 56.00	X
39	FRONT FENDER LEDGE COVER INNER ?cut	\$ 28.00	22.24
40	FRONT FENDER LEDGE COVER SHORT - LH ?cut	\$ 21.00	16.16
SUB TOTAL SPARE PARTS		\$ 4,178.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8441 M

		Damaged Parts & Prices		
S/N	Parts Description	S/Nett	Remarks	
41	BONNET GAS FILLED STRUT X	2 \$	217.00	
42	BONNET STRIKER - LH / RH X	2 \$	92.00	
43	BONNET LID LOCK X	\$	196.00	
44	BONNET BOWDEN CABLE - CENTRE X	\$	53.00	
45	BONNET BOWDEN CABLE - LH X	\$	53.00	
46	BONNET RELEASE LEVER X	\$	12.00	
47	BONNET LID LOCK CABLE X	\$	67.00	
48	PLENUM CHAMBER COVER X	\$	89.00	
49	BONNET SOUND ABSORBER X	\$	311.00	
50	LED HEADLIGHT - LH 840	\$	7,087.00	5669.60
51	MAIN LIGHT ELECTRONICS POWER MODULE ? SVC	\$	716.00	X
52	HEADLIGHT HOSE - LH X SVC	\$	32.00	X
53	HEADLIGHT SPACER cut	\$	39.00	30.56
54	LIFT CYLINDER - LH ms	\$	192.00	153.20
55	HEADLIGHT CORRUGATED PIPE X SVC	\$	83.00	X
56	WHEEL HOUSING CONNECTING PLATE - LH st SVC	\$	54.00	X
57	WHEEL HOUSING CONNECTING PLATE - LH st	\$	197.00	157.20
58	FENDER SUPPORT PANEL - LH ?	\$	228.00	X
59	LOCK CARRIER X	\$	928.00	X
60	COLLANT REGULATOR SUPPORT X	2 \$	69.00	X
Control unit for light control system ? SVC X			685.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8441 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
61	A/C CONDENSER X } SVC	\$ 568.00	2x
62	COOLANT PIP X	\$ 152.00	
63	REFRIGERANT LINE X bt -	\$ 310.00	248
64	DRYER INSERT X	\$ 123.00	2x SVC
65	RADIATOR X	\$ 603.00	
66	RADIATOR RUBBER BUSH - LOWER X	2 \$ 17.00	
67	RADIATOR RUBBER BUSH - LOWER X	2 \$ 24.00	
68	ADDITIONAL RADIATOR - LOWER CENTRE X	\$ 470.00	
69	READY MIX COOLANT X	4 \$ 84.00	
70	RADIATOR FAN RING X	\$ 242.00	
71	RADIATOR FAN CONTROL UNIT X	\$ 2,107.00	
72	RADIATOR AIR GUIDE - LH OUTER X	\$ 25.00	
73	RADIATOR AIR GUIDE - LH INNER X	\$ 11.00	
74	RADIATOR AIR GUIDE - UPPER X	\$ 15.00	
75	RADIATOR AIR GUIDE - LOWER X	\$ 19.00	
76	CHARGE AIR COOLER X	\$ 663.00	832
77	INTER COOLER SEAL X	\$ 16.00	
78	INTER COOLER GASKET X	\$ 13.00	
79	WINDSCREEN X can -	\$ 1,040.00	
80	RAIN SENSOR GEL FOIL X nu -	\$ 128.00	102.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8441 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	PRIMER <i>✓</i>	\$ 19.00	
82	EXTERNAL TEMPERATURE SENSOR <i>x</i>	\$ 54.00	
83	TEMPERATURE SENSOR BRACKET <i>x</i>	\$ 17.00	
84	FRONT WISHBONE LINK <i>?</i>	\$ 491.00	
85	FRONT LOWER CONTROL ARM - LH <i>?</i>	\$ 861.00	
86	FRONT CONTROL ARM - LH UPPER <i>?</i>	\$ 466.00	
87	FRONT CONTROL ARM - LH LOWER <i>?</i>	\$ 466.00	
88	WHEEL BEARING HOUSING - LH <i>?</i>	\$ 884.00	
89	SWIVEL JOINT <i>?</i>	\$ 175.00	
90	WHEEL HUB <i>?</i>	\$ 451.00	
91	DOUBLE ANGLED BALL BEARING <i>?</i>	\$ 232.00	
92	SUSPENSION FORKS - LH <i>?</i>	\$ 239.00	
93	COUPLING ROD <i>?</i>	\$ 123.00	
94	DRIVE SHAFT <i>?</i>	\$ 2,422.00	
95	GAS SHOCK ABSORBER <i>?</i>	\$ 276.00	
96	TRACK ROD <i>?</i>	\$ 90.00	
97	STEERING GEAR GREASE <i>?</i>	\$ 41.00	
98	TIE ROD END <i>?</i>	\$ 180.00	
99	RADIATOR AIR GUIDE GRILLE - LH <i>x cra</i>	✓ TBC 150	
100	FRONT RIM - LH <i>cat</i>	✓ 989.00 989	

SVC

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8441 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
101	FRONT NO PLATE X	S/N \$ 60.00	
102	ACRYLIC SEALANT X	S/N \$ 180.00	
103	CAVITY WAX X	S/N \$ 140.00	
104	STONE CHIP X	S/N \$ 180.00	
105	FRONT W/S SEALANT ne	S/N \$ 200.00	
106	SUNDRIES 7. nec	S/N \$ 1,000.00	
TOTAL SPARE PARTS		: \$ 38,880.00	
TOTAL LABOUR CHARGES		\$ 26,084.00	
GRAND TOTAL		\$ 64,964.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Rasul - 4p 90010068

17/10/19 @ 1050

8 days

EXCESS: TBA

REVERT

Reamy before paint

18/10/19

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant