

Premium Automobiles
Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15799

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1253/2019/NS
Date : 16-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Han Dong
Address : 2 Leedon Heights
#05-02
Singapore 266228
Telephone : HP +65 96466688
Type of Claim : Own Damage Claim
Policy No. : 1900110506
Vehicle No : **SKB 123 M**
Model Code : Audi Q8 3.0 TFSI qu 4MNOX
Model / Year : Jun-19
Engine No : DCB 051796
Chassis No : WAUZZZF1XKD010190
Mileage :
Date In :

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 123 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper. Re-organise frash management components. Reinstall all parts removed.	\$ 1,350.00 ✓ 500. 1800	
3	To respray front bumper, rhs front fender, rhs front bumper spoiler and both front wheel arch trims.	\$ 3,500.00 ✓ 1800	2 x 550 = 1100. Wheel Arch : 250 x 2 = 500 Spoilers : 200. 1800.
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 5,802.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 123 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repr</i>	\$ 2,306.00	+
2	FRONT BUMPER FIXING PARTS - FRONT <i>2 new</i>	\$ 342.00	+
3	FRONT BUMPER CLOSING ELEMENT - RH	\$ 109.00	+
4	FRONT BUMPER FRAME - RH <i>2 new</i>	\$ 74.00	+
5	FRONT BUMPER COVER - RH	\$ 74.00	+
6	FRONT BUMPER CLOSING ELEMENT - CENTRE <i>2 new</i>	\$ 253.00	+
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	+
8	FRONT BUMPER SPOILER - RH <i>at</i>	\$ 192.00	✓ 153.60
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>2</i>	\$ 167.00	+
10	ULTRASOUND SENSOR SUPPORT - RH	\$ 26.00	+
11	FRONT BUMPER BRACKET - RH	\$ 31.00	+
12	FRONT BUMPER GUIDE SECTION - RH	\$ 40.00	+
13	FRONT PARKING AID SENSOR	\$ 231.00	+
14	FRONT PARKING AID SEAL RING <i>2 new</i>	4 \$ 12.00	+
15	FRONT WHEEL HOUSING LINER - RH	\$ 232.00	+
16	REAR WHEEL HOUSING LINER - RH	\$ 232.00	+
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2 new</i>	\$ 66.00	+
18	FRONT SPOILER - RH	\$ 62.00	+
19	FRONT WHEEL COVER - LH / RH <i>2 new</i>	2 \$ 1,044.00	✓ 834.40
20	FRONT ALUMINIUM RIM - RH <i>at</i>	\$ 1,988.00	✓ 1590.40
21	ALUMINIUM RIM RUBBER VALVE <i>2 new</i>	4 \$ 13.00	+
22	SUNDRIES <i>Not new</i>	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		\$ 8,085.00	
TOTAL LABOUR CHARGES		\$ 5,802.00	
GRAND TOTAL		\$ 13,887.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *17/10/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant