

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19018346/UGA3Q2

Date: 11/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0002482
Claimant Vehicle No :	SKZ4892Z	Insured Vehicle No :	SGN2127Z
Date of Loss:	12/10/2019	Nature of Claim:	TP
		Claim No:	MPC2019D0001281

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ4892Z	Engine No:	L15B4027505
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11107503
Reg. Date:	25/01/2016 (Man. Year: 2015)	Odometer:	80351 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,766.50	2,520.96	2,245.54	47.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	680.00	520.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,966.50	3,200.96	2,765.54	46.35
Approved Total (Overridden) (\$\$)		2,550.00		
Nett Amount (\$\$)	5,966.50	2,550.00	3,416.50	57.26
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	17/10/2019	
Date Inspected:	17/10/2019 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ4892Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Warped	845.20 F	*762.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	321.00 F	*- FL
3	1		*FRONT BUMPER FOG LAMP COVR O/S	Not Necessary	145.00 F	*- FL
4	1		*FRONT BUMPER FOG LAMP O/S	Not Necessary	322.50 F	*- FL
5	1		*FRONT BUMPER LOWER SKIRTING	Deformed / Torn	480.00 F	*480.00 FL
6	1		*HEADLAMP O/S	Cracked	1,859.10 F	*1,859.10 FL
7	1		*FRONT FENDER O/S	Repair	455.20 F	*- FL
8	1		*FRONT FENDER OUTER PROTECTOR O/S	Not Necessary	288.50 F	*- FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,766.50	3,151.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	630.24

Total Parts (\$\$)	4,766.50	2,520.96
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	420.00	250.00
4	TO PUTTY & SPRAY PAINTING	New	680.00	400.00
Gross Labour Cost (\$\$)			1,200.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >