

ASS. REC. BY:

REF: CS/CT1 19018349/Eyfs²

Special Instruction:

Surveylor: Steve

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of

CT1

Date/Time: 17.10.19 14.17p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

PA 9134 T

Insured:

YP 5515T

at Workshop m/s

Lexbuild Auto & trading Pte Ltd

Tel:

6362 3393

of

74 Sungai Radut Street 1 #29574

Policy No:

DMCVSN17111719022

Claim No:

SNM19D20499302

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.10.19 2.42p.m

Person Contacted:

Hui Wen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	PA 9134T - CS/CT1 19015107/Eyfs	D.O.A - 23/03/2019
	YP 5515T - X	

Birney Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PA 9134T

Yr Regn: 21/1/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Foton BJ 6940

c.c 6700

Colour

Multi-Colour

A/C: Insured / Std / NI / NA

Sp. Reading

24 7267

T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo:

LVC 83RDB 69M0014.02

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

11R 22.5

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ANNAITE

Front

Rear

R/Bal.

5

mm

R/Bal.

5/5

mm

L/Bal.

5

mm

L/Bal.

5/5

mm

D.O.A.

15/10/19

D.O.I.

17/10/19

Survey held at

Lexbald

Des. of Damages: (Frt) Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/10 Pending Estimate (Workshop said Car Not In)

28/2 Car In to Repair and give Estimate

20/3 LIS \$5350/- (Red \$5473-05, 50%)

RECEIVED 24 MAR 2020

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

23/3/20 Typist

Report Format :

Lump Sum / I.B.I. (\$

\$5350/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

..

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Steve Chen (LKK Auto)

From: Hui Wen Lim <huiwen.lexbuildauto@gmail.com>
Sent: Thursday, March 05, 2020 12:24 PM
To: Steve Chen (LKK Auto)
Subject: Re: PA9134T - Request finalized repair cost

Dear Steve,

We confirm.

Thanks:)

Hui Wen

On Wed, Mar 4, 2020 at 8:38 AM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Hui Wen,

Kindly refer our finalize \$5350 (L/S, before GST). 5 repair days.

Kindly confirm.

Thanks.

Best Regards,

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Oct 2019		17 Oct 2019 14:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: HUI LEONG BUS TRANSPORT SERVICES, Co. Reg. No.: 53151728D									
Vehicle Reg. No.: PA9134T		Date of Loss: 15/10/2019 21:00 - :59							
Claim Type: TP / SNM19D204893C02		Policy/Cover Note No.: DMCVSN17111719022							
Vehicle Reg. No. (Insured): YP5515T		Policy No. (Claimant): D19MTSCBU000030							
		Excess: S\$550.00							
Repairer: Lexbuild Auto & Trading Pte Ltd (HQ) 74 Sungei Kadut Street 1, 729374 Sungei Kadut - Tel: 63623393									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Candice <accident@kscgp.com>
Sent: Thursday, 17 October 2019 12:53 PM
To: 'assignments'
Cc: jiapei@kscgp.com
Subject: Veh no: PA 9134T / Our ref: GS/19/4989/HU/jp/ca

Dear Nivitha,

We refer to the above matter and to our earlier tele-conversation.

Please be informed that our client's vehicle, PA 9134T, is ready for inspection.

The vehicle can be inspected at the following address:-

No. 74 Sungei Kadut Street 1
Singapore 729374

Contact person: Bessy / Tel: 6777 0043

Regards,
Candice
For and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the MxScan Email Security System.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/10/2019 12:05
 Date Of Accident 15/10/2019 21:35
 Exact Location Of Accident JUNCTION OF YISHUN AVE 8 & CANBERRA WAY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number PA9134T
Insured/Policyholder
 Name Of Registered Owner HUI LEONG BUS TRANSPORT SERVICES
 Co Reg No 53151728D
 Email Address OPERATIONS@HUILEONGBUS.COM
 Mobile Phone No
 Alternative Phone No OFFICE-63682818
Vehicle Particulars
 Manufacturer FOTON
 Model BJ6940-6.7 D (M)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
Insurance Company
 Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy NO
 Policy Number D19MTSCBU000030
 Cover Note Number
Driver
 Name of Driver LUAN GUIXING
 Passport No/FIN G2752897Q
 Date Of Birth 22/09/1974
 Occupation OUTDOOR
 Date Of Driving Pass 15/03/2016
 Driving Experience 3 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90859246
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 17

Passenger 1
NAME: : -
GENDER: : MALE

Passenger 2
NAME: : -
GENDER: : MALE

Passenger 3
NAME: : -
GENDER: : MALE

Passenger 4
NAME: : -
GENDER: : MALE

Passenger 5
NAME: : -
GENDER: : MALE

Passenger 6
NAME: : -
GENDER: : MALE

Passenger 7
NAME: : -
GENDER: : MALE

Passenger 8
NAME: : -
GENDER: : MALE

Passenger 9
NAME: : -
GENDER: : MALE

Passenger 10
NAME: : -
GENDER: : MALE

Passenger 11	NAME: : -
	GENDER: : MALE
Passenger 12	NAME: : -
	GENDER: : MALE
Passenger 13	NAME: : -
	GENDER: : MALE
Passenger 14	NAME: : -
	GENDER: : MALE
Passenger 15	NAME: : -
	GENDER: : MALE
Passenger 16	NAME: : -
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 15/10/19 @ 21:35HRS, I WAS DRIVING MY BUS PA9134T TRAVELLING ON THE LEFT MOST LANE ALONG YISHUN AVE 8. WHILE MAKING A LEFT TURN TO CANBERRA WAY, A LORRY YP5515T ON MY RIGHT PERFORMED AN ILLEGAL LEFT TURN FROM A STRAIGHT ONLY LANE AND RESULT IN COLLISION TO MY FRONT RIGHT. LORRY TRIED TO FLEE BUT I MANAGED TO CATCH UP AND STOP HIM TO GET HIS PARTICULARS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5515T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 2

SKETCH PLAN

Vehicle A - PA 91341

Vehicle B - TP 56151

A

B

Vehicle A

DESCRIPTION OF CIRCUMSTANCES OF THE ACCIDENT

On 10/10/19 @ 2:35 PM, I was driving my bus PA 91341 heading on the left most lane along Turner Ave & while moving a left lane to resume way. A large vehicle on my right passed on illegal left turn lane & struck my lane and was in collision to my front right corner due to the but, I managed to pull up and stop time to get his position.

DECLARATION

I am declaring the accuracy of the information provided in this report.

Driver: [Name] Date: [Date]

Witness: [Name] Date: [Date]



Officer: [Name] Date: [Date]



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	728D
Vehicle Details	
Vehicle No.:	PA9134T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	FOTON
Vehicle Model:	BJ6940
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	ISBE425021877167
Chassis No.:	LVCB3RDB69M001402
Maximum Power Output:	-
Open Market Value:	\$113,281.00
Original Registration Date:	21 Jan 2010
First Registration Date:	21 Jan 2010
Transfer Count:	0
Actual ARF Paid:	\$5,665.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jan 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$17,900.00
COE Rebate Amount:	\$461.00
Total Rebate Amount:	\$461.00

The information contained herein is correct as at 17 Oct 2019

OK

10 Sui Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

21 Jan 2010

Our ref: 2101100101N004404621

HUI LEONG BUS TRANSPORT SERVICES
43 THONG BEE ROAD
SINGAPORE 779009



Dear Sir/Madam

NOTIFICATION ON REGISTRATION OF VEHICLE AND ROAD TAX

We wish to inform you that you have successfully registered vehicle PA9134T on 21 Jan 2010. The details of the registration are as follows:

A) Owner Particulars

1.	Name	: HUI LEONG BUS TRANSPORT SERVICES
2.	Identification No. Type	: Business
3.	Identification No.	: 53151728D
4.	Place Of Passport Issue	: -
5.	Registered Address	: 43 THONG BEE ROAD SINGAPORE 779009
6.	Mailing Address	: -

B) Vehicle Particulars

1.	Vehicle No.	: PA9134T
2.	Previous Vehicle No.	: -
3.	Effective Date of Ownership	: 21 Jan 2010
4.	Original Registration Date	: 21 Jan 2010
5.	First Registration Date	: 21 Jan 2010
6.	Vehicle Type	: Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus
7.	Vehicle Scheme	: Public Service Vehicle (Others)
8.	Attachment 1	: No Attachment
9.	Attachment 2	: -
10.	Attachment 3	: -
11.	Vehicle Make	: FOTON
12.	Vehicle Model	: BJ6940
13.	Year of Manufacture	: 2009
14.	Primary Colour	: Red
15.	Secondary Colour	: -
16.	Passenger Capacity	: 37
17.	Chassis/Trailer Chassis No.	: LVCB3RDB69M001402 / -
18.	Propellant	: Diesel
19.	Engine No./Motor No.	: ISBE425021877167 / -
20.	Engine Capacity(cc)/Power Rating(kw)	: 6700 / -
21.	Unladen Weight(kg)	: 9820

22.	Maximum Laden Weight(kg)	: 13800
23.	Open Market Value	: \$113,281.00
24.	PARF Eligibility	: No
25.	PARF Eligibility Expiry Date	: -
26.	Minimum PARF Benefit	: \$0.00
27.	No. of Transfers	: 0
28.	IU Label No.	: -
29.	COE No.	: 2010010105000307H
30.	COE Expiry Date	: 20 Jan 2020
31.	COE Category	: C - Goods Vehicle & Bus
32.	Quota Premium/Prevailing Quota Premium	: \$17,900.00
33.	Actual Quota Premium/PQP Paid	: \$17,900.00
34.	Actual ARF Paid	: \$5,665.00
35.	Vehicle Lifespan Expiry Date	: 20 Jan 2030
36.	Road Tax Amount	: \$435.00
37.	Road Tax Start Date	: 21 Jan 2010
38.	Road Tax End Date	: 20 Jul 2010
39.	Remarks	: This is a public service vehicle. To renew the COE, the Prevailing Quota Premium payable is that of Category C.

2. Enclosed is the validated road tax disc for your use.

3. You may use your NRIC number and SingPass or User ID and Password (for non-Singaporeans/PRs) to login to <http://www.onemotoring.com.sg> and see the details of the above transaction. For ACRA-registered businesses and companies with EASY accounts, your authorised staff may also access the wide range of vehicle-related services via <http://www.onemotoring.com.sg> using EASY. If you do not have an EASY account, you can apply for it at <http://www.iras.gov.sg>. For non-Singaporeans/PRs who do not have a User Password, please contact us at 1800-CALL LTA (1800-2255 582) to request for a new password. Please note that a separate Transaction PIN is required for the following transactions via the Internet or at our Electronic Service Agents. Before you perform these transactions, please request for your Transaction PIN. You may find out more information on how to obtain your Transaction PIN and the documents needed (such as Board Resolution for companies and businesses, etc) via <http://www.onemotoring.com.sg> > LTA Information & Guidelines > Transaction PIN & User Account.

- a. Vehicle PIN - Transfer of Ownership and De-registration of Vehicle
- b. TCOE PIN - Transfer of TCOE (For Category C and E COE bid under individual)
- c. Rebate PIN - Transfer and Splitting of PARF/COE Rebate

4. All new In-vehicle Units (IUs) are covered by a 5-year warranty against manufacturer's defect.



LEXBUILD AUTO & TRADING PTE. LTD.

74 Sungei Kadut St 1, S 729374 Tel: 63623393 Fax: 63632262 Reg No: 200616456D Email Lexbuildauto@gmail.com

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attn : Claim Dept

Dear Sir, Ma'am

Date : 16.10.2019

Our Ref : PA9134T/Hui Leong/1910

Your Ref : YP5515T

RE: Estimate Repair Cost for Vehicle No PA9134T

Traffic Accident on 15.10.2019 Involving PA9134T & YP5515T at Junction of Yishun Ave 8 & Canberra Way

S/N	Quantity	Particular	Unit Price	Amount S\$
1	1	Front Windscreen / OR	5,000.00	5,000.00
2	1	Front RHS Safety Glass / OR	850.00	850.00
3	1	Front RHS Corner Panel x R	650.00	650.00
4	1	Front RHS Drip Moulding / BT	650.00	650.00
				7,150.00
Less : 10% trade discount				(715.00)
				6,435.00

Net Item:-

6	12	Sealant APC	40.00	480.00
7	1	Advertisement nlc		500.00

Labour Charges :-

To remove damaged front windscreen glass & refit new.	800.00	600
To transfer driver window to new safety glass. To remove damaged safety glass & refit new.	350.00	250
To knock/straighten all necessary parts including repairing and changing of all damaged parts and align same.	950.00	500
To putty and spray painting on front rhs corner panel and all affected accident parts.	600.00	350

Total S\$: 10,115.00
GST 7% S\$: 708.05
Amount Due S\$ 10,823.05

Note : This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress.

Yours Sincerely,

Hui Leong

Poh Yew Leong
Workshop Supervisor



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**LEXBUILD
AUTO & TRADING PTE. LTD.**

74 Sungai Kadut St 1, S 729374 Tel: 63623393 Fax: 63632262 Reg No: 200616456D Email: lexbuildauto@gmail.com

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attn : Claim Dept

Dear Sir, Ma'am

Date : 16.10.2019

Our Ref : PA9134T/Hui Leong/1910

Your Ref : YP5515T

RE: Estimate Repair Cost for Vehicle No PA9134T

Traffic Accident on 15.10.2019 Involving PA9134T & YP5515T at Junction of Yishun Ave 8 & Canberra Way

S/N	Quantity	Particular	Unit Price	Amount S\$
1	1	Front Windscreen / OR	5,000.00	5,000.00
2	1	Front RHS Safety Glass / OR	850.00	850.00
3	1	Front RHS Corner Panel X R	650.00	650.00
4	1	Front RHS Drip Moulding / BT	650.00	650.00
				7,150.00
				(715.00)
				6,435.00
				Less : 10% trade discount
				Net Item:-
6	12	Sealant / NC	40.00	480.00
7	1	Advertisement		500.00
				Labour Charges :-
				To remove damaged front windscreen glass & refit new.
				800.00
				To transfer driver window to new safety glass. To remove damaged safety glass & refit new.
				350.00
				To knock/straighten all necessary parts including repairing and changing of all damaged parts and align same.
				950.00
				To putty and spray painting on front rhs corner panel and all affected accident parts.
				600.00
				Total S\$:
				10,115.00
				GST 7% S\$:
				708.05
				Amount Due S\$
				10,823.05

Note : This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress.

Yours Sincerely,

[Signature]

Poh Yew Leong
Workshop Supervisor



P- 4410
L- 2390
6710
LIS- 5368
= 5350

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2019		17 Oct 2019 14:17 Edit Adj Rpt	S\$5,350.00 Edit Estimates	S\$5,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	HUI LEONG BUS TRANSPORT SERVICES, Co. Reg. No.: 53151728D		
Vehicle Reg. No.:	PA9134T	Date of Loss:	15/10/2019 21:00 - :59 [116 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204893C02	Policy/Cover Note No.:	DMCVSN17111719022
Vehicle Reg. No. (Insured):	YP5515T	Policy No. (Claimant):	D19MTSCBU000030
		Excess:	S\$550.00
Repairer:	Lexbuild Auto & Trading Pte Ltd (HQ) 74 Sungei Kadut Street 1, 729374 Sungei Kadut - Tel: 63623393		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 29/10/2019]		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






























***PA9134T (SNM19D204893C02)**
[YP5515T]























TP

HUI LEONG BUS TRANSPORT SERVICES
Oct 15 2019 9:00PM

[-]


Lexbuild Auto & Trading Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 12:17	Video - Accident [Linked Accident Report Documents]	 Load MP4	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	16/10/19 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	16/10/19 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	16/10/19 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	16/10/19 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	16/10/19 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/01/20 09:00	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
24	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/01/20 09:00	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
31	17/01/20 09:00	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
32	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/01/20 09:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
43	17/01/20 09:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/10/19 14:21	PRS - PA9134T	 Load PDF	
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 13:16	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 12:17	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
1	06/12/19 18:59	Accident Statement	 Load HTM	
2	06/12/19 19:00	Accident Statement	 Load HTM	
3	06/12/19 19:01	Accident Statement	 Load HTM	
4	06/12/19 19:03	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 12:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/10/19 12:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/10/19 12:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/10/19 12:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/10/19 12:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/10/19 12:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	Lexbuild Auto & Trading Pte Ltd (HQ)		Thumbnail Print
1	16/10/19 13:16	Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018349/EYF3S2
Date: 31/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN17111719022
Claimant Vehicle No: PA9134T Insured Vehicle No: YP5515T
Date of Loss: 15/10/2019 Nature of Claim: TP Claim No: SNM19D204893C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA9134T Engine No: ISBE425021877167
Make & Model: FOTON BJ6940, 6.7 D (M) Chassis No: LVCB3RDB69M001402
Reg. Date: 21/01/2010 (Man. Year: 2009) Odometer: 247267 km
Colour: Multi-colour
Engine Capacity: 6700 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)
Front Left Side: ANNAITE 5 mm Rear Left Side: ANNAITE 5/5 mm
Front Right Side: ANNAITE 5 mm Rear Right Side: ANNAITE 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,415.00	5,010.00	2,405.00	32.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,700.00	1,000.00	37.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,115.00	6,710.00	3,405.00	33.66
Approved Total (Overridden) (S\$)		5,350.00		
(S\$)	10,115.00	5,350.00	4,765.00	47.11
+ GST 7.00/7.00% (S\$)	708.05	374.50	333.55	47.11
Nett Amount (S\$)	10,823.05	5,724.50	5,098.55	47.11

INSPECTION

Date of Assignment: 17/10/2019
Date Inspected: 17/10/2019 Inspected At: Lexbuild Auto & Trading Pte Ltd (HQ)
74 Sungei Kadut Street 1
Singapore 729374
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2020)	
Parts:	N/A	FOTON BJ6940 6.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9134T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Broken	5,000.00 FL	*3,800.00 FL
2	1		*FRONT RHS SAFETY GLASS	Broken	850.00 FL	*550.00 FL
3	1		*FRONT RHS CORNER PANEL	Repair	650.00 FL	*- FL
4	1		*FRONT RHS DRIP MOULDING	Bent	650.00 FL	*550.00 FL
5	1		*SEALANT	Necessary	480.00 FS	*300.00 FS
			12pcs			
6	1		*ADVERTISEMENT	Necessary	500.00 FS	*300.00 FS
F=Franchise part, S=SpcNett, L=ListItemDisc.						
Sub Total (\$\$)					8,130.00	5,500.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					715.00	490.00
Total Parts (\$\$)					7,415.00	5,010.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED FRONT WINDSCREEN GLASS & REFIT NEW.	New	800.00	600.00
2	TO TRANSFER DRIVER WINDOW TO NEW SAFETY GLASS. TO REMOVE DAMAGED SAFETY GLASS & REFIT NEW.	New	350.00	250.00
3	TO KNOCK / STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME.	New	950.00	500.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT RHS CORNER PANEL AND ALL AFFECTED ACCIDENT PARTS.	New	600.00	350.00
Gross Labour Cost (S\$)			2,700.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >