

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5850U**AAD1910-119**

Not Authorized
11 Sep 8 2001

Vehicle No.:

Chassis No.:

Vehicle Make:

16 OCT 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5850U

VF1ABL15AUC280925

RENAULT

LATITUDE

14.10.19

AIG

11/12/2014

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH
28	1	BOOT HINGE LH

LIST

\$	<i>Avicomp</i>	561.70	✓
\$	<i>Da/Di</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	16.60	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>CM</i>	16.60	✓
\$	<i>BA</i>	547.80	✓
\$	<i>R</i>	114.50	} X
\$	<i>R</i>	100.90	
\$	<i>R</i>	745.80	
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	313.10	
\$	<i>R</i>	401.40	
\$	<i>SL</i>	401.40	
\$	<i>R</i>	401.40	
\$	<i>R</i>	1,677.20	
\$	<i>SL</i>	344.70	
\$	<i>SL</i>	178.20	
\$	<i>SL</i>	277.70	
\$	<i>SL</i>	277.70	
\$	<i>na</i>	82.40	
\$	<i>na</i>	95.80	
\$	<i>SL</i>	145.10	
\$	<i>SL</i>	145.10	
\$	<i>R</i>	254.20	

Trans-cab Auto Services Pte Ltd**AAD1910-119**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5850U

29	1	BOOT HINGE RH	\$	R	253.80	}	X
30	1	BOOT INNER TRIM BOARD	\$	Sh	611.00		
31	1	BOOT SWITCH	\$	R	113.00		
32	1	BOOT LOCK	\$	R	246.60		
33	1	BOOT LOCK CATCH	\$	R	41.70		
34	1	EXHAUST CAP REAR	\$	Sh	125.40		
TOTAL			\$		9,682.26		
10%			\$		968.23		
			\$		8,714.03		

Special Nett

Special Nett					Short	Good
1	1SET	PARKING AID	\$		700.00	
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	1	EXHAUST MOUNTING REAR	\$	Sh	16.00	
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
14	1	WINDSCREEN MOULDING	\$	na	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
16	1	BOOT INNER TRIM CLIP	\$	na	45.00	
17	1SET	BOOT FINISHER CLIP	\$	na	24.20	
18	1	TAILLAMP CLIP LH	\$	na	5.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
20	1	Rear Bumper Protector	\$	na	100.00	Good
TOTAL			\$	1,482.20		
TOTAL PARTS			\$	10,196.23		

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ na 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1910-119**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5850U

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	10/
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	200/
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	220/
To repair and realign rear exhaust pipe.	\$	4 170.00	X

TOTAL \$ 14,720.00**Over All Total \$ 24,916.23****LUMP SUM (REPAIR DAY)****20 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: