

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST1900344
 Date: 16 Oct 2019
 Veh Reg No: SFW5977G
 Make/Model: VOLKSWAGEN
 SCIROCCO 1.4 AT TSI
 Chasis No: WWZZZ13Z9V032636
 Reg. Date: 15/06/2009
 Your Ref No: SLX1353G

Claim Type: Third Party
 Accident Date: 12/10/2019
 TP Veh Reg No: SLX1353G

Jia Le

Estimate Repair Cost to Vehicle No :SFW5977G

Quantity	Description	List Price	Amount
		SS	SS
1	1 PC BONNET <i>Dented</i>	1,700.71	1,700.71 1199
2	1 PC BONNET EMBLEM <i>new</i>	69.20	69.20 ✓
3	1 PC FRT FENDER LH <i>Dislod</i>	888.96	888.96 ✓
4	1 PC FRT FENDER COWLING LH <i>Missing</i>	230.71	230.71 ✓
5	1 PC HEADLAMP LH <i>crushed</i>	899.79	899.79 ✓
6	1 PC HEADLAMP PANEL <i>new</i>	123.71	123.71 ✓
7	1 PC FRT BUMPER <i>Dislod</i>	1,400.90	1,400.90 1288
8	1 PC FRT BUMPER REINFORCEMENT <i>new</i>	689.89	689.89 ✓
9	1 PC FRT BUMPER SPONGE	199.70	199.70 ✓
10	2 PCS FRT BUMPER SIDE RETAINER <i>RH part</i>	98.20	98.20 49.10
11	1 PC FRT BUMPER GRILLE <i>crushed</i>	300.93	300.93 ✓
12	1 PC FRT FOG LAMP LH <i>crushed</i>	200.97	200.97 ✓
13	1 PC FRT FOG LAMP COVER LH <i>new</i>	189.79	189.79 ✓
14	1 PC FRT LH SIGNAL LAMP <i>crushed</i>	165.80	165.80 ✓
15	1 PC FRT BUMPER LOWER GARNISH <i>behind</i>	244.60	244.60 ✓
16	1 PC FRT GRILLE <i>crushed</i>	300.87	300.87 ✓
17	1 PC FRT GRILLE TOP BRACKET <i>new</i>	89.40	89.40 ✓
18	1 PC FRT GRILLE TOP INNER BRACKET <i>crushed</i>	199.60	199.60 ✓
19	1 PC FRT SUPPORT PANEL <i>crushed</i>	1,500.93	1,500.93 1055
20	2 PCS FRT SUPPORT PANEL SIDE GARNISH <i>behind</i>	97.80	97.80 ✓
21	1 PC AIR CONDENSER <i>Dented</i>	670.00	670.00 ✓
22	1 PC RADIATOR <i>Dented</i>	480.00	480.00 ✓
23	1 PC AIRCON FAN	66.90	66.90 ✓
24	1 PC AIRCON FAN MOTOR <i>new</i>	499.60	499.60 ✓
25	1 PC RADIATOR FAN	78.90	78.90 ✓
26	1 PC RADIATOR FAN MOTOR <i>new</i>	386.70	386.70 ✓
27	1 PC FAN COWLING	274.90	274.90 ✓
28	1 PC FRT DOOR LH <i>Dented</i>	2,139.67	2,139.67 1575
29	2 PCS FRT DOOR HINGE LH <i>new</i>	138.84	138.84 ✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangear@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST1900344
 Date: 16 Oct 2019
 Veh Reg No: SFW5977G
 Make/Model: VOLKSWAGEN
 SCIROCCO 1.4 AT TSI
 Chasis No: WWZZZ13Z9V032636
 Reg. Date: 15/06/2009
 Your Ref No: SLX1353G

Claim Type: Third Party
 Accident Date: 12/10/2019
 TP Veh Reg No: SLX1353G

Estimate Repair Cost to Vehicle No :SFW5977G

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	1 PC FRT DOOR CHECK LH. <i>Not Ne</i>	128.50	*
31	1 PC FRT DOOR RUBBER LH <i>ne</i>	188.63	✓
32	1 PC FRT DOOR PROTECTOR LH <i>cut</i>	193.72	✓
33	1 PC FRT LH SIDE SKIRT <i>cut Del'd</i>	699.10	✓
34	1 PC FRT LH SIDE SKIRT LOWER GARNISH <i>cut</i>	224.90	✓
35	1 PC FRT SHOCK ABSORBER MOUNTING LH <i>Repl</i>	199.70	✓
36	1 PC FRT LOWER ARM LH <i>Best</i>	500.91	✓
37	1 PC FRT LOWER ARM BALL JOINT LH <i>Best</i>	197.60	✓
38	1 PC FRT LOWER BRACKET LH <i>Repl'd</i>	398.62	✓
39	1 PC FRT KNUCKLE ARM LH <i>Repl</i>	700.71	✓
40	1 PC FRT WHEEL HUB AND BEARING <i>Repl</i>	689.98	✓
41	1 PC FRT DRIVE SHAFT LH <i>Best</i>	2,339.97	✓ 2016.
42	1 PC FRT BRAKE ROTOR LH <i>re Not Ne</i>	380.98	*
43	1 PC ANTI ROLL BAR <i>Best</i>	500.71	✓
44	1 PC ANTI ROLL BAR LINKAGE <i>Best</i>	112.80	✓
45	1 PC FRT CROSSMEMBER <i>Best</i>	1,770.10	✓
46	1 PC FRT CROSSMEMBER BRACKET LH <i>Damaged.</i>	487.90	✓
47	1 PC STEERING RACK & PINION <i>Base</i>	4,200.71	✓ 2650.
48	1 PC FLOORBOARD PANEL UNDER <i>Damaged.</i>	394.30	✓
49	1 PC REAR LOWER ARM LH <i>Best</i>	497.00	✓
50	1 PC REAR TOP ARM LH <i>Best</i>	398.40	✓
51	1 PC REAR KNUCKLE ARM LH <i>Repl</i>	678.10	✓
52	1 PC REAR WHEEL HUB LH <i>Repl.</i>	426.40	✓
53	1 PC REAR TRAILING ARM LH <i>Best</i>	548.90	✓
54	1 PC FRT DASHBOARD <i>torn</i>	4,900.71	✓ 3372
55	1 PC FRT STEERING AIRBAG	3,600.70	✓ 3032
56	1 PC FRT PASSENGER STEERING AIR BAG <i>} Activated</i>	3,899.70	✓ 2164
57	1 PC FRT AIRBAG CONTROL UNIT <i>} Activated</i>	1,477.66	✓ 748
58	1 PC FRT STEERING LOCK SENSOR	200.75	✓
59	1 PC FRT SEATBELT	800.97	✓ 658
60	1 PC FRT PASSENGER SEAT BELT <i>} Activated</i>	800.97	✓ 658
	<i>Rear LH Stray Arm Best</i>		303 ✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST1900344
 Date: 16 Oct 2019
 Veh Reg No: SFW5977G
 Make/Model: VOLKSWAGEN
 SCIROCCO 1.4 AT TSI
 Chasis No: WWZZZ13Z9V032636
 Reg. Date: 15/06/2009
 Your Ref No: SLX1353G

Claim Type: Third Party
 Accident Date: 12/10/2019
 TP Veh Reg No: SLX1353G

Estimate Repair Cost to Vehicle No :SFW5977G

Quantity	Description	List Price	Amount
		SS	SS
		46.868.07	
		Less 10%	42.181.26
		35725.35	
		32152.81	
	Special Net		
61	1 SET FRT FENDER COWLING CLIPS LH <i>Ne</i>	48.00	30
62	1 SET FRT BUMPER GRILLE CLIPS <i>Ne</i>	40.00	20
63	1 SET FRT BUMPER CLIPS <i>Ne</i>	48.00	30
64	1 SET FRT LH SIDE SKIRT CLIPS <i>Ne</i>	40.00	✓
65	1 PC FRT SOUND PROOF SEAL PROTECTOR <i>Ne</i>	1,000.00	300
66	1 PC FRT REAR SPORTS RIM LH <i>ut</i>	1,500.00	600
67	1 PC FRT TYRE LH <i>Resolved</i>	650.00	380
68	1 PC FRT SHOCK ABSORBER LH <i>Best</i>	500.00	400
69	1 SET FLOORBOARD PANEL UNDER CLIPS <i>Ne</i>	40.00	✓
70	1 PC REAR SPORTS RIM LH <i>ut</i>	1,500.00	600
71	1 PC REAR TYRE LH <i>ut</i>	650.00	+
72	1 PC REAR SHOCK ABSORBER LH <i>Best</i>	450.00	✓
	<i>Rear RH Sport Rim ut 1500 600(SW)</i>	6,466.00	6,466.00
	Labour		
73	1 TOWING	100.00	60 ✓
74	1 TO CHECK WIRING	100.00	30
75	1 TO REMOVE AND REFIT DASHBOARD	480.00	220
76	1 TO REMOVE AND REFIT ENGINE	800.00	+
77	1 TO REMOVE AND REFIT UNDERCARRIAGE (FRONT)	700.00	300
78	1 TO CHECK WHEEL ALIGNMENT	120.00	80
79	1 TO REMOVE AND REFIT UNDERCARRIAGE (REAR)	450.00	? 220
80	1 TO SPRAY UNDERSEAL	150.00	60
81	1 TO SPRAY PAINTING	1,800.00	1400
82	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,400.00	1400
83	1 TO REMOVE AND REFIT DOOR GLASS	150.00	80
	<i>To remove and refit auto gearbox</i>	900	600

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900344
Date: 16 Oct 2019
Veh Reg No: SFW5977G
Make/Model: VOLKSWAGEN
SCIROCCO 1.4 AT TSI
Chasis No: WVVZZZ13Z9V032636
Reg. Date: 15/06/2009
Your Ref No: SLX1353G

Claim Type: Third Party
Accident Date: 12/10/2019
TP Veh Reg No: SLX1353G


Estimate Repair Cost to Vehicle No :SFW5977G

Quantity	Description	List Price	Amount
84	1 TO REMOVE AND REFIX AIRBAG	750.00 380	SS
85	1 TO PROGRAM AND RESET	400.00 200	SS
		8,400.00	8,400.00
		Total	SS 57,047.26
		Add GST @ 7%	3,993.31
		Total Amount Payable	SS 61,040.57

TOTAL: SINGAPORE DOLLAR SIXTY ONE THOUSAND FORTY AND CENTS FIFTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Adrian King
L/s 16/10/19.

Supplementary : 3627.84

total : 44640.65

L/s : 34.8K (Nett Value)

28 Days

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

Supplementary

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST1900344
 Date: 23 Dec 2019
 Veh Reg No: SFW5977G
 Make/Model: VOLKSWAGEN
 SCIROCCO 1.4 AT TSI
 Chasis No: WVWZZZ13Z9V032636
 Reg. Date: 15/06/2009
 Your Ref No: SLX1353G

Claim Type: Third Party
 Accident Date: 12/10/2019
 TP Veh Reg No: SLX1353G

Estimate Repair Cost to Vehicle No :SFW5977G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
	List Price		
1	1 PC AUTO GEARBOX ASSY <i>Cracked.</i>	16,360.90	<i>2000.</i>
2	1 PC FRT INTERCOOLER <i>Dented</i>	697.60	✓
		17,058.50	
	Less 10%	1,705.85	15,352.65
	Total		S\$ 15,352.65
	GST Amount		S\$ 1,074.69
	Total Amount Payable		<u>S\$ 16,427.34</u>


697.60

627.84

S.N: 3000

Supplementary: 3627.84

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE