

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 16/10/2019

TP Veh Reg No: SMD8101P

Estimate No: ES1992143/AMK

Date: 17 Oct 2019

Policy No: 5031126114-11 DC

Veh Reg No: SLF4200P

Make/Model: NISSAN SUNNY 1.6EX

Chassis No: JN1CFAN16Z0111261

Engine No: QG16428157

Reg. Date: 13/09/2008

Estimate Repair Cost to Vehicle No :SLF4200P

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 REAR BUMPER	502.80	1 PC	502.80	✓
2 REAR BUMPER SPONGE	155.60	1 PC	155.60	✓
3 REAR BUMPER MOULDING	141.20	1 PC	141.20	✓
4 REAR BUMPER SIDE RETAINER	36.90	2 PC	73.80	✓
5 REAR BUMPER CORNER RETAINER	40.90	2 PC	81.80	✓
6 REAR BUMPER CLIP	5.00	6 PC	30.00	✓
7 REAR BOOT	754.80	1 PC	754.80	✓
8 REAR BOOT INNER LOCK	60.00	1 PC	60.00	✓
9 REAR BOOT INNER RUBBER	93.00	1 PC	93.00	5080
10 REAR BOOT LOGO	55.10	1 PC	55.10	✓
11 REAR BOOT EMBLEM 'SUNNY'	77.40	1 PC	77.40	✓
12 REAR BOOT EMBLEM 'EX SALOON'	116.70	1 PC	116.70	✓
13 REAR BOOT LOWER MOULDING	96.00	1 PC	96.00	✓
14 REAR BOOT TOP MOULDING	386.70	1 PC	386.70	X
15 REAR BOOT HINGE	243.40	2 PC	486.80	X
16 TAILLAMP	385.50	2 PC	771.00	✓
17 REAR END PANEL	369.20	1 PC	369.20	✓
18 REAR END PANEL INNER TOP GARNISH	76.60	1 PC	76.60	✓
19 REAR END PANEL INNER CENTRE GARNISH	150.90	1 PC	150.90	✓
20 REAR END PANEL INNER TOP GARNISH CLIP	5.00	4 PC	20.00	✓
21 REAR SPARE TYRE COMPARTMENT PANEL	847.10	1 PC	847.10	?
22 REAR SPARE TYRE INNER TOP BOARD	182.20	1 PC	182.20	?
23 REAR RH FENDER INNER TRIM	233.90	1 PC	233.90	?
			5,762.60	
	Less 10%		576.26	5,186.34
Special Net				
24 REAR END PANEL SEALANT	40.00	1 PC	40.00	3000
			40.00	40.00
Labour				
25 REMOVE & REFIX REAR BUMPER, REAR BOOT & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE PANEL; KNOCKING & REPAIR REAR FENDERS, CHASSIS FRAMES & REALIGN THE SAME	1,400.00	1 LA	1,400.00	1000
26 PUTTY & RESPRAY REAR BUMPER, REAR BOOT, BOTH FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL, CHASSIS FRAMES & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
27 REMOVE & REFIX EXHAUST & REALIGN THE SAME	60.00	1 LA	60.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 16/10/2019
TP Veh Reg No: SMD8101P

Estimate No: ES1992143/AMK
Date: 17 Oct 2019
Policy No: 5031126114-11 DC
Veh Reg No: SLF4200P
Make/Model: NISSAN SUNNY 1.6EX
Chassis No: JN1CFAN16Z0111261
Engine No: QG16428157
Reg. Date: 13/09/2008

Estimate Repair Cost to Vehicle No :SLF4200P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
28 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	100.00	1 LA	100.00 ✓	
29 RUSTPROOFING	120.00	1 LA	120.00 601	
			2,680.00	2,680.00
			Total	S\$ 7,906.34
			Add GST @ 7%	553.44
			Total Amount Payable	<u><u>S\$ 8,459.78</u></u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: