

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP AXA.
Xiao Tony,

21 October 2019

QUOTATION FOR ACCIDENT REPAIR OF SJQ7918Z SUZUKI SWIFT

THIRD PARTY INSURER: AXA

S/No.	Parts	Qty	Amount (\$)
1.	Rear door RH <i>dent</i>	1	\$ 695.10 ✓
2.	Rear door glass moulding LH <i>green</i>	1	\$ 85.70 +
3.	Rear door inner trimboard LH	1	\$ 368.30 +
4.	Rear fender LH <i>Rep's</i>	1	\$ 520.40 +
5.	Rear fender inner shield LH <i>new</i>	1	\$ 91.30 +
6.	Rear knuckle bearing LH <i>new</i>	1	\$ 89.40 +
7.	Rocket panel side skirt LH <i>cut</i>	1	\$ 134.70 ✓

Subtotal before discount \$ 1984.915
Discount 15% \$ 297.73
Subtotal 1 \$ 1687.16

S/Nett.	Parts	Qty	Amount (\$)
1.	Rear sport rim LH <i>cut</i>	1	\$ 350 ✓
2.	Rear tyre LH 17" <i>cut</i>	1	\$ 280 <i>200</i>
2.	Rear fender inner shield clip LH <i>new</i>	1	\$ 30 +
4.	Rocket panel side skirt clip LH <i>new</i>	1	\$ 30 ✓

Subtotal 2 \$ 690

Labour

To check & reconnect electrical wiring	\$ 50 30
To remove & install rear left door components.	\$ 120 80
To remove & install side compartment trims, side garnish to facilitate repair	1750 \$ 150 60
To conduct computerised wheel alignment	\$ 120 80
To remove & install rear undercarriage	\$ 120 +

To straighten, repair, realign on affected area and replace damaged parts

\$ 1000 ~~400~~

To prime, sand, block and spray painting

\$ 1000 ~~600~~

Total Labour Cost

\$ 2560

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party Total Cost Of Repairs (Total cost of parts + Total labour cost) \$ 4,937.16
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2535.33
h/s: 2k

Adrian Lim
h/c 21/10/18
050 days