

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GT919L TOYOTA HIACE

DATE 15/10/2019

No	Qty	PARTICULAR	AMOUNT S\$
1	1	TAIL GATE	2,062.00 ✓
2	1	TAIL GATE PILLAR RH	425.00 X
3	1	TAIL GATE TRIM BOARD	428.00 X
4	1	TAIL GATE LOCK	509.20 X
5	1	REAR FENDER PANEL RH	1,988.00 X
6	1	TAIL LAMP RH	325.00 X
7	1	TAIL GATE (HIACE) STICKER	125.00 ✓
8	1	TAIL GATE (LOGO) EMBLEM	165.00 ✓
			\$ 6,027.20
		50% LESS 25%	\$ 1,506.80
			\$ 4,520.40

No	Qty	PARTICULAR	SPECIAL NETT	AMOUNT S\$
1	1	REAR WINDSCREEN GLASS SEALANT		90.00 40
2	1	REAR WINDSCREEN GLASS INNER SEAL		135.00 30
3	1	8 PAX STICKER		25.00 10
4	1	70 KM/H STICKER		25.00 10
				\$ 275.00

LABOUR & MISCELLANEOUS:

1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	400	1,400.00
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	400	1,000.00
3	To transfer tail gate components with all necessary attachments	60	250.00
4	To remove, refit rear windscreen glass and water test	120	250.00
		\$	2,900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: