

ASS. REC. BY:

REF: 03/MSG19018363/Kyd3er

Special Instruction:

Assigner: Kenneth

ASSIGNMENT (Office)

From (Person): Winnie chuan

of MSIG

Date/Time: 17/10/19 @ 3:18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

ES84Z

Insured:

SDQ 3128J

at Workshop w/s

Cheng Hoi Motor

Tel:

6755 6142

of

Blk 1019 Yishun Ind. Park A #01-374

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:50pm @ 17/10/19

Person Contacted:

Jine

Vehicle IN/OUT

Date/Time

Action/Instruction

13/10/19 ✓

ES84Z-X

SDQ 3128J-X

21/10/19

Sent Prel. by mail

87484.95 Confirmed (Red \$171-46, 22%)

ASS. REC. BY:

REF: MSG1

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Soon: _____

Consistent? : Yes or No

Est. Repairs: _____

07 days

Res.: Yes or No

Lum Sum: _____

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File parts to

Veh No: ES848Yr Regn: 11.18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyVios E

c.c

1496Colour: M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading: 17770

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2B231-300148643Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 8 mmL/Bal. 6 mmL/Bal. 8 mmD.O.A. 16/10/19D.O.I. 17/10/19

Survey held at _____

Des. of Damages: 015 / Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 FEB 2020

Data/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Data/Time, File Return to?

2)

19/2/20 TypistDays Of Repair: 7Resurvey No. of Trip: 3

Survey Fee:

Transportation:

S + RS. SI

Furnish

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

PIP \$7484-95

150
11
161

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ing Adj/Est	Status
Main	18 Oct 2019 11:59		18 Oct 2019 13:47 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NG SONG HERNG, ID: S1478546I		
Main Claimant:	TAN LIAN WATT, ID: S0734705G		
Vehicle Reg. No.:	ES84Z	Date of Loss:	16/10/2019 15:00 - :59 [10 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 608798	Policy/Cover Note No.:	29077149 (Comprehensive) Coverage: 29/03/2019 - 28/03/2020
Vehicle Reg. No. (Insured):	SDQ3128J	Policy No. (Claimant):	5105794862
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/11/2019]		
Driver/Custodian (Insured):	GOH MUI LING ANGELA (55 / Female), NRIC: S1629262A, Tel: +6591790798 Email:		
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 17/10/19. Liab: unclear, manual assignment to LKK on 17/10/19.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yvonne Wong (LKK Auto)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Tuesday, February 18, 2020 4:06 PM
To: SUR
Subject: Fw: ES84Z DOA:16/10/2019 TP/MSIG

Hi Yvonne,

Please refer below.

Thank you

Rgds
Efeeda
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Kenneth Kong (LKKAuto)
Sent: Monday, November 25, 2019 8:36 AM
To: Efeeda (Cheng Hoe -Yishun)
Subject: RE: ES84Z DOA:16/10/2019 TP/MSIG (EMAIL 1/2)

Repair cost confirmed.

From: Efeeda (Cheng Hoe -Yishun) [mailto:chmotor@singnet.com.sg]
Sent: Thursday, 21 November, 2019 12:25 PM
To: Kenneth Kong (LKKAuto)
Subject: ES84Z DOA:16/10/2019 TP/MSIG (EMAIL 1/2)

Hi Kenneth,

Photos and finalization list as attached.

Please let us have your confirmation on the final sum- **\$7484.95 / 7 DAYS** via reply email.

Thank you

Rgds
Efeeda
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

Nivitha (LKK Auto)

From: Winnie Chua <pingping_chua@sg.msig-asia.com>
Sent: Thursday, 17 October 2019 3:18 PM
To: assignments@lkkauto.com
Cc: chmotor@singnet.com.sg; Crystal Lee; Ong Zi Hui; Helene Phua
Subject: FW: Repair Survey (Single Joint Expert) - ES84Z DOA: 16/10/19 SDQ3128J (MSIG)
Car in workshop, manual assignment.

Manual Assigned

Dear Sir (LKK),

Please refer to the email below and arrange survey for the vehicle. Car is in.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Best Regards

Winnie Chua
Senior Admin Officer, Claims Services (In-House Survey)
Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Thursday, 17 October 2019 2:39 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: Repair Survey (Single Joint Expert) - ES84Z DOA: 16/10/19 SDQ3128J (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]

Sent: Thursday, 17 October, 2019 1:48 PM

To: Winnie Chua <pingping_chua@sg.msig-asia.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: Re: Repair Survey (Single Joint Expert) - ES84Z DOA: 16/10/19 SDQ3128J (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi Winnie,

Veh is in our workshop on 16/10/19.

Kindly assist to arrange survey asap.

Thank you.

Rgds

June Phua

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

From: Cheng Hoe Motor Pte Ltd (Yishun-June)

Sent: Thursday, October 17, 2019 10:01 AM

To: Winnie Chua

Cc: Helene Phua

Subject: Re: Repair Survey (Single Joint Expert) - ES84Z DOA: 16/10/19 SDQ3128J (MSIG)

Good morning,

Our selection as below :-

1) LKK Auto Consultants Pte Ltd

Kindly assist to arrange for survey asap.

Thank you.

Rgds

June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Winnie Chua
Sent: Thursday, October 17, 2019 9:14 AM
To: chmotor@singnet.com.sg
Cc: Helene Phua
Subject: FW: Repair Survey (Single Joint Expert) - ES84Z DOA: 16/10/19 SDQ3128J (MSIG)

Hi,

We refer to your email/faxed dated 16/10/19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors (Appointment is full on 17 & 18/10/19)**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Best Regards

Winnie Chua
Senior Admin Officer, Claims Services (In-House Survey)
Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com





From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]

Sent: Wednesday, 16 October 2019 6:13 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Subject: Repair Survey (Single Joint Expert) - ES84Z

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir,

OUR CLIENT : ES84Z

D
OA-
:
16.10.19 @1455hrs

YR
INSURED : SDQ3128J

Kindly provide us your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 21 Oct 2019

Preliminary Advice

Insured Vehicle No	: SDQ3128J	Accident Date	: 16/10/2019
TP Vehicle No	: ES84Z	Assignment Date	: 18/10/2019
Make	: TOYOTA VIOS	Est. Duration of Repair	: 7.00
Date of Inspection	: 17/10/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,192.36
Revised Amount	:S\$	5,900.96
Check Items (Estimated)	:S\$	1,792.60
Total	:S\$	7,693.56

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	705G
Vehicle Details	
Vehicle No.:	ES84Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	2NR5272579
Chassis No.:	MR2B23F3001148643
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,390.00
Original Registration Date:	28 Nov 2018
First Registration Date:	28 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$13,390.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2028
PARF Rebate Amount:	\$10,042.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,000.00
COE Rebate Amount:	\$22,400.00
Total Rebate Amount:	\$32,442.00

The information contained herein is correct as at 16 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2019 17:39
Date Of Accident	16/10/2019 14:55
Exact Location Of Accident	T-JUNCTION OF BT BATOK ST 31 & BT BATOK WEST AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	ES84Z
Insured/Policyholder	
Name Of Registered Owner	TAN LIAN WATT
NRIC No	S0734705G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98412345
Alternative Phone No	OTHERS-98412345

Vehicle Particulars

Manufacturer	TOYOTA
Model	LIGHTVIO 1.5 E (AUTO)
Exact Purpose for which vehicle was being used at time of accident	TUITION USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105794862
Cover Note Number	28/11/2018- 27/11/2019

Driver

Name of Driver	CLARA MICHELLE TAN HWEI SIAN
NRIC No	T0016121C
Date Of Birth	14/05/2000
Occupation	INDOOR
Date Of Driving Pass	16/10/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-98412345
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	179 HILLCREST ROAD
Postcode	289062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LEARNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : INSTRUCTOR - TAN LIAN WATT GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving m/car ES84Z and my instructor Mr. Tan was sitting beside me at the passenger seat. Our direction was green light and I proceeded to make a right turn when suddenly car B beat the red light and hit onto the right portion of our car. The accident was captured in our car in-built camera. No one was injured.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	EMAIL DIRECT TO NTUC
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDQ3128J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH MUI LING ANGELA
NRIC/Passport Number	S1629262A
Contact Number	91790798
Address	
Postcode	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT




Bt. Batok St. 31

I was driving m/car ES84Z and my instructor Mr. Tan was sitting beside me at the passenger seat. Our direction was light green and I proceeded to make a right turn when suddenly car B beat the red light and hit onto the right portion of our car. The accident was captured in our car in-built camera. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

<p></p> <p>Policyholder's Signature</p> <p>Date & Time:</p>	<p></p> <p>Driver's Signature (If driver is not the policyholder)</p> <p>Date & Time:</p>	<p> 16/10/19</p> <p>Reporting Centre Personnel's Signature</p> <p>Name: (YS)</p> <p>NRIC/FIN No.:</p>
<p>GRANIC Motor Insurance S/S () Claim Own Policy (<input checked="" type="checkbox"/>) Claim Third Party () Reporting Only</p> <p>() Claim OD/TP at other workshop ()</p>		

MT/1067235-001

SKETCH PLAN


VEHICLE NO.: Es 84 Z
INSURER : NTUC
DATE & TIME: 16/10/19 @ 14:55


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

ES84Z
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 16/10/2019

TP Veh Reg No: SDQ3128J

Estimate No: ES1992135/YISHUN

Date: 17 Oct 2019

Policy No: 5105794862

Veh Reg No: ES84Z1

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR2B23F3001148643

Engine No: 2NR5272579

Reg. Date: 28/11/2018

Estimate Repair Cost to Vehicle No :ES84Z.1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	459.00	1 PC	459.00	—
2 FRONT BUMPER RH SIDE RETAINER	95.30	1 PC	95.30	—
3 FRONT BUMPER RH FOG LAMP	248.20	1 PC	248.20	X
4 FRONT BUMPER RH FOG LAMP GARNISH	132.70	1 PC	132.70	✓
5 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
6 RH HEADLAMP	1,144.90	1 PC	1,144.90	✓
7 FRONT RH FENDER	733.60	1 PC	733.60	✓
8 FRONT RH FENDER INNER SHIELD	195.40	1 PC	195.40	✓
9 FRONT RH FENDER INNER SHIELD CLIPS	3.50	8 PCS	28.00	✓
10 FRONT RH DOOR	959.10	1 PC	959.10	✓
11 FRONT RH DOOR FRAME STICKER	65.10	1 SET	65.10	✓
12 FRONT RH SHOCK ABSORBER	378.10	1 PC	378.10	✓
13 FRONT RH KNUCKLE ARM	621.50	1 PC	621.50	✓
14 FRONT RH WHEEL BEARING	544.80	1 PC	544.80	✓
15 FRONT RH SPORT RIM	1,081.85	1 PC	1,081.85	✓ 17484
			6,708.55	
		Less 25%	1,677.14	5,031.41
Special Net				
16 FRONT RH DOOR SUN VISOR	120.00	1 SET	120.00	✓
17 FRONT RH TYRE	185.00	1 PC	185.00	✓ 305.00 X
			305.00	305.00

Labour

- 18 REMOVE & REFIX FRT BUMPER
ASSY,GRILLE,HEADLAMP,FRT RH FENDER,FRT RH SIDE
MIRROR,FRT RH DOOR,TRANSFER DOOR
ATTACHMENT,KNOCK & REPAIR FRT RH FENDER INNER
PANEL & REALIGN THE SAME

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey vehicle for spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 16/10/2019

TP Veh Reg No: SDQ3128J

Estimate No: ES1992135/YISHUN

Date: 17 Oct 2019

Policy No: 5105794862

Veh Reg No: ES84Z.1

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR2B23F3001148643

Engine No: 2NR5272579

Reg. Date: 28/11/2018

Estimate Repair Cost to Vehicle No :ES84Z.1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
19 REMOVE & REFIX FRT RH UNDERCARRIAGE,CHECK STEERING RACK & DRIVE SHAFT	180.00	1 LA	180.00	1601
20 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
21 REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRAL LOCKING	60.00	1 LA	60.00	✓
22 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER,FENDER INNER PANEL,FRT RH DOOR,REAR RH DOOR,BONNET	980.00	1 LA	980.00	8801
23 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,320.00	2,320.00
Total				S\$ 7,656.41
Add GST @ 7%				535.95
Total Amount Payable				S\$ 8,192.36

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

8196-10

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2019 11:59		18 Oct 2019 13:47 Edit Adj Rpt	S\$7,484.95 Edit Estimates	S\$7,484.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	NG SONG HERNG , ID: S14785461								
Main Claimant:	TAN LIAN WATT , ID: S0734705G								
Vehicle Reg. No.:	ES84Z	Date of Loss:	16/10/2019 15:00 - :59 [10 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608798	Policy/Cover Note No.:	29077149 (Comprehensive) Coverage: 29/03/2019 - 28/03/2020						
Vehicle Reg. No. (Insured):	SDQ3128J	Policy No. (Claimant):	S105794862						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/11/2019]								
Driver/Custodian (Insured):	GOH MUI LING ANGELA (55 / Female), NRIC: S1629262A, Tel: +6591790798 Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 17/10/19. Liab: unclear, manual assignment to LKK on 17/10/19.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (07/02/2020): Re: Alert: Im. Report (ES84Z) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*ES84Z (608798)

[SDQ3128J]

TP





















TAN LIAN WATT

Oct 16 2019 3:00PM







[NG SONG HERNG]

Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	24/10/19 13:16	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Video - AccidentTP	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	21/10/19 17:45	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	16/10/19 18:26	Cheng Hoe Motor Pte Ltd (Yishun) Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	16/10/19 18:26	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	16/10/19 18:26	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
4	16/10/19 18:26	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
5	16/10/19 18:26	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
6	16/10/19 18:26	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
7	16/10/19 18:26	THIRD PARTY CAR <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
8	16/10/19 18:26	THIRD PARTY CAR <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
2	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
3	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
4	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
5	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
6	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
7	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
8	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
9	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
10	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
11	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
12	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
13	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
14	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
15	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
16	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
17	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
18	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
19	21/10/19 17:46	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
20	21/10/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/10/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/10/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/10/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/10/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/10/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	19/02/20 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/10/19 12:51	email to workshop	 Load PDF	
2	18/10/19 12:53	email from workshop	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	18/10/19 13:46	Survey Request - Manual Assigned	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/12/19 19:01	Accident Statement	 Load HTM	
2	06/12/19 19:01	Accident Statement	 Load HTM	
3	06/12/19 19:02	Accident Statement	 Load HTM	
4	06/12/19 19:03	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	16/10/19 18:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/10/19 18:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/10/19 18:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/10/19 18:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/10/19 18:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/10/19 18:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	16/10/19 18:26	THIRD PARTY CAR	 Load JPG	<input checked="" type="checkbox"/>
8	16/10/19 18:26	THIRD PARTY CAR	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	16/10/19 18:25	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	16/10/19 18:25	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018363/KYD3E2

Date: 19/02/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29077149

Claimant Vehicle No : ES84Z

Insured Vehicle No : SDQ3128J

Date of Loss: 16/10/2019

Nature of Claim: TP

Claim No: 608798

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: ES84Z

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 2NR5272579

Reg. Date: 28/11/2018 (Man. Year: 2018)

Chassis No: MR2B23F3001148643

Colour: Metallic Pearl White

Odometer: 17770 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,836.10	5,464.95	371.15	6.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	2,020.00	300.00	12.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,156.10	7,484.95	671.15	8.23
+ GST 7.00/7.00% (S\$)	570.93	523.95	46.98	8.23
Nett Amount (S\$)	8,727.03	8,008.90	718.13	8.23

INSPECTION

Date of Assignment: 18/10/2019

Date Inspected: 17/10/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2020)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for ES84Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	459.00 FL	*459.00 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	95.30 FL	*95.30 FL
3	1		*FRONT BUMPER RH FOG LAMP	Serviceable	248.20 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP GARNISH	Cut	132.70 FL	*132.70 FL
5	8		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
6	1		*RH HEADLAMP	Cut / Mtg Distorted	1,144.90 FL	*1,144.90 FL
7	1		*FRONT RH FENDER	Bent	733.60 FL	*733.60 FL
8	1		*FRONT RH FENDER INNER SHIELD	Cracked	195.40 FL	*195.40 FL
9	8		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	28.00 FL	*28.00 FL
10	1		*FRONT RH DOOR	Bent	959.10 FL	*959.10 FL
11	1		*SET FRONT RH DOOR FRAME STICKER	Necessary	65.10 FL	*65.10 FL
12	1		*FRONT RH SHOCK ABSORBER	Bent	378.10 FL	*378.10 FL
13	1		*FRONT RH KNUCKLE ARM	Bent	621.50 FL	*621.50 FL
14	1		*FRONT RH WHEEL BEARING	Necessary	544.80 FL	*544.80 FL
15	1		*FRONT RH SPORT RIM	Dented	1,748.10 FL	*1,748.10 FL
16	1		*SET FRONT RH DOOR SUN VISOR	Necessary	120.00 FS	*120.00 FS
17	1		*FRONT RH TYRE	Serviceable	185.00 FS	*- FS
					Sub Total (\$\$)	7,679.80 7,246.60
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,843.70 1,781.65
					Total Parts (\$\$)	5,836.10 5,464.95

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, HEADLAMP, FRT RH FENDER, FRT RH SIDE MIRROR, FRT RH DOOR, TRANSFER DOOR ATTACHMENT, KNOCK & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME	New	980.00	800.00
2	REMOVE & REFIX FRT RH UNDERCARRIAGE, CHECK STEERING RACK & DRIVE SHAFT	New	180.00	160.00
3	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
4	REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRAL LOCKING	New	60.00	60.00
5	PUTTY & RESPRAY ON FRT BUMPER, FRT RH FENDER, FENDER INNER PANEL, FRT RH DOOR, REAR RH DOOR, BONNET	New	980.00	880.00
6	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			2,320.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >