

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date : 15/10/2019

Reference: CHEVROLET

Make: SONIC

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLA397H

CHASSIS NO.: KL1TA69FJGB564286

ENGINE NO.: A14XER153110354

Name of insured : CHEN ZHENG

Date of accident: 03/10/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RR BOOTLID	\$ 1,606.00
2	1	RR BOOTLID CHROME MLDG	\$ 362.00
3	1	RR BOOTLID NUMBER PLATE LAMP	\$ 162.00
4	1	RR BOOTLID LOGO	\$ 93.00
5	1	RR BOOTLID CHEVROLET EMBLEM	\$ 81.00
6	1	RR BOOTLID SONIC EMBLEM	\$ 56.00
7	1	RR BOOTLID LTZ EMBLEM	\$ 43.00
8	1	RR BOOTLID LOCK	\$ 312.00
9	1	RR BOOTLID LOCK STRIKER	\$ 52.00
10	1	RR BOOTLID WHEATHERSTRIP	\$ 236.00
11	1	RR BUMPER	\$ 1,625.00
12	1	RR BUMPER TOW COVER	\$ 86.00
13	1	RR BUMPER TOP CENTRE RETAINER	\$ 193.00
14	1	RR BUMPER SIDE RETAINER RH(inner)	\$ 181.00
15	1	RR BUMPER SIDE RETAINER LH(inner)	\$ 181.00
16	1	RR BUMPER SIDE RETAINER RH(outer)	\$ 175.00
17	1	RR BUMPER SIDE RETAINER LH(outer)	\$ 175.00
18	1	RR BUMPER SPONGE	\$ 268.00
19	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	\$ 423.00
20	2	RR BUMPER REVERSE SENSOR	\$ 430.00
21	4	RR BUMPER REVERSE SENSOR SEAL	\$ 48.00
22	1	RR END PANEL	\$ 650.00
23	1	RR END PANEL TOP GARNISH	\$ 316.00

2878

2590.20

Parts Total: \$ 7,754.00

Less 10%: \$ 775.40

Total : \$ 6,978.60

Labour

Labour Description

No.			Price (SGD)	
1		To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00	300
2		Carry out spray painting on affected area, RR BUMPER, RR BOOTLID, RR END PANEL	\$ 1,000.00	400
3		To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	50
4		Remove and refix interior trim, seat cushion/upholstery, roof lining, seatbelt, etc	\$ 200.00	+
5		To remove and refix reverse sensor and conduct test	\$ 80.00	50
6		To remove and refix reverse camera and conduct test	\$ 80.00	+
7		To conduct transfer of parts from old bootlid to new bootlid	\$ 180.00	+

800

Labour Total : \$ 2,660.00

Others

Other Description

No.			Price (SGD)	
1	10	RR BUMPER CLIP	\$ 40.00	+
2	10	RR FENDER INNER TRIM CLIP	\$ 40.00	+
3	5	RR END PANEL TOP GARNISH CLIP	\$ 20.00	+
4	1	RR NUMBER PLATE	\$ 65.00	+

40.

TOTAL: 165.00

GRAND TOTAL : 9,803.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Eric Tan
HP: 8266 1132 Fax: 68445185

Adrian Lim

P/P 25/11/19.

03 days.

total: 3430.20

CP/P)

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: