

ASS. REC. BY:

REF:

ASM (AxA)

ASSIGNMENT

From:

Date:

17.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKS 6809P

at Workshop m/s

Wei hee motor

of Block 9 Sin ming Industrial Estate #01-32

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1.30p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

856k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

• %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKS 6809P

Yr Regn:

04, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy AIAJ

C.C

1598

Colour:

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

94460

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH104531156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Dun

205/55R16

R:

Pir

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

4

mm

L/Bal.

9

mm

L/Bal.

4

mm

D.O.A.

14/10/19

D.O.I.

17/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015154

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL