

ASS. REC. BY:

REF: CS/AIG/19018372/KS 03

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Maximen

To (Person):

Hor Yinnul

of

AIG

Date/Time: 17/10/2019 @ 8:56am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 5335Y

Insured:

SJK 2722K

at Workshop m/s

Yee Auto Service

Tel:

6457 5768.

of

160 Sin Ming Drive #02-17

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37am 17/10/19

Person Contacted:

Mr. Chan

Vehicle IN/OUT

Date/Time

Action/Instruction

Tehongli

SLG 5335Y-X

SJK 2722K-X

3/2

6/1 Pm @ 2400 email & confirmed

(\$ 4,342.40 Red - 64%)

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

5/26

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 53354

Yr Regn:

09, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Camry

c.c.

1998

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

325882

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRO 53BK 410 700 2025

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

4/10/19

D.O.I.

14/1/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 157

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 13 FEB 2020

Date/Time, File Pass to?

13/02/20

1)

Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

250

Transportation:

Fees:

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

2,400/- 45

PRE-REPAIR INSPECTION REQUEST – SLG5335Y vs SJK2722K (OI) on D.O.A.: 07/10/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Sent: 10/17/2019 8:56:49 AM

Hi,

Please refer to the enclosed request from **BONNIE KWOK LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Wednesday, October 16, 2019 5:40 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; yeeauto pteltd
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJK2722K AND SLG5335Y ON 07/10/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,
ST
--

BONNIE KWOK LLC
Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 15 Oct 2019 at 14:33, Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-10-22 14:33 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com

To: litigation@bonniekwok.com

Cc: Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com

,Aashweenjeetkaur.Mithosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJK2722K AND SLG5335Y ON 07/10/2019

Date: Mon, 14 Oct 2019 06:22:08 +0000

Without Prejudice

Your Reference : SLG5335Y

Our Reference : SJK2722K

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Monday, October 14, 2019 12:34 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] PRI - Acc Inv: SLG 5335 Y & SJK 2722 K ON 7 OCTOBER 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SLG 5335 Y at M/s Yee Auto Pte Ltd, 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722. Contact number 6457 5768.

Regards,
June

BONNIE KWOK LLC
Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

 Virus-free. www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 19:48
Date Of Accident	04/10/2019 16:40
Exact Location Of Accident	ALONG AYE (TUAS) TOWARDS TUAS CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5335Y
Insured/Policyholder	
Name Of Registered Owner	ONG YAT THONG
NRIC No	S1425190A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96874657
Alternative Phone No	OTHERS-96874657

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5112550076
Cover Note Number	

Driver

Name of Driver	ONG YAT THONG
NRIC No	S1425190A
Date Of Birth	08/04/1960
Occupation	INDOOR
Date Of Driving Pass	13/01/1978
Driving Experience	41 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96874657
Fax Number	
Contact Number	OTHERS-96874657
Email Address	NOEMAIL

Contact Number

NA

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

(A) SLG53354

(B) SJK 2722K.

Tues Checkpoint

AYE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Police Report No: T/20191006/2037

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191006/2037

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20191006/2037

CONTINUATION OF REPORT

Driver:			
Name	Unknown driver		ID No. NIL
Related Vehicle	SJK2722K (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	ONG YAT THONG		ID No. S1425190A
Related Vehicle	SLG5535Y (Car)		Contact No. 96874657
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 04/10/2019 at around 1640hrs, I was driving my car bearing plate number SLG5535Y along AYE(Tuas). I was queuing for my turn to go through Tuas Checkpoint to enter Malaysia. I was on lane 2. It was a double white line lane. There was another car bearing plate number SJK2722K on my left side trying to squeeze into my lane. I gave way and allowed the car to come into my lane. Suddenly, I noticed the said car had scratches on the rear right side. I went down to make a check on my car and discovered that there were scratches on the left side fender and front bumper. I confronted the driver and tried to settle the matter privately. However, he refused to provide me with his particulars. I have in-car camera installed in my car. Nobody was injured. No damage to government property. I am lodging this report for insurance claim purposes.



YEE AUTO PTE LTD.

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

Estimate No: ES1900166

Date: 14 Jan 2020

Policy No:

Veh Reg No: SLG5335Y

Make/Model: TOYOTA CAMRY 2.0

AUTO ABS AIRBAG

Chassis No: MR053BK4107002025

Engine No: 1AZE008909

Reg. Date: 21/09/2006

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 04/10/2019

TP Veh Reg No: SJK2722K

Estimate Repair Cost to Vehicle No :SLG5335Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT TYRE - LH	300.00	1 PC	300.00	X
2 FRONT WHEEL RIM - LH	550.00	1 PC	550.00	X
			850.00	850.00
Spare Parts				
3 FRONT BUMPER	885.50	1 PC	885.50	2
4 FRONT BUMPER LOWER SPOILER	420.50	1 PC	420.50	2
5 FRONT BUMPER SIDE RETAINER - LH	65.00	1 PC	65.00	✓
6 FRONT BUMPER SIDE RETAINER - RH	65.00	1 PC	65.00	X
7 FRONT FENDER - LH	516.60	1 PC	516.60	✓
8 FRONT FENDER EMBLEM 'VVT'	75.10	1 PC	75.10	✓
9 FRONT FENDER SPLASH SHIELD - LH	154.20	1 PC	154.20	X
10 FRONT FENDER SPLASH SHIELD CLIP	60.00	1 SET	60.00	X
11 FRONT FOG LAMP - LH	285.50	1 PC	285.50	X
12 FRONT FOG LAMP COVER - LH	80.00	1 PC	80.00	X
13 FRONT HEAD LAMP - LH	985.00	1 PC	985.00	2
			3,592.40	3,592.40
Labour				
14 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	400
15 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	600
16 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	30
17 WHEEL ALIGNMENT	120.00	1 T	120.00	X
18 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	20
			2,300.00	2,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary parts must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/10/2019
TP Veh Reg No: SJK2722K


Estimate No: ES1900166
Date: 14 Jan 2020
Policy No:
Veh Reg No: SLG5335Y
Make/Model: TOYOTA CAMRY 2.0
AUTO ABS AIRBAG
Chassis No: MR053BK4107002025
Engine No: 1AZE008909
Reg. Date: 21/09/2006

Estimate Repair Cost to Vehicle No :SLG5335Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 6,742.40
			Add GST @ 7%	310.97
			Total Amount Payable	SS 7,053.37

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FIFTY THREE AND CENTS THIRTY SEVEN ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2019 Edit Reg		17 Oct 2019 00:00 Edit Adj Rpt	S\$2,400.00 Edit Estimates	S\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BEE LING MARIANNE , ID: S8063229J, Tel: +6599999999									
Main Claimant: ONG YAT THONG , ID: S1425190A									
Vehicle Reg. No.:	SLG5335Y	Date of Loss:	04/10/2019 00:00 - :59 [156 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0297793435SG	Policy/Cover Note No.:	1800062656						
Vehicle Reg. No. (Insured):	SJK2722K	Policy No. (Claimant):							
		Excess:							
Repairer: Yee Auto Service () BLK 15, #01-107 SIN MING INDUSTRIAL ESTATE, 575673 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/10/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (05/11/2019): Re: Request To Upload TP GIA Report AIG_SG (18/10/2019): Request To Upload TP GIA Report AIG_SG (18/10/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG5335Y (0297793435SG)**
[SJK2722K]
TP
ONG YAT THONG
Oct 4 2019 12:00AM
[BEE LING MARIANNE]
Yee Auto Service

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/02/20 11:18	General View		Load JPG	
2	13/02/20 11:18	General View		Load JPG	
3	13/02/20 11:18	General View		Load JPG	
4	13/02/20 11:18	General View		Load JPG	
5	13/02/20 11:18	General View		Load JPG	
6	13/02/20 11:18	General View		Load JPG	
7	13/02/20 11:18	General View		Load JPG	
8	13/02/20 11:18	General View		Load JPG	
9	13/02/20 11:18	General View		Load JPG	
10	13/02/20 11:18	General View		Load JPG	
11	13/02/20 11:18	General View		Load JPG	
12	13/02/20 11:18	General View		Load JPG	
13	13/02/20 11:18	General View		Load JPG	
14	13/02/20 11:18	General View		Load JPG	
15	13/02/20 11:18	General View		Load JPG	
16	13/02/20 11:18	Reinspection Photo		Load JPG	
17	13/02/20 11:18	Reinspection Photo		Load JPG	
18	13/02/20 11:18	Reinspection Photo		Load JPG	
19	13/02/20 11:18	Reinspection Photo		Load JPG	
20	13/02/20 11:18	Reinspection Photo		Load JPG	
21	13/02/20 11:18	Reinspection Photo		Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/01/20 16:22	TP GIA REPORT.pdf		Load PDF	
2	15/01/20 16:22	POLICE REPORT.pdf		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19018372/KSD3S2

Date: 14/02/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800062656
Claimant Vehicle No :	SLG5335Y	Insured Vehicle No :	SJK2722K
Date of Loss:	04/10/2019	Nature of Claim:	TP
		Claim No:	0297793435SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG5335Y	Engine No:	1AZE008909
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK4107002025
Reg. Date:	21/09/2006 (Man. Year: 2006)	Odometer:	325682 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,442.40	1,982.74	2,459.66	55.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,050.00	1,250.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,742.40	3,032.74	3,709.66	55.02
Approved Total (Overridden) (\$\$)		2,400.00		
(\$\$)	6,742.40	2,400.00	4,342.40	64.40
+ GST 7.00/7.00% (\$\$)	471.97	168.00	303.97	64.40
Nett Amount (\$\$)	7,214.37	2,568.00	4,646.37	64.40

INSPECTION

Date of Assignment:	17/10/2019	160 SING MING DRIVE# 02-17 SINGAPORE 575722
Date Inspected:	14/01/2020 Inspected At:	Repairer: Yee Auto Service
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	885.50 F	*581.45 FL
2	1		*FRONT BUMPER LOWER SPOILER	Buckled / Deformed	420.50 F	*420.50 FL
3	1		*FRONT BUMPER SIDE RETAINER - LH	Necessary	65.00 F	*65.00 FL
4	1		*FRONT BUMPER SIDE RETAINER - RH	Serviceable	65.00 F	*- FL
5	1		*FRONT FENDER - LH	Bent	516.60 F	*516.60 FL
6	1		*FRONT FENDER EMBLEM VVTI	Necessary	75.10 F	*75.10 FL
7	1		*FRONT FENDER SPLASH SHIELD - LH	Serviceable	154.20 F	*- FL
8	1		*SET FRONT FENDER SPLASH SHIELD CLIP	Not Necessary	60.00 F	*- FL
9	1		*FRONT FOG LAMP - LH	Serviceable	285.50 F	*- FL
10	1		*FRONT FOG LAMP COVER - LH	Serviceable	80.00 F	*- FL
11	1		*FRONT HEAD LAMP - LH	Mtg Cracked	985.00 F	*985.00 FL
12	1		*FRONT TYRE - LH	Serviceable	300.00 FS	*- FS
13	1		*FRONT WHEEL RIM - LH	Serviceable	550.00 FS	*- FS
					Sub Total (S\$)	4,442.40
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	1,982.74

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	New	1,000.00	400.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	New	1,000.00	600.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	New	120.00	30.00
4	WHEEL ALIGNMENT.	New	120.00	0.00
5	TO CHECK WIRING FUNCTIONS.	New	60.00	20.00
Gross Labour Cost (\$\$)			2,300.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >