

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Oct-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1020 U

S/NETT

1 set	Rear bumper clips	X	\$	48.00
1 set	Reverse sensor	X	\$	280.00
1 pc	Rear bumper top protector	X	\$	80.00

Sundry

\$ ~~50.00~~ 20

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ ~~120.00~~ X

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.

\$ ~~500.00~~ 180

To putty and spray painting on rear bumper, rear bumper lower cover

\$ ~~400.00~~ 360
\$ 1,478.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



Kalvin (LKK)

16/10/19

1725h

2 hrs

Us

At the Repair shop