

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Oct-19


ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1020 U

S/NETT

1 set	Rear bumper clips	X "	\$	48.00
1 set	Reverse sensor	X "	\$	280.00
1 pc	Rear bumper top protector	X "	\$	80.00
	Sundry		\$	50.00 2
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 X 1.5
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$	500.00 180
	To putty and spray painting on rear bumper, rear bumper lower cover		\$	400.00 360
			\$	<u>1,478.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



Kahin (1111)

16/10/19 1725h

2675

45

At the Repair shop

4/11/19

Cost of repair \$560/ 2675