



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI19018377/Agb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 09-01-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 9881U	Veh. Inspected	SKC 7711P
Policy No.	DMCOHQ19-000007	Coverage (\$)	0.00
Claim No.	DM19HO02830-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	17/10/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CRV	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHLRE2850AC200111	Colour	SILVER
Odometer	104019	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	DUNLOP	6 mm
L/H Front Tyre	225/65 R17	DUNLOP	6 mm
R/H Rear Tyre	225/65 R17	DUNLOP	6 mm
L/H Rear Tyre	225/65 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/10/2019	Inspection Date	17/10/2019
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
--	------------------------