

Surveyor

REF: 091/MG/19018379/Fy d36r

Special Instruction:

L/S: \$ 13,800.00

From (Person): Lee Ming Yao of MG Date/Time: 16/10/19  
 Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: PAR Automotive consultant

Workshop: N-SI Automotive

ODTP Re-inspection / Evaluation

To Inspect Vehicle No: SLU 4527T Insured: SLG 2292G

at Workshop m/s: N-SI Automotive Tel: 8420051

of 2 Kaki Bukit Ave 2 #01-17/18 Autohub

Policy No: Claim No: 3448806956SG-003

Sum Insured: Excess:

Make of Veh: D.O.A. 28/06/2018

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 9 days)

Date/Time: 4/11/19 Submit Final Fig \$5450K 9 days (Red \$ 8350K 60 %; Original 9 days)


Date/Time Action/Instruction

SLU 4527T-X

SLG 2292G-CC4/AXA17007516/Kua 3y2

DOA: 11/01/2017

25/10/19 Ram said follow Simon malced



25/10/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 05 NOV 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

Fee Charged:

 Basic & Add  
 Transport  
 Photos  
 Others  
 Total

Date:

190

190

1) Date/Time 04/11/19 File Pass to Typist

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

## Nivitha (LKK Auto)

---

**From:** Lee, Ming-Yao <MingYao.Lee@aig.com>  
**Sent:** Wednesday, 16 October 2019 11:04 AM  
**To:** assignments  
**Cc:** Admin-D (LKKAuto)  
**Subject:** Our Ref : 3448806956SG-003 | To Conduct Paper Survey on TPV SLU4527T DOA 28/06/2018  
**Attachments:** 3448806956SG - TP GIA.PDF; 3448806956SG - OI GIA.PDF; 3448806956SG - PRS Photos.pdf; 3448806956SG - TP Surveyor Report.pdf

Hi Sir / Madam,

Kindly assist to conduct paper survey on TPV.

Supporting documents as attached.

Appreciate to acknowledge receipt of this assignment.

Regards,  
Lee Ming Yao, George  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1769

[Ming-Yao.Lee@AIG.com](mailto:Ming-Yao.Lee@AIG.com) | [www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Report No: 0026-19-N51

07 January 2019

Darwin-51 Car Rental Pte Ltd  
c/o N-51 Automotive Pte Ltd  
2 Kaki Bukit Ave 2 #01-18  
Kaki Bukit Auto Hub  
Singapore 417921

INVOICE No. 0026-19-N51

Vehicle No. SLU4527T

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$918.00
Total amount payable		<u>\$918.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0026-19-N51

07 January 2019

## ACCIDENT VEHICLE SURVEY REPORT

Darwin-51 Car Rental Pte Ltd  
c/o N-51 Automotive Pte Ltd  
2 Kaki Bukit Ave 2 #01-18  
Kaki Bukit Auto Hub  
Singapore 417921

### VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLU4527T	<i>Odometer:</i>	58866km
<i>Make &amp; Model:</i>	Toyota Prius Alpha 1.8S	<i>Colour:</i>	Silver
<i>Chassis number:</i>	ZVW400027233	<i>Date of accident:</i>	28/06/2018
<i>Year of Regn.:</i>	01/12/2017	<i>Date inspected:</i>	29/06/2018
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	06/07/2018

### STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	6mm/Habibead	6mm/Habibead	205/60R16
<i>Rear:</i>	5mm/Yokohama	5mm/Yokohama	205/60R16

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.  
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

## Parts and Labour Assessment

### PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER <i>bu</i>	1	squashed	449.25	449.25
REAR BUMPER REFLECTOR L/R	2	fractured	264.50	264.50
REAR BUMPER SIDE RETAINER L/R <i>rec</i>	2	necessary	282.90	282.90
REAR END PANEL <i>bu</i>	1	buckled	781.45	781.45
REAR END PANEL ANTENNA SENSOR <i>xnd</i>	1	shorted	385.00	385.00
REAR END PANEL TOP GARNISH <i>cr</i>	1	fractured	372.45	372.45
REAR EXHAUST GASKET <i>xnd</i>	1	necessary	30.00	30.00
REAR EXHAUST RUBBER MOUNTING <i>xnd</i>	2	distorted	70.00	70.00
REAR EXHAUST SILENCER BOX <i>xnd</i>	1	bent	790.00	790.00
REAR FENDER INNER TRIM L/R <i>xnd</i>	2	deformed	1,563.80	1,563.80
REAR SPARE TYRE PANEL TOOL GARNISH RH <i>xnd</i>	1	deformed	245.10	245.10
REAR SPARE TYRE PANEL TOOL SPONGE <i>cr</i>	1	deformed	374.45	374.45
REAR SPARE TYRE PANEL TOP BOARD <i>xnd</i>	1	deformed	381.55	381.55
REAR SPARE TYRE PANEL TOP BOARD L/R <i>xnd</i>	2	deformed	754.20	754.20
REAR SPARE TYRE TRAY BOX <i>xnd</i>	1	deformed	385.10	385.10
REAR TAILGATE <i>bu</i>	1	buckled	1,045.20	1,045.20
REAR TAILGATE 'HYBRID' EMBLEM <i>rec</i>	1	necessary	67.00	67.00
REAR TAILGATE 'LOGO' EMBLEM <i>rec</i>	1	necessary	81.00	81.00
REAR TAILGATE 'PRIUS' EMBLEM <i>rec</i>	1	necessary	121.10	121.10
REAR TAILGATE DAMPER L/R <i>xnd</i>	2	bent	757.70	757.70
REAR TAILGATE HINGES L/R <i>xnd</i>	2	bent	304.50	304.50
REAR TAILGATE INNER PULL GARNISH <i>xnd</i>	1	warped	110.25	110.25
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>xnd</i>	2	deformed	30.00	30.00
REAR TAILGATE INNER TRIM BOARD <i>xnd</i>	1	fractured	781.10	781.10
REAR TAILGATE MECHANISM LOCK BT <i>cr</i>	1	bent	391.00	391.00
REAR TAILGATE NUMBER PLATE LAMP L/R <i>xnd</i>	2	fractured	460.96	460.96
REAR TAILGATE OUTER GARNISH <i>cr</i>	1	fractured	397.00	397.00
REAR TAILGATE WEATHERSTRIP <i>Def</i>	1	deformed	378.85	378.85
REAR TAILGATE WIPER MOTOR <i>xnd</i>	1	shorted	673.00	673.00
REAR TAILLAMP INNER RUBBER GASKET L/R <i>rec</i>	2	necessary	70.00	70.00
REAR TAILLAMP L/R <i>cr</i>	2	fractured	1,150.00	1,150.00
REAR TAILLAMP LOWER BRACKET L/R <i>xnd</i>	2	bent	282.90	282.90
REAR TAILLAMP PANEL L/R <i>xnd</i>	2	repair	234.00	0.00
REAR WINDSCREEN SEAL <i>rec</i>	1	necessary	115.00	115.00

Subtotal before discount S\$ 14,580.31 S\$ 14,346.31

Percentage discount 25% and 25%

S\$ 3,645.08 S\$ 3,586.58

Sub-total 1 S\$ 10,935.23 S\$ 10,759.73

5623.15

REAR BUMPER CLIPS - SET <i>rec</i>	1	necessary	100.00	100.00	\$20
REAR BUMPER REVERSE SENSOR <i>sc</i>	1	shorted	350.00	350.00	\$200
REAR END PANEL TOP GARNISH CLIPS - SET <i>rec</i>	1	necessary	50.00	50.00	\$30
REAR FENDER INNER TRIM CLIPS L/R - SET <i>rec</i>	2	necessary	60.00	60.00	X
REAR SPARE TYRE PANEL INSULATOR MAT <i>rec</i>	1	necessary	300.00	300.00	X
REAR TAILGATE CAMERA <i>rec</i>	1	shorted	800.00	800.00	X
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>rec</i>	1	necessary	100.00	100.00	X
REAR TAILGATE NUMBER PLATE <i>rec</i>	1	bent	25.00	25.00	\$20
REAR TAILGATE NUMBER PLATE HOLDER <i>rec</i>	1	bent	50.00	50.00	\$25
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>rec</i>	1	necessary	40.00	40.00	\$20
REAR TAILLAMP CLIPS L/R - SET <i>rec</i>	2	necessary	60.00	60.00	\$50
REAR WINDSCREEN SEALANT <i>rec</i>	1	necessary	100.00	100.00	\$10
Subtotal before discount			S\$ 2,035.00	S\$ 2,035.00	\$405
Sub-total 2			S\$ 2,035.00	S\$ 2,035.00	
Parts-total			S\$ 12,970.23	S\$ 12,794.73	

## LABOUR

To reset system after repair works	400.00	400.00	\$120
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	120.00	80.00	\$30
To remove, reinstall tailgate windscreen	300.00	150.00	\$100
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00	\$20
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,800.00	1,320.00	\$800
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	120.00	X
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,600.00	1,250.00	\$600
To apply anti-rust chemical on repaired and replaced panel	120.00	90.00	\$30
Labour Total	S\$ 4,660.00	S\$ 3,470.00	\$1670
Parts & Labour Total	S\$ 17,630.23	S\$ 16,264.73	

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 13,800.00 and the recommended number of working days for the repairs is within 9 day(s).

BJ Loi (1 Eng. NIML AIR13)  
Automotive Apprentice

List Item : \$4750.82  
 Part Item : \$405.15  
 Labour : \$1670.00  
 Total : \$6825.97

at 20% HS : \$5450.00

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

7909C

### Vehicle Details

Vehicle No.:

5LU4527T

Vehicle to be Exported:

No

Intended De-registration Date:

28 Jun 2018

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS ALPHA HYBRID 1.85 CVT

Primary Colour:

Silver

Manufacturing Year:

2017

Engine No.:

2ZR0A26402

Chassis No.:

ZVW400027233

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$29,254.00

Original Registration Date:

01 Dec 2017

First Registration Date:

01 Dec 2017

Transfer Count:

0

Actual ARF Paid:

\$17,956.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

30 Nov 2027

PARF Rebate Amount:

\$13,467.00

### Intended COE Rebate Details

COE Expiry Date:

30 Nov 2027

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$57,414.00

COE Rebate Amount:

\$54,096.00

Total Rebate Amount:

\$67,563.00

The information contained herein is correct as at 28 Jun 2018

OK

# PAR Automotive Consultancy

Page 1 of 1

Telephone: 832 0855 Fax: 832 0294 Singapore 9217713 1221 0000 11111 Fax: 645 96126

Report No: 0026-19-N51

07 January 2019

## ACCIDENT VEHICLE SURVEY REPORT

Darwin-51 Car Rental Pte Ltd  
c/o N-51 Automotive Pte Ltd  
2 Kaki Bukit Ave 2 #01-18  
Kaki Bukit Auto Hub  
Singapore 417921

### VEHICLE INFORMATION:

<i>Vehicle Reg No</i>	SLU4527T	<i>Odometer</i>	58866km
<i>Make &amp; Model</i>	Toyota Prius Alpha 1.8S	<i>Colour</i>	Silver
<i>Chassis number</i>	ZVW400027233	<i>Date of accident</i>	28/06/2018
<i>Year of Regn</i>	01/12/2017	<i>Date inspected</i>	29/06/2018
<i>Repairer at</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair)</i>	06/07/2018

### RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/06/2018 11:46
Date Of Accident	28/06/2018 07:40
Exact Location Of Accident	TEBAN FLYOVER (TOLL ROAD) TOWARDS TUAS
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLU4527T
Insured/Policyholder	
Name Of Registered Owner	DARWIN-51 CAR RENTAL PTE LTD
Co Reg No	201407909C
Email Address	SALES@N51.COM.SG
Mobile Phone No	
Alternative Phone No	Office-68425151
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V08976/VPZ/R00
Cover Note Number	
Driver	
Name of Driver	MOHD RIDWAN BIN ABDULLAH @ TAN WEN HAUR
NRIC No	S1501293E
Date Of Birth	01/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	12/04/1983
Driving Experience	35 YEARS AND 2 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-92477675
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 109 BEDOK NORTH ROAD #07-2294
Postcode	460109
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : UNKNOWN Gender: : Male

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG2292G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THNG HAN TIONG
NRIC/Passport Number	

Contact Number 90678197

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN** A24 (TOWN PLANE) TOWN PLANE

VEHICLE A - SLV 4527 T

VEHICLE B - SLV 2292 G



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I WAS DRIVING ALONG A24 TOWARDS TOWN AFTER  
EXIT 13 (TOWN TOWN HILL EXIT). I WAS IN THE SECOND  
LANE.

WHILE DRIVING FORWARD, DUE TO THE HEAVY TRAFFIC  
THE VEHICLE AHEAD BEGAN TO COMPLETE STOP AND GO  
I TOO ADOPTED SAME TO COMPLETE STOP, STOPPING ABOUT  
A FEW SECONDS. I SAW A GEAR SHIFT FROM THE  
REAR OF MY VEHICLE.

AND SO I GLANCED FROM MY VEHICLE AND OBSERVED IT  
WAS A VEHICLE DRIVING (SLV 2292 G) THAT COLLIDED  
TO THE REAR OF MY VEHICLE.

THE WHOLE INCIDENT SCENARIO WAS CAPTURED BY MY IN-CAR  
CAMERA.

VEHICLE A - SLV 4527 T  
VEHICLE B - SLV 2292 G

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:   
NRIC/ID No:

Accident Photo



Accident Photo



Accident Photo



PRIVATE HIRE DECAL



CHASSIS NO.



TOYOTA MOTOR CORPORATION JAPAN

MODEL DAA-ZVW40W-AWXEB

ENGINE 2ZR-FXE 1797 mL

FRAME No. ZVW40-0027233

COLOR TRIM PLANT OPTION

1F7 FC22 A32

TRANS./AXLE P410 -01A

038

Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/06/2018 11:14
Date Of Accident	28/06/2018 07:50
Exact Location Of Accident	ALONG AYE TOWARDS TUAS
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG2292G
Insured/Policyholder	
Name Of Registered Owner	THNG HAN TIONG (TANG HANZHONG)
NRIC No	S7413235I
Email Address	ANDREW_THNG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90678197
Alternative Phone No	Others-90678197
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100484004-01
Cover Note Number	
Driver	
Name of Driver	THNG HAN TIONG (TANG HANZHONG)
NRIC No	S7413235I
Date Of Birth	29/04/1974
Occupation	INDOOR
Date Of Driving Pass	01/04/1996
Driving Experience	22 YEARS AND 2 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-90678197
Fax Number	
Contact Number	OTHERS-90678197
Email Address	ANDREW_THNG@HOTMAIL.COM
Address	BLK 86 DAWSON ROAD #20-15
Postcode	141086
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU4527I
Vehicle Make/Model/Colour	TOYOTA PRIUS
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	MOHD RIDWAN BIN ABDULLAH @TAN WEN HAUR
NRIC/Passport Number	S1501293E
Contact Number	92477675

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature:

Date & Time:

28/06/2018

28 JUN 2018

11:44 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/IN No.:

Poh Kwee Choo  
S6840583A

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/06/2018 @ 0750 hrs travelling along AYE towards Tuas, I collided onto vehicle SLU4527T which I was unable to stop in time when he applied E-brake and collided.

other party particular

Toyota Prius, SLU4527T  
ST5012936  
Mohd Redwan Bin Abdullah  
@ Tan Wen haur.  
Contact 9247 7675-

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

28/06/2018  
28 JUN 2018  
11:44pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

Poh Kwee Choo  
56840583A

DRIVER'S NRIC & DRIVING LICENCE

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S74132351



NAME  
TONG HAN TONG  
TONG HANZHONG  
Race  
CHINESE  
Date of birth  
19-08-1984  
Issued at  
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

S74132351



TONG HAN TONG  
TONG HANZHONG

Valid from: 29 Apr 1974  
Valid until: 19 Aug 2019



License No. S74132351



Valid from  
19-08-2004

APT BLK 88 LAWSON ROAD #20-15  
SINGAPORE 141088

License No. S74132351

Valid until: 20-08-2019

YOU ARE EXEMPTED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

(EXEMPTIVE ONLY)

Class 2B	Motorcycles <= 250 cc	29 Apr 1984
Class 2A	Motorcycles between 251 cc and 500 cc	22 Mar 2005
Class 3	Motor cars with gross weight <= 2000kg with <= 7 passengers, exclusive of driver, and other motor vehicles with gross weight <= 2000kg	27 Apr 1984



Accident Photo



Accident Photo



Accident Photo



CHASSIS NUMBER

**NISSAN**

**SJNFEAJ11U1723886**

**1880 kg**

**2880 kg**

**1 – 980 kg**

**2 – 980 kg**



**Type FEAJ11 Colour, Trim QAB G**  
**Model FRLARBZJ11UEA – – A – –**



Your Ref: 3448806956SG-003

Date: 08<sup>th</sup> Nov 2019

Our Ref: CS1/AIG19018379/Fyd3e2

**M/s AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way #08-16

Chartis Building

Singapore 079120

Attn : Lee Ming Yao

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLU 4527T**

**INSURED VEHICLE: SLG 2292G**

**ACCIDENT DATE: 28/06/2018**

We thank you for your instruction on 16/10/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLU 4527T from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SLU 4527T and SLG 2292G.
- c) Colour damaged vehicle photographs of SLU 4527T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLU 4527T
Make & Model	: Toyota Prius Alpha Hybrid 1.8S CVT
Year of Registration	: 2017
Chassis Number	: ZVW400027233
Engine Capacity	: 1797 cc

2. We recommend that the repairs of the entire damage require about 9 (Nine) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 4527T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	BUCKLED	449.25	449.25
2	REAR BUMPER REFLECTOR L/R	N/S CRACKED / O/S NO DAMAGED	264.50	90.62
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	282.90	132.45
1	REAR END PANEL	BUCKLED	781.45	781.45
1	REAR END PANEL ANTENNA SENSOR	NO DAMAGED	385.00	-
1	REAR END PANEL TOP GARNISH	CRACKED	372.45	372.45
1	REAR EXHAUST GASKET	NO DAMAGED	30.00	-
2	REAR EXHAUST RUBBER MOUNTING	NO DAMAGED	70.00	-
1	REAR EXHAUST SILENCER BOX	NO DAMAGED	790.00	-
2	REAR FENDER INNER TRIM L/R	N/S DISTORTED / O/S NO DAMAGED	1,563.80	781.90
1	REAR SPARE TYRE PANEL TOOL GARNISH RH	NO DAMAGED	245.10	-
1	REAR SPARE TYRE PANEL TOOL SPONGE	CUT	374.45	200.00
1	REAR SPARE TYRE PANEL TOP BOARD	NO DAMAGED	381.55	-
2	REAR SPARE TYRE PANEL TOP BOARD L/R	NO DAMAGED	754.20	-
1	REAR SPARE TYRE TRAY BOX	NO DAMAGED	385.10	-
1	REAR TAILGATE	BUCKLED	1,045.20	1,045.20
1	REAR TAILGATE 'HYBRID' EMBLEM	NECESSARY	67.00	61.00
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	81.00	61.00
1	REAR TAILGATE 'PRIUS' EMBLEM	NECESSARY	121.10	121.10
2	REAR TAILGATE DAMPER L/R	NO DAMAGED	757.70	-
2	REAR TAILGATE HINGES L/R	NO DAMAGED	304.50	-
1	REAR TAILGATE INNER PULL GARNISH	NO DAMAGED	110.25	-
2	REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	NO DAMAGED	30.00	-
1	REAR TAILGATE INNER TRIM BOARD	NO DAMAGED	781.10	-
1	REAR TAILGATE MECHANISM LOCK	BENT	391.00	391.00
2	REAR TAILGATE NUMBER PLATE LAMP L/R	NO DAMAGED	460.96	-
1	REAR TAILGATE OUTER GARNISH	CRACKED	397.00	397.00
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	378.85	195.00
1	REAR TAILGATE WIPER MOTOR	NO DAMAGED	673.00	-

Report Ref No. CS1/AIG19018379/Fyd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP INNER RUBBER GASKET L/R	NECESSARY	70.00	40.00
2	REAR TAILLAMP L/R	CRACKED	1,150.00	1,150.00
2	REAR TAILLAMP LOWER BRACKET L/R	NO DAMAGED	282.90	-
2	REAR TAILLAMP PANEL L/R	NO DAMAGED	234.00	-
1	REAR WINDSCREEN SEAL	NECESSARY	115.00	65.00
	LESS 25% DISCOUNT		-3,645.08	-1,583.61
			10,935.23	4,750.81
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	20.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORT CIRCUIT	350.00	200.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
2	SET REAR FENDER INNER TRIM CLIPS L/R (SN)	NO DAMAGED	60.00	-
1	REAR SPARE TYRE PANEL INSULATOR MAT (SN)	NO DAMAGED	300.00	-
1	REAR TAILGATE CAMERA (SN)	NO DAMAGED	800.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NO DAMAGED	100.00	-
1	REAR TAILGATE NUMBER PLATE (SN)	BENT	25.00	20.00
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	BROKEN	50.00	25.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	60.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
			2,035.00	405.00
	<b><u>LABOUR</u></b>			
	TO RESET SYSTEM AFTER REPAIR WORKS.		400.00	120.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		120.00	20.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	80.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	20.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,800.00	800.00

Report Ref No. CS1/AIG19018379/Fyd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,600.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			4,660.00	1,670.00
GRAND TOTAL			17,630.23	6,825.81

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,450.00
--	--	--	--	----------

Report Ref No. CS1/AIG19018379/Fyd3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.