

INS. CASE OWNER:

CC 4/LPC1901 8280, E 12/12

LKK:
IDAC:

Surveyor:

STING

DOI:

ASSIGNMENT

11/11/19

Date / Time:

16/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMH 4068H

Claim No.:

Name of Insured:

KEE LEE FONG

Policy No.:

319VP/502015

Insured Tel No.:

HP:

Make / Model:

BMW

Excess Sec II :\$S

D.O.A:

11/10/19

Place of Accident:

Lampang RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

ET 169H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

ET 169H 2020/10/19 10:00 AM - 10:00 AM

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

4/12/2020
Khanh Hoa

File pass to type mandate.

22/3/2020
Khanh Hoa

File pass to HK to close.

RELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P19 \$3,686.05 (5 days) Reduction: 48 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒Call ☐

Final Liability:

100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

Culcast \$3,944.06

(OI REAR END TP)

Loss of Rental (LOR):

428 (4 days) x \$100

Loss of Use (LOU):

(\$ - x - days)

Loss of Income (LOI):

(\$ - x - days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search

\$ -

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost

\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

Total:

\$4,372.06

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

\$4,372.06

Name 1:

KAH MOTOR CO SDN BHD

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	932I
Vehicle Details	
Vehicle No.:	ET169H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	ODY55EY 2.4 EXV-S CVT SR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	K24W72012997
Chassis No.:	JHMRC1890GC206932
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$32,373.00
Original Registration Date:	03 Oct 2016
First Registration Date:	03 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$37,323.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2026
PARF Rebate Amount:	\$27,992.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$39,282.00
Total Rebate Amount:	\$67,274.00

The information contained herein is correct as at 11 Nov 2019

OK



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No. S60FC1380G

Customer	LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWERS SINGAPORE 189702	Document No.	SQT19004518	Page	1
Registration No	ET169H	Date	15. Oct 2019		
Chassis No	JHMRC1890GC206B32	Customer No.	WZL009		
Model	ODYSSEY 2.4 EXV-S 15YM	Svc Advisor	IVAN TEO BOON KIAT		
Owner's Name	NIAM TEE AIK	Engine No	K24W72012997		
Ins Policy No.		Date Time	15. Oct 2019 4:54:38 PM		
Date of Accident	11/10/2019	Surveyor Name			
		Survey Date			
		Authorisation Date			

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (JNO OWNER: NIAM TEE AIK OWNER INSURER: TOKIO MARINE ACC DATE: 11/10/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: SMH406BH						
88190-T8A-Q10ZZ	TAILGATE COMP X R	1	1070.80	25	803.10	56.22	859.32
94715-T6A-900ZZ	FACERR.BUMPER /	1	568.30	25	426.22	29.84	456.06
71502-T6A-003ZZ	FACERR.BUMPER GARNISH X NAI	1	76.80	25	57.60	4.03	61.63
33505-SLJ-013	REFLECTOR ASSYR.RR. /	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. X NAI	1	45.40	25	34.05	2.38	36.43
71512-T6A-021ZZ	SPOILER ASSYR.RR.SIDE X NAI	1	114.10	25	85.57	5.99	91.56
71883-T6A-003	SPACERR.RR.BUMPER SIDE /	1	19.10	25	14.32	1.00	15.32
71898-T6A-003	SPACERR.RR.BUMPER SIDE /	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP.BUMPER /	7	2.30	25	12.07	0.84	12.91
88190-T6A-Q00ZZ	PANEL COMP.REAR X R	1	460.80	25	345.60	24.19	369.79
NMRS-4P-TM390L	4PCS ACT.RR.SENSOR ? X NAI	1	320.00		320.00	22.40	342.40
Sum Item					2148.90	150.27	2299.17
BOSUN	SUNDRIES NAI	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	/	180.00	12.60	192.60
BM102	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	/	180.00	12.60	192.60
BKRP025	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS. 564	1	2240.00	1400	2240.00	156.80	2396.80
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P) 850	1	2250.00	1350	2250.00	157.50	2407.50

Printed on 15/10/2019 5:10:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : ET169H
Chassis No : JHMRC1890GC206932
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : NIAM TEE AIK
Ins Policy No. :
Date of Accident : 11/10/2019

Document No. : SQT19004518
Date : 15. Oct 2019
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : K24W72012997
Date | Time : 15. Oct 2019 4:54:38 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Sum Labor					4950.00	246.50	5,296.50

Survey By : SPK (LKS)
Date & Time : 11/11/19, 11 am
Excess : with bill
Status : PIP
Signature : Ry APC sp

Total Amount 7,096.90 496.77 7,593.67
Total (inclusive of GST) 7,593.67

S dy
sterechn@lkk.com

LKK Auto Consultants hence notify the Repainer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer

Signature:

Date:

Printed on 15/10/2019 5:10:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0025278 / LONPAC	Document No:	SVC19072810
Chassis No:	JHMRC1890GC206932	Printed By:	IVANTEO
License No:	ET169H	Order Date:	11. November 2019
Mileage:	71717	Order Time:	11:58:23 AM
Engine No:	K24W72012997	Service Advisor:	IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: OWNER: NIAM TEE AIK OWNER INSURER: TOKIO MARINE ACC DATE: 11/10/2019 SURVEYED BY: DATE REF NO: TP INSURER: LONPAC TP VEH: SMH4068H	1					
74940-TR0-003	BUZZER ASSYSMART ✓ CR	1	80.10	25	45.07	3.15	48.22

GST Amount is calculated from individual lines

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380GCustomer: CU0025278 / LONPAC
Chassis No: JHMRC1890GC206932
License No: ET169H
Mileage: 71717
Engine No: K24W72012997Document No: SVO19072810
Printed By: IVANTEO
Order Date: 11. November 2019
Order Time: 11:58:23 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (JNO:) OWNER: NIAM TEE AIK OWNER INSURER: TOKIO MARINE ACC DATE: 11/10/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: SMH4068H						
04715-T&A-900ZZ	FACERR BUMPER	1	568.30	25	426.22	29.84	456.06
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	45.40	25	34.05	2.38	36.43
71593-T&A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71598-T&A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP BUMPER	7	2.30	25	12.07	0.84	12.91
74940-TRG-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
	SUM PARTS:				546.05	38.21	584.26
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BML02i	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BKRP02S	1456 STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	1	1,400.00		1,400.00	98.00	1,498.00
BP03R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	1	1,350.00		1,350.00	94.50	1,444.50
	SUM LABOUR:				3,140.00	219.80	3,359.80
	TOTAL SGD				3,686.05	258.01	3,944.06
Total Payable (SGD)							3,944.06

GST Amount is calculated from individual line(s)

Summer Lee (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 16 October, 2019 1:18 PM
To: Ivan Teo; MT_Claim_SG; assignments; Admin-D (LKKAuto)
Subject: RE: CHECK LIABILITY FOR 3RD PARTY CLAIM ET169H AGAINST SMH4068H (LONPAC) DOA 11/10/2019 Our Ref: 19/19/19/VP05/022520

3.26pm @ 16/10/19

VNI

p: Ivan

Without Prejudice

Dear Ivan


Our Insured has not reported the accident.

Do you still want us to arrange survey? If so, please liaise with LKK Auto Consultants Pte Ltd.

Dear Nivitha

Pls follow up.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Ivan Teo [mailto:ivanteo@honda.com.sg]
Sent: Wednesday, 16 October 2019 10:17 AM
To: MT_Claim_SG
Subject: CHECK LIABILITY FOR 3RD PARTY CLAIM ET169H AGAINST SMH4068H (LONPAC) DOA 11/10/2019

Dear Motor Claims,

Kindly advise on 3rd party direct settlement liability.

My client : ET169H
Your insured : SMH4068H
DOA : 11/10/2019


Thank you

Warmest Regards

Ivan Teo
Kah Motor Co. Sdn Bhd
255 Alexandra Road
Singapore 159937

DID : 97317842

Email: ivanteo@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 13 March 2020 2:57 PM
To: Desmond Toh
Cc: Winson Chow; Jerome Tan; Leon Lim; Admin A
Subject: RE: ET169H - TP CLAIM AGAINST SMH4068H DOA: 11.10.2019
Attachments: LONPAC DV.pdf

Without Prejudice
(save as to costs)

Dear Desmond,

We confirm settlement as per your LOD for **(\$4,372.06(all in))**.

We attach herewith a copy of the DV for your further action.

Kindly send us (LKK) all the documents below for our necessary action: -

- Original LOD
- Original Final Repair Tax Invoice & Rental agreement and invoice
- Original Letter of Authorisation & hardcopy of the DV

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>

Sent: Thursday, 12 March 2020 10:38 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: ET169H - TP CLAIM AGAINST SMH4068H DOA: 11.10.2019

Dear All,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19018380/Eka3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 30-03-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 4068H	Veh. Inspected	ET 169H	
Policy No.	Z19VP05022095	Coverage (\$)	0.00	
Claim No.	19/19/19/VP05/022520	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	16/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMRC1890GC206932	Colour	SILVER	
Odometer	71717	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	5 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	5 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	5 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/10/2019	Inspection Date	11/11/2019	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. ET 169H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	TAILGATE COMP (SN)	TO REPAIR SEE LABOUR	803.10	-
1	FACERR.BUMPER (SN)	DENTED	426.22	426.22
1	FACER,RR.BUMPER GARNISH (SN)	NOT NECESSARY	57.60	-
1	REFLECTOR ASSYR.RR (SN)	MISSING	34.05	34.05
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	34.05	-
1	SPOILER ASSYR.RR.SIDE (SN)	NOT NECESSARY	85.57	-
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	14.32	14.32
1	SPACERL.RR.BUMPER SIDE (SN)	NECESSARY	14.32	14.32
7	CLIP,BUMPER (SN)	NECESSARY	12.07	12.07
1	PANEL COMP.REAR (SN)	TO REPAIR SEE LABOUR	345.60	-
4	ACT RR.SENSOR (SN)	NOT NECESSARY	320.00	-
1	BUZZER ASSYSMART (SN) (ADDITIONAL)	BROKEN	45.07	45.07
			2,291.97	576.05
LABOUR				
	REMOVE & RENEW REVERSE SENSORS.		180.00	180.00
	INSPECT RR LIGHTING MECHANISMS PERFORM WATER.		180.00	180.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE COMP AND PANEL COMP.REAR .		2,240.00	1,400.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,250.00	1,350.00
			4,850.00	3,110.00
GRAND TOTAL			7,141.97	3,686.05
RECOMMENDED COST OF REPAIRS				3,686.05

Report Ref No. CC4/LPC19018380/Eka3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.