



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT19004518	Page	1
	100 BEACH ROAD	Date	: 15. Oct 2019		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: ET169H	Engine No	: K24W72012997		
Chassis No	: JHMRC1890GC206932	Date Time	: 15. Oct 2019 4:54:38 PM		
Model	: ODYSSEY 2.4 EXV-S 16YM	Surveyor Name	:		
Owner's Name	: NIAM TEE AIK	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/10/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NIAM TEE AIK OWNER INSURER: TOKIO MARINE ACC DATE: 11/10/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: SMH4068H						
68100-T6A-Q10ZZ	TAILGATE COMP X R	1	1070.80	25	803.10	56.22	859.32
04715-T6A-900ZZ	FACERR.BUMPER /	1	568.30	25	426.22	29.84	456.06
71502-T6A-003ZG	FACER.RR.BUMPER GARNISH X	1	76.80	25	57.60	4.03	61.63
33505-SLJ-013	REFLECTOR ASSYR.RR. /	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. X ?	1	45.40	25	34.05	2.38	36.43
71512-T6A-921ZG	SPOILER ASSYR.RR.SIDE ?	1	114.10	25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER SIDE /	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE /	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER /	7	2.30	25	12.07	0.84	12.91
66100-T6A-Q00ZZ	PANEL COMP,REAR X R	1	460.80	25	345.60	24.19	369.79
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	22.40	342.40
Sum Item					2146.90	150.27	2,297.17
BOSUN	SUNDRIES	1	100.00 30		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 /		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 /		180.00	12.60	192.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS. 800	1	2240.00 1490		2240.00	156.80	2396.80
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) 450	1	2250.00 1350		2250.00	157.50	2407.50

Printed on 15/10/2019 5:10:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWERS SINGAPORE 189702	Document No.	: SQT19004518	Page	2
Registration No	: ET169H	Date	: 15. Oct 2019	Customer No.	: WZL009
Chassis No	: JHMRC1890GC206932	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: K24W72012997
Model	: ODYSSEY 2.4 EXV-S 16YM	Date Time	: 15. Oct 2019 4:54:38 PM	Surveyor Name	:
Owner's Name	: NIAM TEE AIK	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 11/10/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					4950.00	346.50	5,296.50

Survey By	<u>Steve (LKK)</u>						
Date & Time	<u>11/11/19, 11 am</u>						
Excess	<u>Nil</u>						
Status	<u>PIP</u>						
Signature	<u>Ry NPL sp</u>						
	<u>S dy</u>						
	<u>sterechn@lkk auto.com</u>						
Total Amount					7,096.90	496.77	7,593.67
Total (Inclusive of GST)							7,593.67

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/10/2019 5:10:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.