

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT19004518	Page	1
	100 BEACH ROAD	Date	: 15. Oct 2019		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: ET169H	Engine No	: K24W72012997		
Chassis No	: JHMRC1890GC206932	Date Time	: 15. Oct 2019 4:54:38 PM		
Model	: ODYSSEY 2.4 EXV-S 16YM	Surveyor Name	:		
Owner's Name	: NIAM TEE AIK	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/10/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: NIAM TEE AIK						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 11/10/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC						
	TP VEH: SMH4068H						
68100-T6A-Q10ZZ	TAILGATE COMP X R	1	1070.80	25	803.10	56.22	859.32
04715-T6A-900ZZ	FACERR.BUMPER /	1	568.30	25	426.22	29.84	456.06
71502-T6A-003ZG	FACER.RR.BUMPER GARNISH X N/AI	1	76.80	25	57.60	4.03	61.63
33505-SLJ-013	REFLECTOR ASSYR.RR. /	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. X NAI	1	45.40	25	34.05	2.38	36.43
71512-T6A-921ZG	SPOILER ASSYR.RR.SIDE X NAI	1	114.10	25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER SIDE /	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE /	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP.BUMPER /	7	2.30	25	12.07	0.84	12.91
66100-T6A-Q00ZZ	PANEL COMP.REAR X R	1	460.80	25	345.60	24.19	369.79
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ? X NAI	1	320.00		320.00	22.40	342.40
Sum Item					2146.90	150.27	2297.17
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	/	180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	/	180.00	12.60	192.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS. 569	1	2240.00	1490	2240.00	156.80	2396.80
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) 450	1	2250.00	1350	2250.00	157.50	2407.50

Printed on 15/10/2019 5:10:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : ET169H
Chassis No : JHMRC1890GC206932
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : NIAM TEE AIK
Ins Policy No. :
Date of Accident : 11/10/2019

Document No. : SQT19004518 Page 2
Date : 15. Oct 2019
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : K24W72012997
Date | Time : 15. Oct 2019 4:54:38 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Sum Labor					4950.00	346.50	5,296.50

Survey By SPM (LKK)
Date & Time 11/11/19, 11am
Excess Nil
Status PIP
Signature Ry MC sp

Total Amount 7,096.90 496.77 7,593.67
Total (Inclusive of GST) 7,593.67

S dy
sferechn@lkk at .com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/10/2019 5:10:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0025278 / LONPAC
Chassis No: JHMRC1890GC206932
License No: ET169H
Mileage: 71717
Engine No: K24W72012997

Document No: SVO19072810
Printed By: IVANTEO
Order Date: 11. November 2019
Order Time: 11:58:23 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NIAM TEE AIK OWNER INSURER: TOKIO MARINE ACC DATE: 11/10/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: SMH4068H						
74940-TR0-003	BUZZER ASSYSMART ✓ OR	1.	60.10	25.	45.07	3.15	48.22

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0025278 / LONPAC
Chassis No: JHMRC1890GC206932
License No: ET169H
Mileage: 71717
Engine No: K24W72012997

Document No: SVO19072810
Printed By: IVANTEO
Order Date: 11. November 2019
Order Time: 11:58:23 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NIAM TEE AIK OWNER INSURER: TOKIO MARINE ACC DATE: 11/10/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: SMH4068H						
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	45.40	25	34.05	2.38	36.43
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
74940-TR0-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
	SUM PARTS:				546.05	38.21	584.26
BOSUN		1	30.00		30.00	2.10	32.10
	SUNDRIES						
BA02R		1	180.00		180.00	12.60	192.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BML02I		1	180.00		180.00	12.60	192.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKRP02S	1466 STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1,400.00		1,400.00	98.00	1,498.00
BP03R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,350.00		1,350.00	94.50	1,444.50
	SUM LABOUR:				3,140.00	219.80	3,359.80
	TOTAL SGD				3,686.05	258.01	3,944.06
	Total Payable (SGD)						3,944.06

GST Amount is calculated from individual line(s)