

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 25/9/18  
1415hrs

  
Driver's Signature  
(if driver is not the policyholder)


Date & Time: 24/9/18 1705hrs

  
Reporting Centre Personnel's Signature

Name: April  
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



Date of Accident = 24-9-18

A: GBD 8129 R

B: GBG 8385 B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I was driving along King George Rd, accidentally hit the rear portion of a parked vehicle: GBG 8385 B (the loading/unloading bay beside BLK 806).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Cadenis Quatro*

Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 24/9/18 17:05 hrs

*[Signature]*

Reporting Central Personnel's Signature  
Name: April  
NRIC/FIN No.:

Scene Photo



Scene Photo



Scene Photo



Scene Photo



Accident Photo

CHASSIS NO: JN1MC2E26Z0003031

U.L.W : 1800 KGS

M.L.W : 3300 KGS

P. CAP : F: 1 DRIVER, 2 OTHERS  
R: 00

TYRE SIZE : F: 195 x 15R 8PLY  
R: 195 x 15R 8PLY(S)

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048520  
Tel: (65) 6724 0010 Fax: (65) 6724 0030  
Operating Hours: Monday to Friday, 09:00 - 17:00  
UEN: S66550020G / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MJAS18124376 Vehicle Registration No: GBD8129R  
Name (as shown in NRIC) : Aloysius Tang Bo Hui NRIC/FIN/Passport No : S9424756Z  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : Blk 213 Lorong 8 Toa Payoh #08-63 Singapore (3/0213)  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 94518460  
Email Address : \_\_\_\_\_  
Date of Accident : 24-9-2018 Time of Accident : 1450hrs  
Place of Accident : Block 808 King George Road  
Insurance Company : China Taiping Insurance (Singapore) Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Policyholder name should be Cadenzaudio LLP.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

F G  
Policyholder / Driver's Signature  
Date: 25-9-2018

C  
Reporting Centre Personnel's Signature  
Name: Cassandra  
NRIC/FIN No.: \_\_\_\_\_  
Date: 25-9-2018





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0750918

Date of Report : 03/11/2018

To : M/s. P5 Pte Ltd  
C/o. 13 Kaki Bukit Road 4  
#01-20 Bartley Biz Centre  
Singapore 417807

Date of Assignment : 27/09/2018  
Report requested by : M/s. P5 Pte Ltd  
Date of Accident : 24/09/2018  
Date of Inspection : 27/09/2018  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.	: GBG8385B	Engine Capacity (cc)	: 2953cc
Make & Model	: Nissan Cabstar	Mileage (km)	: 11653km
Date of Registration	: 07/11/2017	Chassis / Frame No.	: JN1SC2F24Z0860326
Colour	: Met. Silver	Engine No.	: ZD30026500N

### TYRE CONDITION

Front LH	: 12 mm	Front RH	: 12 mm
Make	: Dunlop	Make	: Dunlop
Rear LH	: 12 mm / 12 mm	Rear RH	: 12 mm / 12 mm
Make	: Dunlop	Make	: Dunlop

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent Engine Modification	: Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Motor Intel Automo Pte. Ltd.  
13, Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807

### ASSESSMENT

Repairer's Estimate	: \$ 12,921.05
Revised Amount	: \$ 9,803.61
Less Excess	: \$ -
Recommended Reserve	: \$ 7,840.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

*Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.*



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8509 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : GBG8385B

Report No. : PAS/TP/0750918

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Motor Intel Automo Pte. Ltd., 13, Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the front and rear RH portions.

### DAMAGES

The front panel, front bumper, RHR door pillar, headlamps, front grille, rear tailgate, RHR sidegate, rear deck end panel, RH taillamp, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$9,803.61.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$7,840.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : GBG8385B

Report No. : PAS/TP/0750918

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$S)	Our Assessment (\$S)
-------	-----	--------------------	-----------	---------------------------	----------------------

### PARTS LIST

1	1 pc	Frnt bumper	Dented	\$ 859.20	\$ / 859.20
2	1 pc	Frnt panel	Dented/Repair	\$ 1,412.70	\$
3	1 pc	Frnt door pillar outer assy RH	Dented/Distorted	\$ 1,083.00	\$ X 1,083.00 Repair
4	1 pc	Tailgate	Dented/Distorted	\$ 1,399.70	\$ / 1,399.70
5	1 pc	Rr sidegate RH	Dented/Distorted	\$ 1,782.40	\$ X 1,782.40 Repair
6	1 pc	Rr deck end panel	Dented/Repair	\$ 982.40	\$
7	1 pc	Rr tailgate side support bracket RH	Dented/Bent	\$ 203.70	\$ X 203.70 Repair
8	1 pc	Frnt panel	Dented/Repair		(Refer labour no. 1, 2 & 4)
9	1 pc	Rr deck end panel	Dented/Repair		(Refer labour no. 5 & 6)

\$ 7,723.10	\$ 5,328.00
-------------	-------------

Less Discount : 30%	\$ 2,316.93	30%	\$ 1,598.40
---------------------	-------------	-----	-------------

List Parts Sub-Total :	\$ 5,406.17	\$ 3,729.60
------------------------	-------------	-------------

### PARTS NETT

1	2 pcs	Headlamp R/L	Cracked/Loop Broken	\$ 473.40	\$ 946.80	\$ / 946.80
2	1 pc	Frnt emblem (Cabstar)	Necessary	\$ 51.80	\$ / 51.80	
3	1 pc	Frnt grille assy	Dented/Cracked	\$ 578.60	\$ / 578.60	
4	1 pc	Frnt grille emblem (Logo)	Necessary	\$ 55.10	\$ / 55.10	
5	1 pc	Frnt bumper beam	Dented	\$ 283.70	\$ X 283.70 SVC	
6	1 pc	Rr tailgate side top lock RH	Dented/Bent	\$ 42.70	\$ / 42.70	
7	1 pc	Rr tailgate stopper RH	Torn	\$ 18.20	\$ / 18.20	
8	1 pc	Rr tailgate stopper bracket RH	Dented/Bent	\$ 73.40	\$ / 73.40	
9	1 pc	Taillamp RH	Cracked	\$ 248.60	\$ / 248.60	
10	1 pc	Taillamp bracket RH	Bent/Repair	\$ 84.30	\$	

\$ 2,383.20	\$ 2,298.90
-------------	-------------

Less Discount : 10%	\$ 238.32	10%	\$ 229.89
---------------------	-----------	-----	-----------

Nett Parts Sub-Total :	\$ 2,144.88	\$ 2,069.01
------------------------	-------------	-------------

### PARTS S/NETT

1	1 pc	Frnt no.plate	Dented	\$ 50.00	\$ / 35.00 15
2	1 pc	Rr sidegate railing RH	Dented/Bent	\$ 650.00	\$ / 650.00 350
3	1 pc	Rr tailgate sticker (70km/h)	Necessary	\$ 20.00	\$ / 20.00 10
4	1 pc	Rr tailgate sticker (6pax)	Necessary	\$ 20.00	\$ / 20.00 10
5	1 pc	Rr tailgate sticker (P5 Studio)	Necessary	\$ 120.00	\$ / 120.00 50
6	1 set	Rr reverse sensor	Refit	\$ 220.00	\$

Special Nett Sub-Total :	\$ 1,080.00	\$ 845.00
--------------------------	-------------	-----------

Parts Total :	\$ 8,631.05	\$ 6,643.61
---------------	-------------	-------------



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 9508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : GBG8385B

Report No. : PAS/TP/0750918

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 1,000.00	\$ 880.00 400
2	To spray painting, blending on front affected and adjacent area.	\$ 1,000.00	\$ 600.00 400
3	To check electrical system, repair wire harness and focus headlamp.	\$ 60.00	\$ 50.00 20
4	To remove and reinstall interior trims, garnishes, seats, etc. for necessary repairs.	\$ 100.00	\$ 80.00 X
5	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 1,000.00	\$ 660.00 400
6	To spray painting, blending on rear affected and adjacent area.	\$ 1,000.00	\$ 800.00 600
7	To check rear electrical wiring system.	\$ 50.00	\$ 30.00 20
8	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ 60.00 /
<b>Labour Total :</b>		<b>\$ 4,290.00</b>	<b>\$ 3,160.00</b> 1900
<b>Total (Parts &amp; Labour) :</b>		<b>\$ 12,921.05</b>	<b>\$ 9,803.61</b>

### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 7,840.00

Under normal circumstances, the repairs should be completed within a reasonable period of **10 Working Days**. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

5729.91  
20% 4600  
6 Days

*Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18017546/Gsd3s2-1

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-11-2019



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 8129R	Veh. Inspected	GBG 8385B
Policy No.	DMCVSN3034041800	Coverage (\$)	0.00
Claim No.	SNM18D04623C02	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	16/10/2019

## 2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1SC2F24Z0860326	Colour	SILVER
Odometer	11653	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/80 R15	DUNLOP	6 mm
L/H Front Tyre	175/80 R15	DUNLOP	6 mm
R/H Rear Tyre	155 R13	DUNLOP	6 mm
L/H Rear Tyre	155 R13	DUNLOP	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	24/09/2018	Inspection Date	27/09/2018
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8385B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRT BUMPER	DENTED	859.20	859.20
1	FRT PANEL	TO REPAIR SEE LABOUR	1,412.70	-
1	FRT DOOR PILLAR OUTER ASSY RH	TO REPAIR SEE LABOUR	1,083.00	-
1	TAILGATE	DENTED / DISTORTED	1,399.70	1,399.70
1	RR SIDEGATE RH	TO REPAIR SEE LABOUR	1,782.40	-
1	RR DECK END PANEL	TO REPAIR SEE LABOUR	982.40	-
1	RR TAILGATE SIDE SUPPORT BRACKET RH	TO REPAIR SEE LABOUR	203.70	-
1	FRT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR DECK END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 30% DISCOUNT		-2,316.93	-677.67
			5,406.17	1,581.23
<b>NETT ITEMS</b>				
2	HEADLAMP R/L @ \$473.40 (N)	CRACKED / LOOP BROKEN	946.80	946.80
1	FRT EMBLEM (CABSTAR) (N)	NECESSARY	51.80	51.80
1	FRT GRILLE ASSY (N)	DENTED / CRACKED	578.60	578.60
1	FRT GRILLE EMBLEM (LOGO) (N)	NECESSARY	55.10	55.10
1	FRT BUMPER BEAM (N)	SERVICEABLE	283.70	-
1	RR TAILGATE SIDE TOP LOCK RH (N)	DENTED / BENT	42.70	42.70
1	RR TAILGATE STOPPER RH (N)	TORN	18.20	18.20
1	RR TAILGATE STOPPER BRACKET RH (N)	DENTED / BENT	73.40	73.40
1	TAILLAMP RH (N)	CRACKED	248.60	248.60
1	TAILLAMP BRACKET RH (N)	TO REPAIR SEE LABOUR	84.30	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-238.32	-201.52
			2,144.88	1,813.68
	<b>SPECIAL NETT ITEMS</b>			
1	FRT NO. PLATE (SN)	DENTED	50.00	15.00
1	RR SIDE GATE RAILING RH (SN)	DENTED / BENT	650.00	350.00
1	RR TAILGATE STICKER (70KM/H) (SN)	NECESSARY	20.00	10.00
1	RR TAILGATE STICKER (6PAX) (SN)	NECESSARY	20.00	10.00
1	RR TAILGATE STICKER (P5 STUDIO) (SN)	NECESSARY	120.00	50.00
1	SET RR REVERSE SENSOR (SN)	REFIT	220.00	-
			1,080.00	435.00
	<b>LABOUR</b>			
	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT PANEL, FRT DOOR PILLAR OUTER ASSY RH AND FRT PANEL.		1,000.00	400.00
	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA.		1,000.00	400.00
	TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.		60.00	20.00
	TO REMOVE AND REINSTALL INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS.	NOT NECESSARY	100.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR SIDE GATE RH, RR DECK END PANEL, RR TAILGATE SIDE SUPPORT BRACKET RH, RR DECK END PANEL AND TAILLAMP BRACKET RH.		1,000.00	400.00
	SPRAY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA.		1,000.00	600.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		50.00	20.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		80.00	60.00
			4,290.00	1,900.00
	<b>GRAND TOTAL</b>		<b>12,921.05</b>	<b>5,729.91</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,600.00</b>



A handwritten signature in black ink, appearing to be 'XGQ'.

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

A handwritten signature in black ink, appearing to be 'ALWP'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.