

ASS. REC. BY:

REF:

AGI 19018383 / EY d307

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Ivy Pullen

of

AGI

Date/Time: 17/10/2018 3:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 11744

Insured:

SJV 1648R

at Workshop m/s

SMRT

Tel:

G866 2872.

of

Woodlands Depot

Policy No:

Claim No:

C10004289 / JM

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

54pm 17/10/18

Person Contacted:

Sharfi

Vehicle IN / OUT

Date/Time

Action/Instruction

John M

SHB 11744-CC3/LCR/8013672/Gen39.2

DVA: 17/6/2018

SJV 1648R-X

ASS. REC. BY:

Steve

REF:

AGI

ASSIGNMENT

From:

Date:

18/10/2019

Veh No:

SHB 11744

Yr Regn:

16/4/14

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHB 11744

Make:

Toyota Pass

C.C.

1798

at Workshop m/s

Colour

Marr

A/C: Insured / Std / NI / NA

of

Sp. Reading

999999

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JTOKN13643574199

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

S

mm

R/Bal.

S

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

S

mm

L/Bal.

S

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

14/10/19

D.O.I.

18/10/19

Lump Sum:

%

3 Val.: Yes or No

Survey held at

SMRT

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/11/19 Lump Sum \$4700/- (Red \$10900/-, 69%)

RECEIVED 29 NOV 2019

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

4

1)

☐

Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

2)

27/11/19 Typist

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

490

Transportation:

S + RS, SI

Photos

Others

TOTAL

490

Report Format:

Lump Sum / B.I. (\$)

\$4700/-

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Thursday, 17 October 2019 3:53 PM
To: Admin-D (LKKAuto)
Cc: SUR; Julie Mangubat
Subject: FW: TPD Survey: Claim ref:C10004289/JM || OI- SJV1648R (Black) TP- SHB1174U || Est:0.00 || SMRT

Hi Team,

We would like to arrange TP survey for SHB1174U.

Vehicle is in Woodlands.

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the

stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>
Sent: Wednesday, 16 October 2019 4:03 PM
To: 'claims@budgetdirect.com.sg'
Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/ARC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis) <ngsiuching@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>
Subject: RE: SHB1174U - SURVEY (AUTO & GENERAL INSURANCE)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB1174U** within 48 hours according to GIA guide line, involving your insured **SJV1648R**
Vehicle in Woodlands

Regards
Shanti
SMRT Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6866 2671/2 | bthaiyaln@smrt.com.sg



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2019 10:27
Date Of Accident	14/10/2019 19:50
Exact Location Of Accident	AIRPORT BOULEVARD (NO 50 AIRPORT BOULEVARD RD D
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1174U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	NG JASON (HUANG JASON)
NRIC No	S7400348F
Date Of Birth	07/01/1974
Occupation	OUTDOOR
Date Of Driving Pass	23/02/2000
Driving Experience	19 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS DIVISION HQ
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20191015/2006

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SJV1648R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUSA BIN OSMAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20191015/2006

1 of 3

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

Report No. T/20191015/2006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/10/2019 01:00		Vide Report No.:		Station Diary No.: 39
Informant's Particulars				
Name of Informant: NG JASON		Address: APT BLK 476B CHOA CHU KANG AVENUE 5 #09-23 SINGAPORE 682476		
ID Type / ID No.: NRIC NO / S7400348F		Contact No.: Home/Office: Mobile: 87691099		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 45	Date of Birth: 07/01/1974	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: TAXI DRIVER		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/10/2019 19:50	Type of Location: Straight Road
Location: Along Road 1 AIRPORT BOULEVARD NO 50 AIRPORT BOULEVARD ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB1174U	Car	TOYOTA		Maroon	Seriously Damaged	0
SJV1648R	Car	HYUNDAI		Black	Seriously Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999



T/20191015/2006

2 of 3

Report No. T/20191015/2006

CONTINUATION OF REPORT

Driver			
Name	NG JASON		ID No. S7400348F
Related Vehicle	SHB1174U (Car)		Contact No. 87691099
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	MUSA BIN OSMAN		ID No. S1485267J
Related Vehicle	SJV1648R (Car)		Contact No. 91125411
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On the 14/10/2019 at about 1950hrs, I was traveling along Airport Blvd road towards T1. Out of a sudden, I saw a vehicles front stopping in front of my lane. I tried to stop but to no avail that I collided to the right side of the vehicle's front. The other vehicle's driver then proceeded to reverse back which cost more damages to my vehicle. I suffered minor injury to my knee however, I have yet to see a doctor.



**SINGAPORE
POLICE FORCE**



T/20191015/2006

Police Station Of Origin;
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

3 of 3

Report No. T/20191015/2006

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 2 ELTON DE LAURE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 15/10/2019 01:00
Officer In Charge Of Case: TP / AEIT / SSI 2 YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:
Authentication Stamp NP168	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB1174U
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1326886
Chassis No.:	JTDKN36U305741199
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	16 Apr 2014
First Registration Date:	16 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Apr 2022
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	15 Apr 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$59,871.00
COE Rebate Amount:	\$18,659.00
Total Rebate Amount:	\$24,516.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Oct 2019

OK

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/10/2019

User ID : PohSuan

4102.88

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,183.00	\$400.00
Total Labour	\$1,183.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,872.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00 40 / MK
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 / AC
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 / AC
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 / MK
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$1,052.88	\$356.88 2196.88 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Not Given
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given
		53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given

x AMI
✓ DR
x NAI
✓ DR
✓ DR
x NAI
x NAI
x NAI
x NAI
✓ DR
x NAI
x NAI
x NAI

2061.10

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/10/2019

User ID : PohSuan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given
		75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace
		53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given
		90467-09050	CLIP(FOR HOOD INSULATOR)	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		55084-47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given
		55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given
		53630-47050	CABLE ASSY, HOOD	0.00	\$52.20	0.00	\$0.00	Replace	Not Given
		53614-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Not Given
		17700-38252	AIR CLEANER ASSY	0.00	\$929.90	0.00	\$0.00	Replace	Not Given
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Not Given
		53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	100.00	\$0.00	Replace	Old Damage
Total					\$18,784.23		\$1,390.15		

X N/A!
/ MC
X N/A!
X N/A!
X N/A!
X N/A!
X N/A!
X N/A!
X N/A!
X N/A!
X N/A!
X N/A!

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2245 82

22906.60
1 2608.40 (57)
29815



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/10/2019

User ID : PohSuan

Section A - Accident Details	
Registration Number	SHB1174U
Case Reference Number	TAX/10/19/2055
Registration Date	16/4/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG JASON(HUANG JASON)
Type of Accident	Head To Side
Accident Date and Time	14/10/2019 7:50 PM
Accident Reported Date and Time	15/10/2019 9:31 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	14/10/2019 8:54 PM
Replacement Vehicle issued?	No
Job Card Number	24103846
Special Instruction to ARC, if any	TOWED \$40 / TP / AUTO & GENERAL
Prepared Date and Time	16/10/2019 3:38 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,183.00	\$400.00
Total Spray Cost	\$1,872.00	\$800.00
Total Spare Part Cost	\$11,472.26	\$1,112.12
Total Other Cost	\$1,052.88	\$356.88
TOTAL COST	\$15,580.14	\$2,669.00
Lump Sum Total	\$15,600.00	\$1,100.00
Number of Repair Days	8.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN
ARC / Surveyor Sign Off Date	16/10/2019 4:36 PM	18/10/2019 2:33 PM
Signature		
Remarks	L/S repair, take after spray.	



Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Yvonne - Fik

Section A - Accident Details

Registration Number	SHB1174U
Case Reference Number	TAX/10/19/2055
Registration Date	16/4/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG JASON(HUANG JASON)
Type of Accident	Head To Side
Accident Date and Time	14/10/2019 7:50 PM
Accident Reported Date and Time	15/10/2019 9:31 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	Yes
Towed Back Date and Time	14/10/2019 8:54 PM
Replacement Vehicle issued?	No
Job Card Number	24103846
Special Instruction to ARC,if any	TOWED \$40 / TP / AUTO & GENERAL
Prepared Date and Time	16/10/2019 3:38 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,183.00	\$400.00
Total Spray Cost	\$1,872.00	\$800.00
Total Spare Part Cost	\$13,444.15	\$3,084.02
Total Other Cost	\$1,052.88	\$396.88
TOTAL COST	\$17,552.03	\$4,680.90
Lump Sum Total	\$17,550.00	\$4,700.00 (L/S)
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / AUTO & GENERAL
ARC / Surveyor Sign Off Date	22/10/2019 5:26 PM	22/10/2019 3:49 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	L/S repair, take after spray.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1911-0007	Invoice Number	
Quotation Date	03.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,183.00	\$400.00
Total Labour	\$1,183.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,872.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$1,052.88	\$396.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given ✓
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace ✓
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 50 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63655592
 Estimator Telephone Number : 98652623
 Accident Reporting Number : 88652672

Date Generated : 05/11/2015

User ID : PohSuan

57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Not Given X
53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Not Given X
53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given X
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X
53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given X
5311247240	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given X
53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given X
51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given X
53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$581.08	Replace	Replace ✓
53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Not Given X
53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given X
53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given X
55708-47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Not Given X
53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Not Given X
53557-47010	HOOD AUXILIARY CATCH	0.00	\$8.60	0.00	\$0.00	Replace	Not Given X
86510-28130	HORN ASSY, HIGH	0.00	\$110.40	0.00	\$0.00	Replace	Not Given X
86520-28180	HORN ASSY, LOW	0.00	\$110.40	0.00	\$0.00	Replace	Not Given X
81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check X
81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given X
88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Not Given X
G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Not Given X
G9225-47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Not Given X
G9229-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Not Given X
16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Not Given X
16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Not Given X
16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Not Given X
16711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Not Given X
16712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Not Given X
16361-37010	FAN BLADE	0.00	\$158.60	0.00	\$0.00	Replace	Not Given X
16361-28360	FAN BLADE NO 2	0.00	\$204.20	0.00	\$0.00	Replace	Not Given X
16363-37010	FAN MOTOR NO 1	0.00	\$538.30	0.00	\$0.00	Replace	Not Given X
16363-37020	FAN MOTOR NO 2	0.00	\$538.30	0.00	\$0.00	Replace	Not Given X
53801-47050	FENDER FRT/RH	0.00	\$723.40	100.00	\$0.00	Replace	Repair R
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given X
53802-47050	FENDER FRT/LH	0.00	\$723.40	100.00	\$0.00	Replace	Repair R
53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given X
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given X

	52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	✓
	52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE FRAME	1.00	\$15.00	0.00	\$15.00	Replace	Replace	✓
		NUMBER PLATE	1.00	\$12.00	0.00	\$12.00	Replace	Replace	✓
	52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	✓
	82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	X
	88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X
	81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	X
	81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Not Given	X
	81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given	X
	75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace	✓
	53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given	X
	90467-09050	CLIP(FOR HOOD INSULATOR)	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	55084-47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
	55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
	53630-47050	CABLE ASSY, HOOD	0.00	\$52.20	0.00	\$0.00	Replace	Not Given	X
	53614-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Not Given	X
	17700-38252	AIR CLEANER ASSY	0.00	\$929.90	0.00	\$0.00	Replace	Not Given	X
		COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Not Given	X
	53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	100.00	\$0.00	Replace	Old Damage	X
Total				\$18,784.23		\$1,390.15			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace
		81220-12230	FOG LAMP LH	1.00	\$280.10	25.00	\$210.08	Replace	Replace
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace
		53420-47070	HOOD HINGE LH	1.00	\$55.90	25.00	\$41.93	Replace	Replace
		53410-47070	HOOD HINGE RH	1.00	\$55.90	25.00	\$41.93	Replace	Replace
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
		81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
Total					2,908.40		2,464.88		

DD
BR
BR
BT
BT
CUT
URA

3855.03
- 208

3084.02
+ 400.00
+ 1196.88

4680.90

45 \$4700+

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7A4 / 10 / 19 / 2055	Date of Collection	19 / 10 / 19
Vehicle No	SHB 1174 U	Date of Request	21 / 10 / 19
Vehicle Model	TOYOTA PREVUS	Number of Days to Extend (If any)	3 days / day

S/N	Part Number	Part Description	Quantity	Unit Price	
	2857, 2859	Bumper Reinforcement Front	1	\$498.00	/ OD
	2845, 2846	Fog Lamp LH	1	\$280.10	/ OR
	2861, 2862, 63	Bumper Front Absorber Lower	1	\$127.70	/ OR
	2859, 2860	Hood Hinge LH	1	\$55.90	/ OT
	2864, 2866	Hood Hinge RH	1	\$55.90	/ OT
	2849, 2850	Headlamp Lamp LH	1	\$945.20	/ CR
	2865, 2866	Headlamp Lamp RH	1	\$945.20	/ CRA
	2854, 2855				
	2842, 2843				
	2844				

Please submit photographs for damaged parts

I, (Name)

Long Chee Keng (Signature) Steve CLKK 21/10/19, 4.50pm

(Position)

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 WOC	Form 22 / P13 / WOC. Reservation Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLEMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/10/19/2055	Date of Collection	19/10/19
Vehicle No	SHB1174U	Date of Request	21/10/19
Vehicle Model	Toyota Prius	Number of Days to Extend (If any)	3 days 1 day

S/N	Part Number	Part Description	Quantity	Unit Price	
	2857, 2859	Bumper Reinforcement Front	1	\$498.00	/ 00
	2845, 2846	Fog lamp LH	1	\$280.10	/ 0R
	2861, 2862, 63	Bumper Front Absorber Lower	1	\$127.70	/ 0R
	2859, 2860	Hood Hinge LH	1	\$55.90	/ 0T
	2864, 2866	Hood Hinge RH	1	\$55.90	/ 0T
	2849, 2850	Headlamp lamp LH	1	\$945.20	/ CRT
	2865, 2866	Headlamp lamp RH	1	\$945.20	/ CRA
	2854, 2855				
	2842, 2843				
	2844				

Please submit photographs for damaged parts

I, (Name) Long Chee Keng Store (LKK) 21/10/19, 4.50pm
 (Position) _____

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply: Form 22 WOC	Form 22 / P13 / WOC. Reservation Number
Photo Submitted	YES / NO	Date of submission



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19018383/Eyd3e2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 09-12-2019



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 1648R	Veh. Inspected	SHB 1174U
Policy No.		Coverage (\$)	0.00
Claim No.	C10004289/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	17/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U305741199	Colour	MAROON
Odometer	999999	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	FALKEN	5 mm
L/H Front Tyre	195/50 R15	FALKEN	5 mm
R/H Rear Tyre	195/50 R15	FALKEN	5 mm
L/H Rear Tyre	195/50 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/10/2019	Inspection Date	18/10/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1174U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	BROKEN	482.00	361.50
1	BUMPER SUPPORT F/LH (DISC 25%)	BROKEN	76.40	57.30
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	BROKEN	78.80	59.10
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	BROKEN	311.10	233.33
1	HOOD PANEL (DISC 25%)	DENTED	748.10	561.08
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	COVER, FR BUMPER HOLE LH (DISC 25%)	MISSING	18.50	13.88
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	BUMPER REINFORCEMENT FRT (DISC 25%)	DENTED	498.40	373.80
1	FOG LAMP LH (DISC 25%)	BROKEN	280.10	210.08
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	BROKEN	127.70	95.78
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.93
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.93
1	HEAD LAMP LH (DISC 10%)	CUT	945.20	850.68
1	HEAD LAMP RH (DISC 10%)	CRACKED	945.20	850.68
1	NUMBER PLATE FRAME (SN)	BROKEN	15.00	15.00
1	NUMBER PLATE (SN)	BROKEN	12.00	12.00
1	FENDER LINER PAD, FR WHEEL. LH	NOT NECESSARY	49.30	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	DEFLECTOR, RADIATOR RH	NOT NECESSARY	83.50	-
1	DEFLECTOR, RADIATOR LH	NOT NECESSARY	77.00	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-
1	LENS & BODY, FR TURN LH	NOT NECESSARY	511.80	-
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	GRILLE RADIATOR LOWER NO.2	NOT NECESSARY	94.60	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	UNDER COVER CENTER	NOT NECESSARY	448.30	-
1	HOOD PANEL INSULATOR	NOT NECESSARY	390.50	-
1	HOOD HINGE LH	NOT NECESSARY	55.90	-

Report Ref No. CS/AGI19018383/Eyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HOOD HINGE RH	NOT NECESSARY	55.90	-
1	WIPER GARNISH	NOT NECESSARY	614.00	-
1	HOOD LOCK	NOT NECESSARY	128.90	-
1	HOOD AUXILIARY CATCH	NOT NECESSARY	8.60	-
1	HORN ASSY, HIGH	NOT NECESSARY	110.40	-
1	HORN ASSY, LOW	NOT NECESSARY	110.40	-
1	HEAD LAMP LH	NOT NECESSARY	945.20	-
1	HEAD LAMP RH	NOT NECESSARY	945.20	-
1	A/C CONDENSER	NOT NECESSARY	1,181.90	-
1	RADIATOR ASSY, UPPER	NOT NECESSARY	679.60	-
1	HOSE, INVERTER NO.1	NOT NECESSARY	80.00	-
1	HOSE, INVERTER COOLING NO.5	NOT NECESSARY	125.30	-
1	RADIATOR ASSY	NOT NECESSARY	1,496.90	-
1	RADIATOR HOSE LOWER	NOT NECESSARY	42.40	-
1	RADIATOR TOP HOSE NO. 1	NOT NECESSARY	42.40	-
1	FAN SHROUD	NOT NECESSARY	244.50	-
1	FAN SHROUD TOP	NOT NECESSARY	99.60	-
1	FAN BLADE	NOT NECESSARY	158.60	-
1	FAN BLADE NO. 2	NOT NECESSARY	204.20	-
1	FAN MOTOR NO. 1	NOT NECESSARY	538.30	-
1	FAN MOTOR NO. 2	NOT NECESSARY	538.30	-
1	FENDER FRT / RH	NOT NECESSARY	723.40	-
1	FENDER FRT / LH	NOT NECESSARY	723.40	-
1	FENDER LINER FRT / LH	NOT NECESSARY	171.70	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	BRACKET, FR BUMPER	NOT NECESSARY	110.40	-
1	WIRE, ENGINE ROOM, NO. 3	NOT NECESSARY	242.00	-
1	THERMISTOR ASSY	NOT NECESSARY	107.00	-
1	BRACKET, FR TURN UPPER LH	NOT NECESSARY	24.40	-
1	BRACKET, FR TURN CENTER LH	NOT NECESSARY	58.20	-
1	BRACKET, FR TURN LOWER LH	NOT NECESSARY	26.00	-
1	COVER, RADIATOR	NOT NECESSARY	122.80	-
1	CLIP (FOR HOOD INSULATOR)	NOT NECESSARY	2.20	-
1	WIPER GARNISH COVER, LH	NOT NECESSARY	23.80	-
1	WIPER GARNISH COVER, RH	NOT NECESSARY	23.80	-
1	CABLE ASSY, HOOD	NOT NECESSARY	52.20	-

Report Ref No. CS/AGI19018383/Eyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CLAMP, HOOD LOCK	NOT NECESSARY	5.90	-
1	AIR CLEANER ASSY	NOT NECESSARY	929.90	-
1	COOLANT	NOT NECESSARY	12.32	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	NAME PLATE (HYBRID)	TO REPAIR SEE LABOUR	51.90	-
			21,707.12	3,855.03
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF NAME PLATE (HYBRID).		1,183.00	400.00
	SPRAY PAINT.		1,872.00	800.00
	TOWING CHARGE.		56.00	40.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	NOT NECESSARY	120.00	-
	TO CONDUCT RADIATOR PRESSURE CHECK.	NOT NECESSARY	120.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		296.88	296.88
			4,107.88	1,596.88
	GRAND TOTAL		25,815.00	5,451.91
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CS/AGI19018383/Eyd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.