

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15748

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1250/2019/NS
Date : 16-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chong Wai Keong
Address : Blk 63 Choa Chu Kang Loop
#11-05
Singapore 689669
Telephone : (HP) +65 97239838
Type of Claim : Own Damage Claims
Policy No. : 1700062767-02
Vehicle No : **SDA 1169 M**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 10-10-17
Engine No : CVK 047169
Chassis No : WAUZZZF56JA034313
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Oct-19
Place of Accident : BKE Towards Woodlands

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDA 1169 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle both front door panel trims. To remove and reinstall both wing mirror assy.	S/N \$ 600.00	X
3	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To repair both front door. Re-organise crash management components. Reinstall all parts removed.	\$ 5,600.00	1000.
4	To respray front bumper, both front fenders, bonnet, both upper A-pillars and both front doors.	\$ 7,700.00	1100.
5	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 14,572.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 1169 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,073.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 368.00	?
3	FRONT BUMPER SECURING STRIP	2 \$ 64.00	?
4	FRONT BUMPER GRILLE - CENTRE	\$ 178.00	?
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	X
6	FRONT BUMPER SPOILER	\$ 489.00	X
7	FRONT BUMPER AIR GUIDE - LH	\$ 56.00	X
8	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	X
9	RADIATOR GRILLE	\$ 2,131.00	Cur-
10	ULTRASOUND SENSOR SUPPORT - LH / RH	2 \$ 96.00	?
11	RADIATOR GRILLE COVER - UPPER	\$ 174.00	?
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 862.00	X
13	FRONT PARKING AID SENSOR - INNER	2 \$ 462.00	X
14	HORN - LH HIGH TONE	\$ 37.00	?
15	HORN - RH LOW TONE	\$ 262.00	?
16	SPRING SHACKLE - LH / RH	2 \$ 52.00	?
17	FRONT BUMPER CARRIER	\$ 733.00	? plus to.
18	FRONT BUMPER FOAM FILLER PIECE	2 \$ 113.00	? plus to.
19	FRONT BUMPER COVER	2 \$ 116.00	?
20	CAUTION SIGN STICKER	NEC \$ 13.00	?
SUB TOTAL SPARE PARTS		\$ 8,542.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 1169 M

S/N	Parts Description	Damaged Parts & Prices			Remarks
			S/Nett		
21	AIRCON STICKER	NEC	\$	7.00	?
22	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	66.00	?
23	LOCK CARRIER BRACKET		\$	125.00	?
24	FRONT BUMPER SUPPORT - LH / RH	2	\$	52.00	?
25	FRONT FENDER - LH / RH	2	\$	1,936.00	X
26	FRONT FENDER ATTACHMENT PARTS	2	\$	95.00	X
27	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$	136.00	?
28	FRONT FENDER BRACKET - LH / RH	2	\$	64.00	X
29	FRONT FENDER BRACE - LH / RH	2	\$	214.00	X
30	DEFORMATION ELEMENT BRACKET - LH / RH	2	\$	90.00	X
31	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	512.00	X
32	WHEEL HOUSING LINER ATTACHMENT PARTS	2	\$	164.00	X
33	WHEEL SPOILER - LH / RH	2	\$	132.00	X
34	WHEEL SPOILER TRIM - LH / RH	2	\$	64.00	X
35	STONE CHIP GUARD - LH / RH	2	\$	92.00	X
36	FRONT FENDER TRIM - LH / RH	2	\$	290.00	X
37	BONNET		\$	2,602.00	ht ✓
38	BONNET ATTACHMENT PARTS		\$	111.00	?
39	BONNET LID HINGE - LH / RH	2	\$	762.00	?
40	BONNET IMPACT PROTECTION - LH / RH / CEN	3	\$	75.00	Me ✓
SUB TOTAL SPARE PARTS		:	\$	<u>7,589.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 1169 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	ENGINE BONNET SOUND ABSORBER	\$	311.00	? pto f.
42	FENDER LEDGE COVER - LH / RH	2 \$	64.00	?
43	FENDER LEDGE COVER - LH / RH FRONT	2 \$	28.00	?
44	BONNET GAS FILLED STRUT	2 \$	217.00	?
45	BONNET STRIKER - LH / RH	2 \$	92.00	?
46	BONNET LID LOCK	2 \$	391.00	?
47	FLAT CONNECTOR HOUSING	\$	12.00	?
48	BONNET LOCK CABLE - CENTRE	\$	53.00	?
49	BONNET RELEASE CABLE - CENTRE	\$	53.00	?
50	BONNET RELEASE LEVER	\$	12.00	?
51	LED HEADLIGHT - LH / RH	2 \$	14,408.00	?
52	LED HEADLIGHT LIFT CYLINDER - LH / RH	2 \$	362.00	?
53	LED HEADLIGHT CORRUGATED PIPE	\$	78.00	?
54	FRONT WINDOW SLOT SEAL - LH / RH	2 \$	728.00	X
55	FRONT ROOF MOLDING - LH / RH	2 \$	1,148.00	X
56	FRONT DOOR TRIM - LH / RH	2 \$	290.00	X
57	FRONT WATER DEFLECTOR STRIP - LH / RH	2 \$	122.00	X
58	RADIATOR AIR GUIDE - LH / RH OUTER	2 \$	56.00	?
59	RADIATOR AIR GUIDE - LH / RH INNER	2 \$	30.00	?
60	RADIATOR AIR GUIDE - UPPER / LOWER	2 \$	34.00	?
61	FRONT NO. PLATE	S/N \$	40.00	ht
62	SUNDRIES	\$	500.00	?
TOTAL SPARE PARTS		:	\$ 35,160.00	
TOTAL LABOUR CHARGES		:	\$ 14,572.00	
GRAND TOTAL		:	\$ 49,732.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 9749544
Ex: to be advise
Not Authorise
17/10/19 @ 250pm
Resurvey before paint.
str @ Khanderson
25 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant