

Surveyor: Marcus ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of SMD Date/Time: 17.10.19 17.08p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFH 8178E Insured: SEA 3950 C

at Workshop m/s Profi Automotive Tel: 94335558 / 83202028

of BK10 Kati Bukit Road 2 A01-03

Policy No: D18MTPV01020224 Claim No: CMTD 1904898

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15.10.2019

(Client's Record) CA / REV / REP. / REV 24 HRS <sup>mp</sup> H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 18.10.19 9.48a.m Person Contacted: Alvin Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SFH 8178E - CC31AXA 11603279/T4/4292 DOA - 18/10/2011
	SEA 3950 C - CS/TP13 022861/47m 3K3 DOA - 10/11/2013
22/10/19	Send preli revised via merimen

merimen

ASSIGNMENT

From: \_\_\_\_\_ Date: 21.10.2019

Estimated Cost: \_\_\_\_\_

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SPH 8178E

at Workshop m/s Profi Automotive

of BIK 10 Kaki Bukit Road 2-01-03

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: AAV 10000m

Veh No: SPH 8178E Yr Regn: 2.18

Type:  Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or CA /

Make: Honda Vezel Hybrid 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 166419 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU 31257589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 215/60 R16

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 6

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS imp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or 7 ALVIN

Front	<u>6</u>	Rear	<u>6</u>
R/Bal.	mm	R/Bal.	mm
L/Bal.	<u>6</u>	L/Bal.	<u>6</u>
L/Bal.	mm	L/Bal.	mm

D.O.A. 15/10/19 D.O.I. 21/10/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear

The UIC / Chassis frame / Body Structure affected due to collision.

23/10/19 4/5 @ 3850 Confirmed with Alvin. (Ref 3701.50, 4910)

RECEIVED 24 OCT 2019

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

2) 24/10 - typist

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:	
Transportation:	<u>250</u>
S + RS. SI	<u>11</u>
Photos	
Others	
TOTAL	<u>261</u>

Report Format: merimen

Lump Sum / F.P. / %: 3850/2

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Hwang Shiang Yi	Date: 22 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SKA3950C	Accident Date	: 15/10/2019
TP Vehicle No	: SFH8178E	Assignment Date	: 17/10/2019
Make	: HONDA VEZEL HYBRID (A)	Est. Duration of Repair	: 4
Date of Inspection	: 21/10/2019		
Inspection At	: PROFI AUTOMOTIVE		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,551.50
Revised Amount	:S\$	5,372.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,372.72
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2019		17 Oct 2019 17:08 Assign				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	YAU CONG JING SAMUEL, ID: S8723039B, Tel: +6597122272, Email: yau_87cj@hotmail.com		
Main Claimant:	BENEDICT HO LAY CHEONG		
Vehicle Reg. No.:	SFH8178E	Date of Loss:	15/10/2019 22:00 - :59
Claim Type:	TP / CMTD1904898	Policy/Cover Note No.:	D18MTPV01020224 (Comprehensive)
Vehicle Reg. No. (Insured):	SKA3950C	Policy No. (Claimant):	
Repairer:	Prof1 Automotive (KB) BLK 10 KAKI BUKIT ROAD 2, #01-03 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/10/2019]		
Driver/Custodian (Insured):	YAU CONG JING SAMUEL (32 / Male), NRIC: S8723039B, Tel: +6597122272 Email: yau_87cj@hotmail.com		
Adj Asg. Remarks:	Please assign to Mr Marcus Chua		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

# Google Home Mini

Buy Google Home Mini for hands-free control of your smart home. Shop now at Google Store.

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Showroom Condition Porsche Macan



Very Low Mileage. Accident Free. Superb Condition. See To Believe.  
Direct Owner StarAd

**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997** [View our cars](#)

Browse by Category

Sort by Date Posted  20 results/page

13 vehicles

VezeL Hybrid 1.5A

Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	VezeL Hybrid 1.5A		Any	Any	2018	Any	Any	Any	Available
	Honda	VezeL Hybrid 1.5A	\$95,800	\$10,120 /yr	27-Jun-2018	1,496 cc	5,000 km	SUV	Available
<p><b>Fuel Type:</b> Petrol-Electric Almost New 2018 New Facelifted Honda VezeL Hybrid. Best Fuel Consumption SUV In Town. 10 Years Repayment, In House Loan Or Ball... <span style="float: right;">PREMIUM AD</span></p> <p>Trust Motoring Posted: 20-Oct-2019 Tags: 2018 Honda VezeL, 2018 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda</p>									
	Honda	VezeL Hybrid 1.5A	\$92,800	\$9,800 /yr	18-Jun-2018	1,496 cc	-	SUV	Available
<p><b>Fuel Type:</b> Petrol-Electric New Facelifted Honda VezeL Hybrid. Best Fuel Consumption SUV In Town., In House Loan Available. Trade In Always Welcome! <span style="float: right;">PREMIUM AD</span></p> <p>Posted: 19-Oct-2019 Tags: 2018 Honda VezeL, 2018 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda</p>									
	Honda	VezeL Hybrid 1.5A X Honda Sensing	\$92,800	\$9,680 /yr	06-Jun-2018	1,496 cc	18,236 km	SUV	Available
<p><b>Fuel Type:</b> Petrol-Electric 1 Owner. Low Mileage. Well Kept. Accident Free. Bank Loans And In-house Financing Available. 100% Financing Available. View Now! <span style="float: right;">PREMIUM AD</span></p> <p>Posted: 19-Oct-2019 Tags: 2018 Honda VezeL, 2018 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda</p>									
	Honda	VezeL Hybrid 1.5A X	\$90,800	\$9,300 /yr	28-Aug-2018	1,496 cc	12,572 km	SUV	Available
<p><b>Fuel Type:</b> Petrol-Electric 1 Owner! Accident Free! Non-PHV Unit! Low Mileage Done 12,172KM! Condition Like Brand New! Loan Available, Well Serviced And Main... Posted: 18-Oct-2019 Tags: 2018 Honda VezeL, 2018 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda</p>									
	<p><b>Door Visors For Touran and GOLF</b> Window door visor for Touran and GOLF. More info about this product</p>								
	Honda	VezeL Hybrid 1.5A X	\$93,800	\$9,250 /yr	17-Oct-2018	1,496 cc	6,800 km	SUV	Available
<p><b>Fuel Type:</b> Petrol-Electric Owner Migrated, Hardly Use Car, Mileage Low. Nice Number, Condition Like New. Come And View, U Will Be Impressed. High Loan, Low... Swee Seng Motors Posted: 10-Oct-2019 Tags: 2018 Honda VezeL, 2018 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda</p>									
	Honda	VezeL Hybrid 1.5A X	\$104,988	\$10,820 /yr	31-Aug-2018	1,496 cc	28 km	SUV	Available
<p><b>Fuel Type:</b> Petrol-Electric 2018 Facelifted Honda VezeL Hybrid. Best Fuel Consumption SUV In Town. - Fast Loan Approve - Welcome For Trade In 5 Years/130 00... Posted: 10-Oct-2019 Tags: 2018 Honda VezeL, 2018 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda</p>									

Compare

\$89,800 \$9,430 /yr 19-Apr-2018 1,496 cc 38,000 km SUV Available

## &gt; Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	203J
<b>Vehicle Details</b>	
Vehicle No.:	SFH8178E
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5957607
Chassis No.:	RU31257589
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,115.00
Original Registration Date:	09 Feb 2018
First Registration Date:	09 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$17,161.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2028
PARF Rebate Amount:	\$12,870.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Feb 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,903.00
COE Rebate Amount:	\$33,118.00
<b>Total Rebate Amount:</b>	<b>\$45,988.00</b>

The information contained herein is correct as at 21 Oct 2019

OK

# profi automotive

21 October 2019

Your Ref: Your insured SKA3950C  
Our Ref: PA191001-SFH8178E

Accident Date: 15-10-2019  
Vehicle No: SFH8178E  
Make/Model: Honda Vezel 1.5X  
Name: Homan Distance Solution  
Address: c/o 10 Kaki Bukit Road 2 #01-03 Singapore 417868

*Not Authorized  
date  
21/10/19  
H/S #3850  
who the Attorney  
Hdy.*

S/NO	QTY	LISTED ITEM	AMOUNT (S\$)
01	1 pc	Rear Boot <i>953.00</i>	<i>2065.00</i> 1210.80
02	1 pc	Rear Boot Lock	<i>400/shd</i> 200.90
03	1 pc	Rear Boot Lock Catch	<i>11</i> 53.60 X
04	1 pc	Rear Boot <del> </del> Rubber	<i>200</i> 148.70
05	1 pc	Rear Boot Emblem (VEZEL)	<i>00</i> 56.20
06	1 pc	Rear Boot Emblem (HYBRID)	<i>00</i> 57.40
07	1 pc	Rear Boot Inner Cover Board	<i>00</i> 405.20 X
08	1 pc	Rear Boot Inner Pull Handle Garnish	<i>11</i> 53.20 X
09	1 pc	Rear End Panel <i>517</i>	<i>3065.00</i> 675.30 ?
10	1 pc	Rear End Panel Top Garnish	<i>00</i> 219.30 ?
11	1 pc	Rear Bumper <i>721</i>	<i>00/00</i> 949.80
12	2 pc	Rear Side Bumper (2 X 325.40)	<i>00</i> 650.80 X
13	2 pc	Rear Bumper Side Retainer (2 X 48.20)	<i>11</i> 96.40 X
14	1 pc	Rear Bumper Under Cover	<i>00</i> 174.40 ?
15	1 Set	Rear Windscreen <i>Seat moulding</i>	<i>00</i> 60.20
<b>Listed Item Total</b>			4964.00
<b>*Less 20%</b>			992.80
			3971.20

S/NO	QTY	SPECIAL NETT ITEM	AMOUNT (S\$)
01	1 pc	Rear Windscreen <i>Gum sealant</i>	<i>00</i> 30.00 ✓
02	1 Set	Rear Bumper Sensor	<i>SWD</i> 300.00 200
<b>Special Nett Item Total</b>			330.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts used are subject to confirmation
- Total repair cost is on a "Without Prejudice" basis
- No further claim(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*23471  
202  
2776.80  
4852.80  
3855*

# prof automotive

S/NO	LABOUR	AMOUNT (S\$)	
01	Panel Beating	1400.00	800
02	Check Wiring	60.00	20
03	Rust Proofing	60.00	✓
04	Remove and Replace bumper sensor	80.00	50
05	Spray Painting	1200.00	800
06	Remove and Refit rear windscreen	160.00	120
	<b>Labour Total</b>	<b>2960.00</b>	
	<b>Grand Total</b>	<b>72 61.20</b>	

7551.50

7590.08



21 October 2019

Your Ref: Your insured SKA3950C  
Our Ref: PA191001-SFH8178E

Accident Date: 15-10-2019  
Vehicle No: SFH8178E  
Make/Model: Honda Vezel 1.5X  
Name: Homan Distance Solution  
Address: c/o 10 Kaki Bukit Road 2 #01-03 Singapore 417868

**SUPPLEMEANTARY**

S/NO	QTY	LISTED ITEM	AMOUNT (S\$)
01	1 pc	Rear Boot Inner Tool Tray	<i>one</i> 362..90
		<b>Listed Item Total</b>	362.90
		<b>*Less 20%</b>	75.60
			290.30

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/SMO19018396/UVF3N2  
**Date:** 30/10/2019

#### REFERENCE

<b>Handling Insurer:</b> Sompoo Insurance Singapore Pte. Ltd.	<b>Policy No:</b> D18MTPV01020224		
<b>Claimant Vehicle No :</b> SFH8178E	<b>Insured Vehicle No :</b> SKA3950C		
<b>Date of Loss:</b> 15/10/2019	<b>Nature of Claim:</b> TP	<b>Claim No:</b> CMTD1904898	

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b> SFH8178E		<b>Engine No:</b> LEB5957607	
<b>Make &amp; Model:</b> HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)		<b>Chassis No:</b> RU31257589	
<b>Reg. Date:</b> 09/02/2018 (Man. Year: 2017)		<b>Odometer:</b> 166419 km	
<b>Colour:</b> Black			
<b>Engine Capacity:</b> 1496 cc			
<b>Market Value/New Car Price:</b> N/A			
<b>Sum Insured (S\$):</b> Market Value/New Car Price			

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b> Yes	<b>Footbrake (Serviceable):</b> Yes	
<b>Handbrake (Serviceable):</b> Yes	<b>Engine Modification:</b> No	<b>Pre-accident Condition:</b>	

#### CONDITION OF TYRES

<b>Front Tyre Size:</b> 215/60R16	<b>Rear Tyre Size:</b> 215/60R16		
<b>Front Left Side:</b> Falken 6 mm	<b>Rear Left Side:</b> Falken 6 mm		
<b>Front Right Side:</b> Falken 6 mm	<b>Rear Right Side:</b> Falken 6 mm		

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,630.08	3,006.80	1,623.28	35.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,850.00	1,110.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,590.08</b>	<b>4,856.80</b>	<b>2,733.28</b>	<b>36.01</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,850.00</b>		
	(S\$) 7,590.08	3,850.00	3,740.08	49.28
	<b>+ GST 7.00/7.00% (S\$)</b> 531.31	269.50	261.81	49.28
	<b>Nett Amount (S\$)</b> 8,121.39	<b>4,119.50</b>	<b>4,001.89</b>	<b>49.28</b>

#### INSPECTION

<b>Date of Assignment:</b> 17/10/2019			
<b>Date Inspected:</b> 21/10/2019	<b>Inspected At:</b>	Profi Automotive (KB) BLK 10 KAKI BUKIT ROAD 2, #01-03 FIRST EAST CENTRE Singapore 417868	

**Estimated Period of Repair:** 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2019)
<b>Parts:</b> 144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFH8178E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,210.80 FL	*953.00 FL
2	1		*REAR BOOT LOCK	Twisted/Shorted	200.90 FL	*200.90 FL
3	1		*REAR BOOT LOCK CATCH	Not Necessary	53.60 FL	*- FL
4	1		*REAR BOOT RUBBER	Twisted	148.70 FL	*148.70 FL
5	1		*REAR BOOT EMBLEM (VEZEL)	Necessary	56.20 FL	*56.20 FL
6	1		*REAR BOOT EMBLEM (HYBRID)	Necessary	57.40 FL	*57.40 FL
7	1		*REAR BOOT INNER COVER BOARD	Serviceable	405.20 FL	*- FL
8	1		*REAR BOOT INNER PULL HANDLE GARNISH	Not Necessary	53.20 FL	*- FL
9	1		*REAR END PANEL	Badly Dented	675.30 FL	*517.00 FL
10	1		*REAR END PANEL TOP GARNISH	Twisted	219.30 FL	*219.30 FL
11	1		*REAR BUMPER	Dented/Deformed	949.80 FL	*721.00 FL
12	2		*REAR SIDE BUMPER	Repair	650.80 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER	Not Necessary	96.40 FL	*- FL
14	1		*REAR BUMPER UNDER COVER	Twisted	174.40 FL	*174.40 FL
15	1		*SET REAR WINDSCREEN MOULDING	Necessary	60.20 FL	*60.20 FL
16	1		*REAR WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS
17	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS
18	1		*REAR BOOT INNER TOOL TRAY	Cracked	362.90 FL	*362.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,705.10</b>	<b>3,701.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>1,075.02</b>	<b>694.20</b>
<b>Total Parts (\$)</b>	<b>4,630.08</b>	<b>3,006.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,400.00	800.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	60.00
4	REMOVE AND REPLACE BUMPER SENSOR	New	80.00	50.00
5	SPRAY PAINTING	New	1,200.00	800.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	160.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>2,960.00</b>	<b>1,850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >