

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53134
Date Estimated : 18/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ng Song Herng
38 Jalan Dermawan

Singapore 668983

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ3128J	WBAJG12040EE74913	29/03/2018	X1 sDrive18i	0

DESCRIPTION

To replace front bumper, bonnet, air duct and attachments.

Painting front bumper and bonnet.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To replace left headlight.

To supply front emboss number plate.

To carry out body cavity preservation. (Per panel).

Sundries.

VALUE

3825 5,100.00

2102 2,336.00

150 177.00

408 481.00

bt 83.00

100 118.00

? 150.00

Total Labour 1: 8,445.00

DESCRIPTION

CHARGE AIR COOLER
IMPACT ABSORBER TOP
FRT BUMPER TOP CARRIER
GRID CENTRE OPEN (BASIS/X LINE)
FRT LH BOTTOM DEFORMATION ELEMENT
FRT LH GRILLE (X LINE)
FRT RH GRILLE (X LINE)
TRIM PANEL AIRDUCT (X LINE)
FRT BUMPER PANEL PRIMED (PDC/PMA)
LH OPEN GRID (BASIS PDC)
FRT BUMPER PANEL LOWER SECTION (PDC)
FRT BUMPER BOTTOM CARRIER (M)
LICENCE PLATE HOLDER ECE
BMW PLAQUE WITH ADHESIVE FILM
AIR DUCT

QTY PRIC

1 593.65
1 60.15
1 373.95
1 110.85
1 85.45
1 121.85
1 121.85
1 224.25
1 854.55
1 111.45
1 213.65
1 145.55
1 70.65
1 71.25
1 270.55

VALUE

? 593.65
cna 60.15
? 373.95
? 110.85
? 85.45
cna 121.85
cna 121.85
224.25
de 854.55
inf 111.45
de 213.65
bt 145.55
de 70.65
ney 71.25
? 270.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53134**
Date Estimated : **18/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ3128J	WBAJG12040EE74913	29/03/2018	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
LH HEADLIGHT LED TECHNOLOGY	1	2,670.85	<i>ent</i> 2,670.85
LH FOGLAMP	1	281.85	? 281.85
Total Parts :			6,382.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 18/10/19 2410 Claim No. to be advise.

Date & Time 18/10/19 2410 Excess S\$ to be advise.

Surveyor's Name Tan Jia Sign Tan Jia

Surveyor's Tel 9749549 Authorised Yes / No

Authorised Date Not Authorise Time Revert

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Tan Jia @ Thurasamy.com

No. of Working Days Recommend 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,445.00
Parts	:	6,382.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,037.91
Grand Total	:	15,865.26

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **