

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 21 Oct 2019

Preliminary Advice

Insured Vehicle No : GT4238S

TP Vehicle No : SMJ5683P

Make : HONDA FIT

Date of Inspection : 18/10/2019

Inspection At : Advance Auto Garage (HQ)

23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE
Singapore 415933

Accident Date : 16/10/2019

Assignment Date : 18/10/2019

Est. Duration of Repair : 6 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,528.00
Revised Amount	:S\$	5,400.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,400.04

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.