

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

31-12-19

Accident Date : 04-10-2019

OUR REF : SMF 4844U/T/19

WANG LEI

Blk 114 Hougang Ave 1

#04-1294

Singapore 530114

Lkk. Adrian

Date In/Out: 05/11/19 to 12/11/19

TPCHING

Jhone

ESTIMATE BILL ON VEH NO. : SMF 4844U

MODEL : HONDA VEZEL

CHASSIS NO. : RU11309528

LIST ITEM

Bonnet	Repair		X	892.50
Bonnet Inner Center Rubber			X	381.90
Bonnet Inner Center Rubber Clips	2 N-P rec	4pcs @ 3.90	X	15.60
Head Lamp Assy LH	cracked		✓	1,859.20
Head Lamp Lower Bracket	cracked		✓	35.60
Front Grille (Outer)	cracked		✓	440.50
Front Grille (Inner)	cracked		✓	380.00
Front Grille Badge	2 N-P rec		✓	27.40
Front Grille Clips		5pcs @ 3.90	✓	19.50
Front Grille Center Bracket (Top)	all in		X	40.10
Front Grille Center Bracket (Bottom)	cracked		✓	35.00
Front Bumper Fascia	replaced	3621.80	762	927.50
Front Bumper Side Retainer	new	2897.44	✓	23.60
Front Bumper Reinforcement	new		X	360.80
Front Bumper Clips	new	10pcs @ 3.90	✓	39.00

5,478.20

Less Discount 20%:

1,095.64

4,382.56

SPECIAL NETT ITEM

Front Number Plate *Not Me*

X 35.00

LABOUR CHARGE

To check wiring system

300 ~~50.00~~

To respray affected areas

400 ~~750.00~~

To renew damaged parts, straighten & repair front support panel
and aligned all parts

300 ~~650.00~~

750

To reset head lamp module system

50 ~~250.00~~

6,117.56

GST 7% : 428.23

AMOUNT DUE: 6,545.79

total: 3647.44
L/S: 2.9K ✓
04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: