

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 17-Oct-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
Vic			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMF4071H		
MODEL	: TOYOTA PRIUS ALPHA		
CHASSIS NO			ZVW400030039.
<u>ACCIDENT DETAILS</u>		DATE	: 16-Oct-19
		TIME	: 1850HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Perked</i>	1	\$ 1,455.90	\$ 1,455.90
2	TAILGATE LOGO <i>Not Nu</i>	1	\$ 72.10	\$ 72.10
3	TAILGATE EMBLEM 'PRIUS' <i>Nu</i>	1	\$ 68.00	\$ 68.00
4	TAILGATE EMBLEM 'HYBRID SYNERGY DRIVE' <i>Nu</i>	1	\$ 60.00	\$ 60.00
5	TAILGATE LOCK <i>Dangd</i>	1	\$ 360.00	\$ 360.00
6	BOOTLID INNER BOARD <i>Can'd</i>	1	\$ 530.00	\$ 530.00
7	TAILGATE WEATHERSTRIPE <i>let</i>	1	\$ 320.00	\$ 320.00
8	TAILGATE WINDSCREEN MOULDING <i>Nu</i>	1	\$ 155.60	\$ 155.60
9	REAR BUMPER <i>Perked</i>	1	\$ 820.00	\$ 820.00
10	REAR BUMPER SIDE RETAINER <i>Not Nu</i>	2	\$ 60.30	\$ 120.60
11	TAILLAMP <i>RH can'd</i>	2	\$ 630.00	\$ 1,260.00
12	TAILLAMP LOWER BRACKET <i>RH can'd</i>	2	\$ 80.00	\$ 160.00
13	REAR END PANEL <i>Perked</i>	1	\$ 630.00	\$ 630.00
14	REAR END PANEL TOP GARNISH <i>Perked</i>	1	\$ 255.80	\$ 255.80
15	REAR TOOLS TRAY <i>Perked</i>	1	\$ 430.00	\$ 430.00

5755.30

4346.47

TOTAL PRICE \$ 6,698.00
LESS 25% \$ 1,674.50

SUB TOTAL PRICE \$ 5,023.50

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not New</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE SEALANT <i>Not New</i>	1	\$ 120.00	\$ 120.00
3	TAILGATE INNER BOARD CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
4	TAILGATE WINDSCREEN SEALANT <i>3 New</i>	1	\$ 120.00	\$ 120.00
5	TAILGATE WINDSCREEN INNER SEAL	1	\$ 150.00	\$ 150.00
6	REAR BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
7	TAILLAMP SEALANT <i>New</i>	2	\$ 120.00	\$ 240.00
8	REAR END PANEL INSULATOR SEAL <i>New</i>	1	\$ 150.00	\$ 150.00
9	REAR END PANEL TOP GARNISH CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
10	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

390

TOTAL \$ 1,110.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 180.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
7	TRANSFER TAILGATE MECHANISM	\$ 120.00	60	
8	REMOVE AND REFIX REAR WINDSCREEN	\$ 160.00	120	
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 220.00	X	

TOTAL

\$4,350.00

1920

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,133.50
TOTAL LABOUR COST : \$ 4,350.00
TOTAL REPAIR COST : \$ 10,483.50

APPROVED DETAILS

SURVEYOR :

Adrian Ling
total: 6656.47
L/S 53K
L/S 17/10/19.
06 Days.

CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS :

FAX :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification is allowed
- Supplementary items are not resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: