

khanchra



陳林摩呀私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLQ6832U

Date of Accident : 12 October 2019

Steve (LKK) W/L P47-L  
83228813 3 days  
L/S

17/10/19, 10.30 am

Mr Quek Chee Wei

Date : 14 October 2019

Ry AL SM

Estimate To Repair SJM7507Y - SUBARU IMPREZA 4DR 1.5R AWD 4AT ABS A  
Chassis No : JF1GE3KS59G003694

| S/No                              | Quantity       | Description                                                                                                             | Amount                     |
|-----------------------------------|----------------|-------------------------------------------------------------------------------------------------------------------------|----------------------------|
| <u>LIST ITEMS</u>                 |                |                                                                                                                         |                            |
| 01                                | 1 pc           | rear bumper ✓ 00                                                                                                        | \$ 588.60 ✓                |
| 02                                | 1 pc           | rear reinforcement ? / 00                                                                                               | \$ 208.80 ✓                |
| 03                                | 2 ps           | rear bumper reflector @ \$21.60 X NAI                                                                                   | \$ 43.20 X                 |
| 04                                | 1 pc           | rear bumper tow cover / CR4                                                                                             | \$ 16.00 ✓                 |
| 05                                | 16 ps<br>1 set | rear bumper fastener clips @ \$2.40 / 11pc                                                                              | \$ 38.40 ✓                 |
| Less 20 %                         |                |                                                                                                                         | \$ 895.00                  |
|                                   |                |                                                                                                                         | \$ 179.00                  |
|                                   |                |                                                                                                                         | \$ 716.00                  |
| <u>SPECIAL NETT ITEMS</u>         |                |                                                                                                                         |                            |
| 06                                | 1 set          | rear bumper parking sensor ✓ shut 908.80<br>- 20%<br>727.04                                                             | \$ 450.00 200<br>\$ 450.00 |
| <u>LABOUR &amp; MISC. CHARGES</u> |                |                                                                                                                         |                            |
| 01                                |                | To reinstall of rear bumper parking sensor.                                                                             | \$ 80.00 20                |
| 02                                |                | To check electrical lighting concerned.                                                                                 | \$ 60.00 30                |
| 03                                |                | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 500.00 300              |
| 04                                |                | Putty and spray painting of the affected portion.                                                                       | \$ 500.00 380              |
| Total                             |                |                                                                                                                         | \$ 1,140.00 730            |
|                                   |                |                                                                                                                         | \$ 2,306.00                |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 727.04  
AI- 290  
L- 730  
1657.04  
L/S- 1325.63  
= 1350