



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLQ6832U

Date of Accident : 12 October 2019

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Steve (LKK) W/L 17/10/19, 10.30 am
8322 8813 3 days
L/S
Ry AL SM

Mr Quek Chee Wei

Date : 14 October 2019

Estimate To Repair SJM7507Y - SUBARU IMPREZA 4DR 1.5R AWD 4AT ABS A

Chassis No : JF1GE3KS59G003694

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper ✓ 00	\$ 588.60
02	1 pc	rear reinforcement ?	\$ 208.80
03	2 ps	rear bumper reflector @ \$21.60 X	\$ 43.20
04	1 pc	rear bumper tow cover ✓ CR4	\$ 16.00
05	16 ps 1 Jp	rear bumper fastener clips @ \$2.40	\$ 301 38.40
			\$ 895.00
		Less 20 %	\$ 179.00
			\$ 716.00
		<u>SPECIAL NETT ITEMS</u>	
06	1 set	rear bumper parking sensor ✓ Shd	\$ 450.00 200
			\$ 450.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 80.00 20
02		To check electrical lighting concerned.	\$ 60.00 30
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00 300
04		Putty and spray painting of the affected portion.	\$ 500.00 380
			\$ 1,140.00
		Total	\$ 2,306.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: