



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 6532 H

Not Authorised

Parts	(a) Cost / List Price Items	\$	4,969.40
	Plus/Less 25%	\$	1,242.35
	Total of Cost / List	\$	3,727.05
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	3,772.05
Labour		\$	900.00
Total		\$	4,672.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

18/10/19

at

11.50am

Remarks By Surveyor

(a) The repair of this vehicle is *authorized* / is not authorized until further notice.

(b) Recommended Days of Repair : *02* day(s)

(c) Resurvey : Required / *Not Required*

(d) Excess : \$

(e) Signature of surveyor

Le

Date:

18/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMA 6532 H**
Make & Model : **TOYOTA PRIUS**
Chassis No : **ZVW508036536**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		✓
3	Headlamp panel LH	1	\$89.20		X
4	Headlamp LH	1	\$2,531.60		?
5	Front bumper	1	\$450.80		?
6	Front bumper clip	10	\$40.00		?
7	Front bumper reinforcement - upper	1	\$711.50		?
8	Front bumper reinforcement - lower	1	\$245.30		?
9	Front bumper side retainer RH	1	\$107.20		X
10	Front bumper side retainer LH	1	\$107.20		X
11	Front bumper upper grille	1	\$321.90		✓
12	Front bumper lower grille	1	\$148.60		X
13	Front bumper emblem	1	\$87.10		?
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

