



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 6532 H

Parts	(a) Cost / List Price Items	<u>\$ 2987.00</u>	4,969.40
	Plus/Less 25%	<u>\$ 745.63</u>	1,242.35
	Total of Cost / List	<u>\$ 2236.87</u>	3,727.05
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	<u>\$ 45.00</u>	45.00
	Total Parts Cost	<u>\$ 2281.87</u>	3,772.05
	Labour	<u>\$ 440.00</u>	900.00
	Total	<u>\$ 2721.87</u>	4,672.05

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / Is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 18/10/19

Not authorize

Question Mark item:

* Head lamp LH } take out
* Front Bumper } and take photo

* If cracked, please take cracked photo.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : SMA 6532 H
Make & Model : TOYOTA PRIUS
Chassis No : ZVW508036536

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		✓
3	Headlamp panel LH	1	\$89.20		X
4	Headlamp LH	1	\$2,531.60		X
5	Front bumper	1	\$450.80		X
6	Front bumper clip	10	\$40.00		X
7	Front bumper reinforcement - upper	1	\$711.50		X
8	Front bumper reinforcement - lower	1	\$245.30		X
9	Front bumper side retainer RH	1	\$107.20		X
10	Front bumper side retainer LH	1	\$107.20		X
11	Front bumper upper grille	1	\$321.90		✓
12	Front bumper lower grille	1	\$148.60		X
13	Front bumper emblem	1	\$87.10		X
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

7477 SD

455N



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Vehicle No. : SMA 6532 H Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

440