

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Tel: 8269-9999 Email: estimate.tap@gmail.com /teamautopl@gmail.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____ After-Paint: _____
Contacts : _____

Vehicle Nos : **SLQ 6869 P**
Made : Toyota
Model : CHR Hybrid 1.8
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 1,124.50	\$ 1,124.50
2	Rear bumper lower lid	1	\$ 465.00	\$ 360.20 465.00
3	Rear bumper reinforcement	1	\$ 498.50	\$ 456.00 498.50
4	Rear bumper inner S-side bracket	2	\$ 104.20	\$ 208.40
5	Rear bumper retainer	2	\$ 38.00	\$ 76.00
6	Rear bumper tow cover	1	\$ 35.00	\$ 35.00
7	Rear bumper reflector	2	\$ 146.00	\$ 292.00
8	Rear bumper reflector garnish 1 RH	1	\$ 125.60	\$ 125.60 270.00
9	Rear end panel	1	\$ 498.50	\$ 380.00 498.50
10	Rear end panel top garnish	1	\$ 185.70	\$ 185.70
11	Tail gate lock sensor	1	\$ 275.40	\$ 240.00 275.40
12	Tail gate inner lock	1	\$ 364.50	\$ 364.50
13	Tail gate striker	1	\$ 106.90	\$ 106.90
14	Tailgate damper	2	\$ 187.50	\$ 375.00
15	Tailgate trimboard	1	\$ 267.80	\$ 267.80
16	Tail gate	1	\$ 1,245.50	\$ 1,200.00 1,245.50
17	Tail gate logo	1	\$ 48.50	\$ 48.50
18	Tailgate emblem "C-HR"	1	\$ 129.60	\$ 83.20 129.60
19	Tailgate emblem "Hybrid synergy drive"	1	\$ 106.30	\$ 71.00 106.30
20	Tailgate lamp RH 1	1	\$ 353.50	\$ 353.50 778.00
21	Rear exhaust assy	1	\$ 987.00	\$ 987.00
22	Tail lamp RH 1	1	\$ 403.10	\$ 403.10 964.40
23	Tail lamp garnish	2	\$ 125.00	\$ 250.00
Parts Sub Total :				\$ 6,761.60 9,552.50
Discount 25%				\$ 1,690.40 2,388.13
PARTS TOTAL :				\$ 5,071.20 7,164.38

DDV ✓
DDV ✓
BT ✓
NAX ✓
NECV ✓
DLV ✓
NAX ✓
BRV ✓
DDV ✓
BBV ✓
BRV ✓
DDV ✓
NDMX ✓
NDMX ✓
BRV ✓
DDV ✓
NECV ✓
CUTV ✓
BT ✓
BRV ✓
NDMX ✓

5071.20

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear bumper clips	1set	\$ 50.00	\$ 30.00 50.00
2	Reverse sensor	4	\$ 180.00	\$ 200.00 720.00
3	Tail gate inner trimboard clips	1	\$ 50.00	\$ 30.00 50.00
4	Sundries	1	\$ 50.00	\$ 50.00
5	Tail lamp seal	2	\$ 50.00	\$ 100.00
6	Tail gate reflector seal	2	\$ 30.00	\$ 60.00
7	Tail gate sealant	2	\$ 100.00	\$ 60.00 200.00
8	Rear end panel sealant	1	\$ 100.00	\$ 60.00 100.00
9	Reverse camera	1	\$ 280.00	\$ 280.00
10	Number plate	1	\$ 50.00	\$ 50.00
SPECIAL NETT TOTAL :				\$ 1,660.00

Nos.	LABOUR	S\$
1	To dismantle, replace, cut, weld, panel beat and straighten accident damaged portion	\$ 1,500.00 1,500.00
2	Putty and spray paint accident damaged portion including paint/materials	\$ 240.00 1,500.00
3	Apply rust proofing	\$ 60.00 100.00
4	To remove replace and respray rear bumper sensors with safety distance setting	\$ 60.00 120.00
5	Remove and rebuild rear exhaust system	\$ 50.00 120.00
6	To remove and refit rear tailgate components	\$ 80.00 200.00
7	Remove and replace reverse camera & conduct safety distance setting	\$ 120.00
7	Wiring and bulb checks	\$ 20.00
LABOUR TOTAL :		\$ 3,690.00

PARTS TOTAL : \$ 7,164.38 5071.20
 SPECIAL NETT TOTAL : \$ 1,660.00 380.00
 LABOUR TOTAL : \$ 3,690.00 2050.00
 GRAND TOTAL : \$ 12,514.38 7501.20
 1500.24
 6000.96

Survey 18/10/19
 1530 hrs

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

H/S 6,000/2 TGLim
 Re Survey on 30/10/19
 21/10/19
 1600 hrs
 Repair days 6