



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1389 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

ACCIDENT DATE : 16 October 2019
OWNER : Gary Saw Kay Hooi

REG NO. : SLQ 1622 S
MAKE/MODEL : BMW 730i

21 October 2019

Not Authorized
HKK
18/10/19
2/s \$66007 4day

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE WBATAD

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front headlamp -L/H 4688.22	5,847.60
1	Front bumper 1501.35	2,065.60
1	Front bumper lower grille -side	\$ 11 185.00 X
2	Front bumper PDC sensors	\$ 11 570.00 X
1	Front bumper side retainer	\$ 11 136.00 X
1	Front fender -L/H	1014.50
1	Front fender emblem	\$ 11 82.00 X
1	Front fender inner shield	\$ 11 181.56 X
1	Front alloy wheel rim -L/H 1150.00	1,274.70
1	Front wheel hub with bearing	\$ 11 709.30 X
1	Front shock absorber	\$ 11 1,026.90 X
1	Front knuckle arm	\$ 11 1,060.50 X
1	Front lower arm	\$ 11 653.70 X
1	Front top control arm	\$ 11 589.70 X
1	Front lower control arm	\$ 11 653.71 X
		\$ 16,050.77
		10% Less 5% \$ 802.54
		\$ 15,248.23

SPECIAL NETT ITEMS

1	Front tyre	\$ 550.00 X
		\$ 550.00

LABOUR CHARGES

1	To check wiring and resetting headlamps focusing.	\$ 80.00 20
2	To remove and refit front sensor.	\$ 150.00 50
3	To remove and refit front undercarriage.	\$ 450.00 X
4	To conduct wheel alignment.	\$ 180.00 60
5	To apply undercoating.	\$ 150.00 30
6	Panel beating.	\$ 1,600.00 300
7	To re-spray painting on the affected areas.	\$ 1,500.00 400
8	To diagnose erase fault memory after repair.	\$ 350.00 X
		\$ 4,460.00

GRAND TOTAL :

\$ 20,258.23

P-831107
10%
748896
860
P-832107
802
4160.54
860.00
5020.54