

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53104**
Date Estimated : **16/10/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -
Karthik Palaniramachandran
669A Edgefield Plains
#11-650

Singapore 821669

- ACCOUNT - 148376
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP9069S	WBAHS720905G663	22/06/2017	X1 sDrive20i	0

DESCRIPTION	ACCOUNT: 148376		NETT
	ORIGINAL PRICE	DISC. %	
To make good rear bumper and replace damaged parts including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	40.00	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# REAR BUMPER MIDDLE TRIM PANEL (PDC)	265.65	1.00	0	265.65
# REAR BUMPER BOTTOM TRIM PANEL (LINE	242.70	1.00	0	242.70
REAR LH REFLECTOR	38.70	1.00	0	38.70

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	547.05
Total Labour & Parts :	2,521.05
GST @7%:	176.47
Grand Total :	2,697.52

LOSS OF USE = \$100 X 3 DAYS
LTA SEARCH FEE = \$7.45

Handwritten notes and stamps on a grid:

- Top left: FAX TO FAX NO
- Top middle: Rasu / LKK
- Top right: 8/11/19 3
- Bottom left: FAX TO FAX NO
- Bottom middle: CONFIRMED
- Bottom right: FAX TO FAX NO

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53104**
Date Estimated : **16/10/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -
Karthik Palaniramachandran
669A Edgefield Plains
#11-650

Singapore 821669

- ACCOUNT - 148376
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP9069S	WBAHS720905G6633	22/06/2017	X1 sDrive20i	0

DESCRIPTION	ACCOUNT: 148376	
	ORIGINAL PRICE	DISC. % NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# REAR BUMPER MIDDLE TRIM PANEL (PDC)	265.65	1.00	0	265.65
# REAR BUMPER BOTTOM TRIM PANEL (LINE	242.70	1.00	0	242.70
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	508.35
Total Labour & Parts :	508.35