

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

not Adhant
LHR
2/2700
3dy.
22/10/19
Adhant Adhant rep.
DATE 17/10/2019

GBJ1311U TOYOTA HIACE

No	Qty	PARTICULAR	AMOUNT S\$
1	1	TAIL GATE	2,062.00
2	1	TAIL GATE TRIM BOARD	428.00
3	1	TAIL GATE LOCK	509.20
4	1	TAIL GATE LOCK CATCH	68.00
5	1	TAIL GATE DAMPER LH	269.80
6	1	TAIL GATE (HIACE) EMBLEM	125.00
7	1	TAIL GATE (LOGO) EMBLEM	165.00
8	1	REAR END PANEL OUTER	1,288.00
9	1	REAR BUMPER	1,260.00
10	2	REAR BUMPER SIDE RETAINER R+L	243.00
11	1	TAIL LAMP ASSY LH	786.00
			\$ 7,204.00
LESS 25%			\$ 1,801.00
			\$ 5,403.00

No	Qty	PARTICULAR	SPECIAL NETT	AMOUNT S\$
1	1	REAR WINDSCREEN GLASS SEALANT	nu	90.00
2	1	REAR WINDSCREEN GLASS INNER SEAL	nu	135.00
3	1	70 KM/H STICKER	nu	25.00
4	1	8 PAX STICKER	nu	25.00
5	8	TAIL GATE TRIM BOARD CLIP	11	48.00
6	1	REVERSE SENSOR	shnd 1set	250.00
				\$ 573.00

LABOUR & MISCELLANEOUS:

1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	300	900.00
2	To spray paint replaced/repainted body parts inclusive of preparatory works and painting materials	400	800.00
3	To transfer tail gate components with all necessary attachments	60	250.00
4	To remove,refix rear windscreen glass and water test	120	250.00
5	To install reverse sensor and test function	50	100.00
			\$ 2,300.00

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: P-2888.1

Date: 25/10/19

P-2163.82

SU 290.00

L-930.00

TOTAL 3383.82