

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo





Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/04/2019 16:07
Date Of Accident	11/04/2019 07:20
Exact Location Of Accident	PIONEER RDD TWDS JLN BUROH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM7677L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BUILDLINK CONSTRUCTION PRIVATED LIMITED
Co Reg No	200100073D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90842950
Alternative Phone No	OFFICE-90842950

### Vehicle Particulars

Manufacturer	ISUZU
Model	NHR85EU3ES
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	CV3/GA425961
Cover Note Number	

### Driver

Name of Driver	RUBAL MOHAMMAD
NRIC No	G2373375M
Date Of Birth	10/03/1994
Occupation	INDOOR
Date Of Driving Pass	23/10/2017
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90842950
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 212 HOUANG ST 21  
 Postcode 530212  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 6  
 Passenger 1 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 2 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 3 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 4 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 5 NAME: : UNKNOWN  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name NANYANG N.P.C  
 Police Station Address ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7929999 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO



Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	PC5085S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD AZLI BIN ZAHIS
NRIC/Passport Number	S8629904F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and Acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:

## Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was changing to right most lane after turned on my signal lamp. Suddenly CAR B collided into my rear left portion and caused my vehicle moving forward to opposite direction of the road.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

*Bub*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/Fin No.:

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20190411/2039

1 of 3

Report No. T/20190411/2039

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:  
11/04/2019 11:30

Vide Report No.:  
J/20190411/0035

Station Diary No.:  
44

Informant's Particulars

Name of Informant: RUBAL MOHAMMAD			Address:		
ID Type / ID No.: FIN NO / G2373375M			Contact No.: Home/Office: Mobile: 90842950		
Nationality: BANGLADESHI			Email:		
Sex: Male	Age: 25	Date of Birth: 10/03/1994	Type of Informant: Driver		
Race: Others			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/04/2019 07:20	Type of Location: Straight Road
Location: Along Road 1 PIONEER ROAD				
Twds Jln Buroh				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC5085S	Bus/Coach/Mi nibus				Slightly Damaged	0
YM7677L	Lorry				Slightly Damaged	4

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190411/2039

2 of 3

Report No. T/20190411/2039

Police Station Of Origin:  
Anyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	MUHAMMAD AZLI BIN ZAHIS	ID No.	S8629904F
Related Vehicle	PC5085S (Bus/Coach/Minibus)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	RUBAL MOHAMMAD	ID No.	G2373375M
Related Vehicle	YM7677L (Lorry)	Contact No.	90842950
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 11/04/2019, at about 0720hrs, I was driving my lorry, YM7677L, along Pioneer Road, when I was changing lane into Lane 1, when suddenly, a bus, PC5085S, collided with the rear right of my vehicle. During the collision, my vehicle turned and faced the opposite direction. I then stopped my vehicle and make check on my vehicle. I then saw one of my passenger, MANIK, HP: 8450 3711, fell down from my lorry. I saw blood coming out from his head. I then called for ambulance. I then checked with my other passengers and they complained of pain on their body.

I wish to come that there was ambulance and police at my scene. The ambulance conveyed MANIK to National University Hospital.



POLICE REPORT



T/20190411/2039

3 of 3

Report No. T/20190411/2039

POLICE FORCE

Station Of Origin:  
N.P.C  
West Avenue 5 SINGAPORE  
1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /  
MUHAMMAD IRFAN BIN MISRAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/04/2019 11:30

Officer In Charge Of Case:

TP / GIT /  
Sgt 3 RASHIDAH BINTE AZMAN  
Contact No.: 65476216

Classification Of Case:

SN 127

Authentication Stamp

NP168



Signature :

Singapore Police Force

Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo







RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-061407

Date of Request: 18/04/2019

Your Ref No: WALK IN NG

A-TEC AUTOMOTIVE PTE LTD  
1 KAKI BUKIT AVE 6 #02-11 AUTOBAY  
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: PC5085S

Date of Accident: 11/04/2019

Place of Accident: PIONEER RD

Involving Vehicle No: YM7677L

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-061408

Date of Request: 18/04/2019

Your Ref No: WALK IN NG

A-TEC AUTOMOTIVE PTE LTD  
1 KAKI BUKIT AVE 6 #02-11 AUTOBAY  
SINGAPORE 417883

Dear Sir/Madam,

Date of Accident: 11/04/2019

Vehicle No: PC5085S

Place of Accident: PIONEER RD TWDS JLN BUROH AFT JUNC OF TUAS RD NEAR

Involving Vehicle No: YM7677L

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
YM7677L	PIONEER RD TWDS JLN BUROH AFT JUNC OF TUAS RD NEAR	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[ ] GIRO [X] Cash [ ] Cheque

## Enquire Vehicle & Owner Information ( Vehicle No. YM7677L As At 11 Apr 2019 / 07:20:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MKR/404/8849/2019

### Current Owner Details

Owner ID Type: Company

Owner ID: 200100073D

Owner Name: BUILDINK CONSTRUCTION PRIVATE LIMITED

Registered Address Type: HDB / HUDC

Registered Block/House No.: 212

Registered Street Name: HOUGANG STREET 21

Registered Unit No.: # 03 - 333

Registered Building Name: -

Registered Postal Code: 530212

### Current Vehicle Details

Vehicle No.: YM7677L

Make Description/Model: ISUZU / NHR85EU3ES

Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Seah Siew Hoon has successfully logged out.

Your last login date and time was 16 Apr 2019, 18:03:14.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/Nc. 11	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction
1	Vehicle	YM7677L	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



**24 HOUR RECOVERY SERVICES**  
**24 HRS HOTLINE: 8455 5669**

Co Reg No: 533329290

No. 16368



Date : 16-4-19

M/S : CASH  
Vehicle No : PC 50855 Model : \_\_\_\_\_  
From : TP To Kaki St Ave Time Start : 1400  
To : To Kaki St #04-20 Time End : 1430  
Remarks : (A) 1500

- |  |   |   |                                 |
|--|---|---|---------------------------------|
| <input type="checkbox"/> Change Tyres / Jump Start | <input checked="" type="checkbox"/> Accident        | <input type="checkbox"/> Use Car Carrier      | <input type="checkbox"/> Loaded |
| <input type="checkbox"/> Basement / Multi Carpark  | <input type="checkbox"/> Low Bldg Kit / Low Spoiler | <input type="checkbox"/> Open Door            |                                 |
| <input type="checkbox"/> Using King Dolly          | <input type="checkbox"/> Dismantle Brake / Shaft    | <input type="checkbox"/> Crane Up / Winch Out |                                 |

**PAID**

16/4/19  
TP

AMOUNT S\$ 130 k

Woe

Received By \_\_\_\_\_

for 24 hour Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.



# DREAM CARZ LEASING PTE LTD

Company Registration: 201433037R

8 Kaki Bukit Ave 4, #04-20, Premier, Singapore 415875 Tel: (65) 63845206 Fax: (65) 63845205  
Email: dreamcarzleasing@gmail.com

## INVOICE

Muhammad Azli Bin Zahis  
Blk 489C Tampines Street 45  
#04-177  
Singapore 522489

Invoice No: 10641  
Invoice Date: 08-07-19  
Due Date: 08-07-19  
VHA No: 2310

### Description

Rental for	29	Days @	\$ 150.00 per Day	\$ 4,350.00
Vehicle No	PC1928L			
Vehicle Description	Toyota Hiace Hi Roof			
Rental Period	11-04-19	to	10-05-19	

Total Amount Payable \$ 4,350.00

8 Kaki Bukit Ave 4 #04-20 Premier Singapore 415875

Email: dreamcarzleasing@gmail.com


Tel: +65 6384 5206 Fax: +65 6384 5205

**DCL**  
**DREAM CARZ LEASING**  
PTE LTD

VHA No: 2310

ROC No: 201433037R

### VEHICLE RENTAL AGREEMENT


<b>HIRER'S PARTICULAR</b> Name: (as in I/C) <u>Muhammad Azli Bin Zahis</u> NRIC/PASSPORT No: <u>BK 4856 5862 99041</u> Address (Res): <u>BK 4856 Tampines St 45</u> <u>#04-177 Singapore 522489</u> Name & Address of Employer: _____ Occupation: _____ Driving Exp: _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Tel: (O) _____ (R) _____ HP / PG _____		Vehicle No: <u>PC1928L</u> Replace Veh No: <u>PC50858</u> Mileage Out: _____ Mileage Out: _____ Make & Model: <u>Toyota Hiace Hybrid</u> Auto / Manual Group: _____ Out Date: <u>11/4/2019</u> Time: _____ HIRE / PERIOD EXPIRY Time: _____ NON-WAIVER EXCESS = \$ <u>200</u>																																														
<b>ADDITIONAL DRIVER'S PARTICULARS</b> Name: (as in I/C) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Occupation: _____ Driving Exp: _____		<b>CHARGES</b> <table border="1"> <tr> <td>Daily</td> <td><u>29</u></td> <td>@ \$ <u>150</u></td> <td>per day</td> <td><u>\$4350</u></td> </tr> <tr> <td>Weekly</td> <td></td> <td>@ \$</td> <td>per week</td> <td></td> </tr> <tr> <td>Monthly</td> <td></td> <td>@ \$</td> <td>per month</td> <td></td> </tr> <tr> <td>Hours</td> <td></td> <td>@ \$</td> <td>per hour</td> <td></td> </tr> <tr> <td>Others</td> <td></td> <td>@ \$</td> <td></td> <td></td> </tr> <tr> <td>CDW</td> <td></td> <td>@ \$</td> <td>per day/month</td> <td></td> </tr> <tr> <td>PAI</td> <td></td> <td>@ \$</td> <td>per day/month</td> <td></td> </tr> <tr> <td colspan="4">Delivery/ Collection Service</td> <td></td> </tr> <tr> <td colspan="4"><b>SUB-TOTAL</b></td> <td>\$ <u>4350</u></td> </tr> </table>		Daily	<u>29</u>	@ \$ <u>150</u>	per day	<u>\$4350</u>	Weekly		@ \$	per week		Monthly		@ \$	per month		Hours		@ \$	per hour		Others		@ \$			CDW		@ \$	per day/month		PAI		@ \$	per day/month		Delivery/ Collection Service					<b>SUB-TOTAL</b>				\$ <u>4350</u>
Daily	<u>29</u>	@ \$ <u>150</u>	per day	<u>\$4350</u>																																												
Weekly		@ \$	per week																																													
Monthly		@ \$	per month																																													
Hours		@ \$	per hour																																													
Others		@ \$																																														
CDW		@ \$	per day/month																																													
PAI		@ \$	per day/month																																													
Delivery/ Collection Service																																																
<b>SUB-TOTAL</b>				\$ <u>4350</u>																																												
<b>VEHICLE CHECK LIST</b> INDICATE: D - DENTS S - SCRATCHES A - ACCIDENTS 		<b>PETROL LEVEL</b> <table border="1"> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td><u>3/4</u></td> <td>F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td><u>3/4</u></td> <td>F</td> </tr> </table> <b>EXTENSION</b> Misc. _____ <b>TOTAL CHARGES \$</b> _____		Out	E	1/4	1/2	<u>3/4</u>	F	In	E	1/4	1/2	<u>3/4</u>	F																																	
Out	E	1/4	1/2	<u>3/4</u>	F																																											
In	E	1/4	1/2	<u>3/4</u>	F																																											
<b>ACCESSORIES CHECK</b> <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		Hirer's Signature: <u>tylo</u> Additional Driver's Signature: _____ Authorised Person Signature: _____																																														

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/ credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/ credit card voucher. All information I have given Dream Carz Leasing Pte Ltd in connection with this agreement is true.

#### \*IMPORTANT

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

RETURN OF VEHICLE, THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN\* SINGAPORE OF HIRER / DRIVER \* FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	 SIGNATURE OF HIRER/DRIVER
<u>10/5/19</u>					



**A-Tec Automotive Pte Ltd**

8 Kaki Bukit Ave 4 #04-20 Premier Singapore 415875

Company Reg No: 201227298M

GST Reg No: 201227298M

EMAIL : atec\_automotive@yahoo.com.sg

TEL: 6384-5205

FAX: 6384-5205

NAME Sevilai Transport Pte Ltd

DATE : 08-07-19

PROFORMA TAX INVOICE 7298794

JOB NO.

ADDRESS : 18 Kaki Bukit Road 3  
Entrepreneur Business Centre  
Singapore 415978

VEHICLE NO.

PC5085S

MAKE&MODEL :

Joylong HKL6450RC

TERM

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	Lump Sum Repair As Per Surveyor Report			\$ 27,500.00
SUB-TOTAL				\$ 27,500.00
ADD GST 7%				\$ 1,925.00
TOTAL AMOUNT				\$ 29,425.00

**IMPORTANT**

Please remit payment within 7 days from the due date

All cheques must be made payable to **A-TEC AUTOMOTIVE PTE LTD**

*This a computer generated document.No signature is required.*



**SINCERE**  
APPRAISAL SERVICES PTE LTD

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel : 6636 4628 Fax : 6636 4638 E-mail : office@sincereappraisal.com.sg

## INVOICE

Sevilai Transport Pte Ltd  
C/O A-Tec Automotive Pte Ltd  
8 Kaki Bukit Avenue 4  
#04-20 Premier  
Singapore 415875

Invoice No: 270619-251  
Our ref: 251/TP/2019  
Date: 27/6/2019

Claim Type: Third Party	Date of Loss: 11/4/2019
Vehicle Reg No: PC5085S	Claimant: Sevilai Transport Pte Ltd
Vehicle Make/Model: Joylong HKL6540RC Manual	

Description	Amount (S\$)
1. Professional Fee (including Transport, 84 Photographs and Miscellaneous charges)	1309
<b>Total</b>	<b>1309</b>
Singapore Dollar: One thousand three hundred and nine dollars only.	

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd



Sincere Appraisal Services Pte Ltd



**SINCERE**  
APPRAISAL SERVICES PTE LTD

### VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 251/TP/2019

Date: 27/6/2019

#### REFERENCE

Date of loss: 11/4/2019  
Claimant: Sevilai Transport Pte Ltd

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC5085S	Make &	Joylong
Reg date:	5/8/2016	Model	HKL6540RC Manual
Colour:	White	Engine No:	ISF28S5129T89651481
Type:	Van	Chassis No:	LJSKA3BG9ED002578
Type of Claims:	Third Party	Odometer No:	malfunction
		Engine Cap.:	2776cc

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition:	Good	Steering:	Good	Engine Modification:	Nil
Paint work:	Good	Handbrake:	Good	Pre-accident	
		Footbrake:	Good	Damage:	Nil

#### CONDITION OF TYRES

Front Left Size:	Westlake 195/R15 70%	Front Right Size:	Westlake 195/R15 70%
Rear Left Size:	Westlake 195/R15 70%	Rear Right Size:	Westlake 195/R15 70%

*The above percentages represent the remaining life of the tyre threads*

#### COST OF REPAIRS


Parts	Repairer S\$	Adjuster S\$
	\$ 29,318.90	\$ 29,318.90
Labour	\$ 5,860.00	\$ 5,060.00
Calculated Cost (S\$) :	<u>\$ 35,178.90</u>	<u>\$ 34,378.90</u>

**Recommended Lump Sum Repair Cost (S\$) : \$ 27,500.00**

Date of Assignment: 17/4/2019  
Date Inspected: 17/4/2019  
Est. repair Period: 21 days

Inspected At: A-Tec Automotive Pte Ltd  
8 Kaki Bukit Avenue 4  
#04-20 Premier  
Singapore 415875

### POINT OF IMPACT

Damaged at the front portion	
------------------------------	--

### BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Pioneer Road towards Jalan Buroh after junction of Tuas Road.

### GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the front portion.

### SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$35,178.90. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$27,500.00.

We have not authorised the repair. Under normal circumstances, estimated **21** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



**Dave Chang**  
Automotive Appraiser  
AUTO. ENG, CAE, CGI  
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

*Please note that this report is solely based on our findings at the time and place of inspection stated herein. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.*



## ANNEX A

## REPAIR DETAILS

## Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy	deformed	\$ 986.00	\$ 986.00 ✓ 788
2	1 set	Front bumper retainer	bent/necessary	\$ 88.00	\$ 88.00 ✓
3	1	Front bumper reinforcement	deformed	\$ 355.00	\$ 355.00 ✓
4	1	Front panel assy <i>Repair</i>	deformed	\$ 1,127.00	\$ 1,127.00 ✓
5	1	Front left 'A' pillar	deformed	\$ 420.00	\$ 420.00 ✓
6	1	Front horn	malfunction	\$ 88.00	\$ 88.00 ✓
7	1	Front grille assy	missing	\$ 175.00	\$ 175.00 ✓
8	1	Front grille emblem	missing	\$ 66.00	\$ 66.00 ✓
9	1	Front left fog lamp	cracked	\$ 250.00	\$ 250.00 ✓
10	1	Front right fog lamp <i>Not Nec.</i>	cracked	\$ 250.00	\$ 250.00 ✓
11	1	Front left headlamp	cracked	\$ 2,675.00	\$ 2,675.00 ✓ 620
12	1	Front right headlamp	cracked	\$ 2,675.00	\$ 2,675.00 ✓ 620
13	1	Front windscreen glass assy	cracked	\$ 1,810.00	\$ 1,810.00 ✓
14	1	Front windscreen glass moulding	necessary	\$ 280.00	\$ 280.00 ✓
15	2	Front wiper arm <i>Not nec</i>	bent	\$ 120.00	\$ 120.00 ✓
16	2	Front wiper blade	bent	\$ 68.00	\$ 68.00 ✓
17	2	Front wiper nozzle <i>Not nec</i>	bent	\$ 48.00	\$ 48.00 ✓
18	1	Front wiper linkage <i>Not nec</i>	bent	\$ 226.00	\$ 226.00 ✓
19	1	Front wiper motor <i>Not nec</i>	malfunction	\$ 378.00	\$ 378.00 ✓
20	1	Front left wing mirror assy <i>Not nec</i>	bent	\$ 215.00	\$ 215.00 ✓
21	1	Front left door panel	buckled	\$ 1,658.00	\$ 1,658.00 ✓ 1298
22	1	Front left door lock	bent	\$ 126.00	\$ 126.00 ✓
23	1	Front left door inner trim board <i>Not nec</i>	cracked	\$ 394.00	\$ 394.00 ✓
24	1	Front left door outer moulding <i>Not nec</i>	bent/necessary	\$ 176.00	\$ 176.00 ✓
25	2	Front left door hinges	bent/necessary	\$ 110.00	\$ 110.00 ✓
26	1	Front left door checker linkage	bent/necessary	\$ 115.00	\$ 115.00 ✓
27	1	Front dashboard assy	deformed	\$ 1,403.00	\$ 1,403.00 ✓
28	1	Front instrument cluster <i>Not nec</i>	malfunction	\$ 928.00	\$ 928.00 ✓
29	1	Front instrument cluster outer cover	dislodged	\$ 200.00	\$ 200.00 ✓
30	1	Front left glove compartment	warped	\$ 150.00	\$ 150.00 ✓
31	1	Front top support panel assy	deformed	\$ 1,254.00	\$ 1,254.00 ✓ 850
32	1	Front bottom support panel assy	deformed	\$ 1,250.00	\$ 1,250.00 ✓ 650
33	1	Front support panel top garnish seal	necessary	\$ 88.00	\$ 88.00 ✓
				\$ 20,152.00	\$ 20,152.00
Less 10%				\$ 2,015.20	\$ 2,015.20
				\$ 18,136.80	\$ 18,136.80



## ANNEX A

## REPAIR DETAILS

## Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
34	1	Front air con condenser assy	cracked	\$ 1,350.00	\$ 1,350.00 ✓
35	1	Front air con suction pipe <i>3 new</i>	bent	\$ 320.00	\$ 320.00 ✗
36	1	Front air con discharge pipe	bent	\$ 320.00	\$ 320.00 ✗
37	1	Front air con evaporator assy	cracked	\$ 1,665.00	\$ 1,665.00 ✓
38	1	Front radiator assy	cracked	\$ 1,442.00	\$ 1,442.00 ✓
39	1 set	Front radiator cooling fan assy with motor assy	malfunction	\$ 1,672.00	\$ 1,672.00 ✗ <i>nn</i>
40	1	Front radiator expansion tank	bent	\$ 125.00	\$ 125.00 ✓
41	1	Front radiator top hose <i>3 new</i>	necessary	\$ 60.00	\$ 60.00 ✗
42	1	Front radiator bottom hose	necessary	\$ 60.00	\$ 60.00 ✗
43	1	Front secondary radiator assy	bent	\$ 1,129.00	\$ 1,129.00 ✓
44	1	Front secondary radiator cooling fan assy with motor <i>new</i>	malfunction/cracked	\$ 823.00	\$ 823.00 ✗
45	1	Front washer tank	warped	\$ 120.00	\$ 120.00 ✓
46	1	Front left corner panel	deformed	\$ 125.00	\$ 125.00 ✓
47	1	Front bonnet assy	deformed	\$ 1,450.00	\$ 1,450.00 ✓
48	1	Front wiper top garnish	bent	\$ 295.00	\$ 295.00 ✓
49	1	Front panel top beam	bent	\$ 198.00	\$ 198.00 ✓
50	2	Front support panel side garnish	warped/bent	\$ 65.00	\$ 65.00 ✓
51	2	Front bonnet hinges	bent	\$ 105.00	\$ 105.00 ✓
52	1	Front radiator cooling fan cowling	cracked	\$ 255.00	\$ 255.00 ✓
				\$ 11,579.00	\$ 11,579.00
Less 10%				\$ 1,157.90	\$ 1,157.90
				\$ 10,421.10	\$ 10,421.10

Special Nett Items

1	1	Front ERP unit <i>new</i>	malfunction	\$ 156.00	\$ 156.00 ✗
2	1	Front ERP unit bracket	necessary	\$ 25.00	\$ 25.00 ✓
3	10	Front bumper clips	necessary	\$ 50.00	\$ 50.00 <i>30</i>
4	1	Front radiator coolant	necessary	\$ 120.00	\$ 120.00 <i>50</i>
5	1	Front air con gas	necessary	\$ 120.00	\$ 120.00 <i>50</i>
6	4	Front grille clips	necessary	\$ 20.00	\$ 20.00 ✓
7	8	Front left door inner trim board clips	necessary	\$ 40.00	\$ 40.00 <i>30</i>
8	4	Front left door outer moulding clips <i>new</i>	necessary	\$ 20.00	\$ 20.00 ✗
9	20	Front instrument cluster outer cover clips	necessary	\$ 50.00	\$ 50.00 <i>30</i>
10	1	Front windscreen glass sealant	necessary	\$ 80.00	\$ 80.00 <i>60</i>
11	1	Front no plate	necessary	\$ 80.00	\$ 80.00 <i>50</i>
				\$ 761.00	\$ 761.00

## Total parts

\$ 29,318.90 \$ 29,318.90

# ANNEX B

## REPAIR DETAILS

### Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,800.00	\$ 1,600.00 1500.
2	To putty and spray painting front portion.	\$ 1,800.00	\$ 1,600.00 1500
3	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00 ✓
4	To remove and install air con system to facilitate the repair and refill gas.	\$ 180.00	\$ 150.00 80
5	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 180.00	\$ 150.00 80.
6	To remove and install front dashboard assy including instrument cluster and reset system.	\$ 350.00	\$ 300.00 220
7	To remove and install front air con evaporator assy and refill gas.	\$ 180.00	\$ 150.00 ✓
8	To repair, straighten and align front right door panel.	\$ 180.00	\$ 150.00 x
9	To apply anti rust proofing to front affected area.	\$ 150.00	\$ 120.00 ✓
10	To remove and install front left door lock mechanism.	\$ 80.00	\$ 60.00 30
11	To transfer door glass to new door.	\$ 80.00	\$ 60.00 30
12	To check door central locking for function.	\$ 80.00	\$ 60.00 ✓
13	To remove and install front windscreen glass to facilitate the repair.	\$ 140.00	\$ 120.00 ✓
14	To conduct chassis alignment.	\$ 350.00	\$ 300.00 ✓
15	To remove and install front lock mechanism.	\$ 80.00	\$ 60.00 30.
16	Towing service.	\$ 180.00	\$ 150.00 ✓
Total labour :		\$ 5,860.00	\$ 5,060.00

# ANNEX C

## REPAIR DETAILS

### Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$29,318.90	\$ 29,318.90
Total labour :	\$ 5,860.00	\$ 5,060.00
Total repair cost :	\$35,178.90	\$ 34,378.90

Adjusted Repair Cost (Lump Sum Repair)

\$ 27,500.00

total: 21612.80  
 4/5: 15K (Nett Value)  
 21 Days



Your Ref: 19.27316 V.S.CK.xy

Date: 11<sup>th</sup> February 2020

Our Ref: CS3/ASM19007019/Asd3s2-1

**M/s AXA Insurance Pte Ltd**  
C/o: Seah Ong & Partners LLP  
36 Robinson Road  
#12-03 City House  
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PC 5085S  
INSURED VEHICLE: YM 7677L ACCIDENT DATE: 11/04/2019**

We thank you for your instruction on 10/10/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PC 5085S from M/s Sincere Appraisal Services Pte Ltd.
- b) Final Repair Bill of PC 5085S from M/s A-Tec Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles PC 5085S and YM 7677L.
- d) Colour damaged vehicle photographs of PC 5085S.

Pre-Repair Inspection Date: 18/04/2019 at M/s A-Tec Automotive Pte Ltd, 8 Kaki Bukit Ave 4  
#04-20 Premier Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PC 5085S
Make & Model	: Joylong HKL6540
Year of Registration	: 2016
Chassis Number	: LJSKA3BG9ED002578
Engine Capacity	: 2776 cc
2. We recommend that the repairs of the entire damage require about 21 (Twenty-One) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5085S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT BUMPER ASSY	DEFORMED	986.00	788.00
1	SET FRONT BUMPER RETAINER	BENT / NECESSARY	88.00	88.00
1	FRONT BUMPER REINFORCEMENT	DEFORMED	355.00	355.00
1	FRONT PANEL ASSY	TO REPAIR SEE LABOUR	1,127.00	-
1	FRONT LEFT 'A' PILLAR	DEFORMED	420.00	420.00
1	FRONT HORN	MALFUNCTION	88.00	88.00
1	FRONT GRILLE ASSY	MISSING	175.00	175.00
1	FRONT GRILLE EMBLEM	MISSING	66.00	66.00
1	FRONT LEFT FOG LAMP	CRACKED	250.00	250.00
1	FRONT RIGHT FOG LAMP	NOT NECESSARY	250.00	-
1	FRONT LEFT HEADLAMP	CRACKED	2,675.00	620.00
1	FRONT RIGHT HEADLAMP	CRACKED	2,675.00	620.00
1	FRONT WINDSCREEN GLASS ASSY	CRACKED	1,810.00	1,810.00
1	FRONT WINDSCREEN GLASS MOULDING	NECESSARY	280.00	280.00
2	FRONT WIPER ARM	NOT NECESSARY	120.00	-
2	FRONT WIPER BLADE	BENT	68.00	68.00
2	FRONT WIPER NOZZLE	NOT NECESSARY	48.00	-
1	FRONT WIPER LINKAGE	NOT NECESSARY	226.00	-
1	FRONT WIPER MOTOR	MALFUNCTION	378.00	-
1	FRONT LEFT WING MIRROR ASSY	NOT NECESSARY	215.00	-
1	FRONT LEFT DOOR PANEL	BUCKLED	1,658.00	1,298.00
1	FRONT LEFT DOOR LOCK	BENT	126.00	126.00
1	FRONT LEFT DOOR INNER TRIM BOARD	NOT NECESSARY	394.00	-
1	FRONT LEFT DOOR OUTER MOULDING	NOT NECESSARY	176.00	-
2	FRONT LEFT DOOR HINGES	BENT / NECESSARY	110.00	110.00
1	FRONT LEFT DOOR CHECKER LINKAGE	BENT / NECESSARY	115.00	115.00
1	FRONT DASHBOARD ASSY	DEFORMED	1,403.00	1,403.00
1	FRONT INSTRUMENT CLUSTER	NOT NECESSARY	928.00	-
1	FRONT INSTRUMENT CLUSTER OUTER COVER	NOT NECESSARY	200.00	-
1	FRONT LEFT GLOVE COMPARTMENT	WARPED	150.00	150.00
1	FRONT TOP SUPPORT PANEL ASSY	DEFORMED	1,254.00	850.00

Report Ref No. CS3/ASM19007019/Asd3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BOTTOM SUPPORT PANEL ASSY	DEFORMED	1,250.00	650.00
1	FRONT SUPPORT PANEL TOP GARNISH SEAL	NECESSARY	88.00	88.00
1	FRONT AIR CON CONDENSER ASSY	CRACKED	1,350.00	1,350.00
1	FRONT AIR CON SUCTION PIPE	NOT NECESSARY	320.00	-
1	FRONT AIR CON DISCHARGE PIPE	NOT NECESSARY	320.00	-
1	FRONT AIR CON EVAPORATOR ASSY	CRACKED	1,665.00	1,665.00
1	FRONT RADIATOR ASSY	CRACKED	1,442.00	1,442.00
1	SET FRONT RADIATOR COOLING FAN ASSY WITH MOTOR ASSY	NOT NECESSARY	1,672.00	-
1	FRONT RADIATOR EXPANSION TANK	BENT	125.00	125.00
1	FRONT RADIATOR TOP HOSE	NOT NECESSARY	60.00	-
1	FRONT RADIATOR BOTTOM HOSE	NOT NECESSARY	60.00	-
1	FRONT SECONDARY RADIATOR ASSY	BENT	1,129.00	1,129.00
1	FRONT SENCODARY RADIATOR COOLING FAN ASSY WITH MOTOR	NOT NECESSARY	823.00	-
1	FRONT WASHER TANK	WARPED	120.00	120.00
1	FRONT LEFT CORNER PANEL	DEFORMED	125.00	125.00
1	FRONT BONNET ASSY	DEFORMED	1,450.00	1,450.00
1	FRONT WIPER TOP GARNISH	BENT	295.00	295.00
1	FRONT PANEL TOP BEAM	BENT	198.00	198.00
2	FRONT SUPPORT PANEL SIDE GARNISH	WARPED / BENT	65.00	65.00
2	FRONT BONNET HINGES	BENT	105.00	105.00
1	FRONT RADIATOR COOLING FAN COWLING	CRACKED	255.00	255.00
	LESS 10% DISCOUNT		-3,173.10	-1,874.20
			28,557.90	16,867.80
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT ERP UNIT (SN)	NOT NECESSARY	156.00	-
1	FRONT ERP UNIT BRACKET (SN)	NECESSARY	25.00	25.00
10	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT RADIATOR COOLANT (SN)	NECESSARY	120.00	50.00
1	FRONT AIR CON GAS (SN)	NECESSARY	120.00	50.00
4	FRONT GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
8	FRONT LEFT DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	40.00	30.00
4	FRONT LEFT DOOR OUTER MOULDING CLIPS (SN)	NOT NECESSARY	20.00	-
20	FRONT INSTRUMENT CLUSTER OUTER COVER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	60.00

Report Ref No. CS3/ASM19007019/Asd3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NO PLATE (SN)	NECESSARY	80.00	50.00
			761.00	345.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT PANEL ASSY.		1,800.00	1,500.00
	TO PUTTY AND SPRAY PAINTING FRONT PORTION.		1,800.00	1,500.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	30.00
	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS.		180.00	80.00
	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.		180.00	80.00
	TO REMOVE AND INSTALL FRONT DASHBOARD ASSY INCLUDING INSTRUMENT CLUSTER AND RESET SYSTEM.		350.00	220.00
	TO REMOVE AND INSTALL FRONT AIR CON EVAPORATOR ASSY AND REFILL GAS.		180.00	150.00
	TO REPAIR, STRAIGHTEN AND ALIGN FRONT RIGHT DOOR PANEL.	NOT NECESSARY	180.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.		150.00	120.00
	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM.		80.00	30.00
	TO TRANSFER DOOR GLASS TO NEW DOOR.		80.00	30.00
	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION.		80.00	60.00
	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS TO FACILITATE THE REPAIR.		140.00	120.00
	TO CONDUCT CHASSIS ALIGNMENT.		350.00	300.00
	TO REMOVE AND INSTALL FRONT LOCK MECHANISM.		80.00	30.00
	TOWING SERVICE.		180.00	150.00
			5,860.00	4,400.00
<b>GRAND TOTAL</b>			<b>35,178.90</b>	<b>21,612.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>15,000.00</b>

Report Ref No. CS3/ASM19007019/Asd3s2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.