

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number : 68662672

Date Generated : 19/10/2019 User ID : GohKK2

Section A - Accident Details					
Registration Number	SG1747K				
Case Reference Number	BUS/10/19/6001				
Registration Date	1/3/2016				
Company Type	SMRT Buses Ltd				
Make	MAN				
Model	MAN NL320F(A22)				
Name of Driver	Shahnan Bin Mohd Shariff				
Type of Accident	Side Swipe				
Accident Date and Time	18/10/2019 10:22 AM				
Accident Reported Date and Time	18/10/2019 12:15 PM				
ls Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number					
Special Instruction to ARC, if any	SG1747K-RIGHT REAR PORTION SHD7251E (TP) INSURED WITH III				
Prepared Date and Time	19/10/2019 9:28 AM				
Chassis Number	WMAA22ZZXF7002871				
Mileage					
Work Shop					
Repair Completion Date and Time					

	Section B - Summary of Repa	ir Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$795.00	\$0.00			
Total Spray Cost	\$786.00	\$0.00			
Total Spare Part Cost	\$0.00	\$0.00			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$1,581.00	\$0.00			
Lump Sum Total	\$1,600.00	\$0.00			
Number of Repair Days	3.0	0			
Prepared / Adjusted By	Kok Khoon Goh	1			
ARC / Surveyor Sign Off Date					
Signature	9	×			
Remarks					

Stere CLKK) 21/10/19, 9.0gm WL MyrL 2 Ly LIS M/L Sy

Quotation Number	Invoice Number	
Quotation Date	Invoice Date	
Invoice Amount	Prepared Date	

Page 1 of 2 Podermings of Finder Service and other a

Theil train turning new at William Prejudice" basis
 Women on the second of places of

bna deyeva ar en izum a men a vegyer and

in telepron of an account from insurance Company

1910157

1000



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/10/2019 User ID : GohKK2

			Secti	on D - Deta	ails of Repair E	stimates			TX -7 X 1 1 -1
Part 1 - Labor	ur Works			V.93.117			1. 0		TOTAL PERC
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00				\$40 530		
Total Labour			\$795.00						
Part 2 - Spray	Painting & P	anel Beating Rela	ited Works						121 121 121
Job Scope				Quotation f	rom ARC		A 16.5	Adjusted by Surveyo	or, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				616	1	
Total Spray Pa	inting & Panel	Beating		\$786.00				- 1	4
Part 3 - Other	Costs - Accid	dent and Accident	Repair Related Expens	se		Total Control	Branch La	all its bares	
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Co	sts								
Part 4 - Spare	Parts / Mater	ial Usage		Evel J. L.			Do- 3 m (s		
	Parts / Mater		Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Part Number		Stock Number		Quantity	List Price (\$) \$710.70	Discount (%)	Final Price (\$) \$0.00	Estimator Approved	Surveyor Approved
Part Number 6009990	Portion	Stock Number	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22					A CONTRACTOR OF THE PARTY OF TH	Surveyor Approved
Part Number 6009990 6009991	Portion BODY RH	Stock Number A01001-CW565 4000F06-	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS PANEL,SIDE:R10,FOR	1.00	\$710.70	100.00	\$0.00	Repair	Surveyor Approved
Part Number 6009990 6009991 6009992	Portion BODY RH BODY RH	Stock Number A01001-CW565 4000F06- ACCE4526	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS PANEL,SIDE:R10,FOR MAN A22 BUS PANEL,SIDE:R11,FOR	1.00	\$710.70 \$192.70	100.00	\$0.00 \$0.00 \$0.00	Repair Repair	Surveyor Approved
Part Number 6009990 6009991 6009992 6010062	BODY RH BODY RH BODY RH	Stock Number A01001-CW565 4000F06-ACCE4526 A01001-CW564	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS PANEL,SIDE:R10,FOR MAN A22 BUS PANEL,SIDE:R11,FOR MAN A22 BUS COVER:REAR TAIL LAMP,RH,FOR MAN A22	1.00	\$710.70 \$192.70 \$1,782.50	100.00	\$0.00 \$0.00 \$0.00	Repair Repair Repair	Surveyor Approved
Part Number 6009990 6009991 6009992 6010062 Total	Portion BODY RH BODY RH BODY RH BODY RH	Stock Number A01001-CW565 4000F06- ACCE4526 A01001-CW564 F01001-CW273	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS PANEL,SIDE:R10,FOR MAN A22 BUS PANEL,SIDE:R11,FOR MAN A22 BUS COVER:REAR TAIL LAMP,RH,FOR MAN A22	1.00	\$710.70 \$192.70 \$1,782.50 \$974.70	100.00	\$0.00 \$0.00 \$0.00 \$0.00	Repair Repair Repair	Surveyor Approved
Part Number 6009990 6009991 6009992 6010062 Total	Portion BODY RH BODY RH BODY RH BODY RH	Stock Number A01001-CW565 4000F06- ACCE4526 A01001-CW564 F01001-CW273	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS PANEL,SIDE:R10,FOR MAN A22 BUS PANEL,SIDE:R11,FOR MAN A22 BUS COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$710.70 \$192.70 \$1,782.50 \$974.70	100.00	\$0.00 \$0.00 \$0.00 \$0.00	Repair Repair Repair Repair	Surveyor Approved

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: