

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP111
Xiao Tony.
NH?1707155511

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

21 Oct 2019

Acknowledged by Repairer

Signature:

Date:

Accident date: 17th OCT 2019

Estimated repair cost for vehicle no: SGMN9767J TOYOTA SIENTA 1.5A 2019

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -RH <i>wt</i>		\$1,325.60 ✓
2	1	Front head lamp lower bracket-RH <i>new</i>		\$155.20 X
3	1	bonnet lock <i>2011 new</i>		\$225.30 X
4	1	Front grille centre granish <i>?</i>		\$285.30 X
5	1	Front grille <i>1M</i>		\$385.00 X
6	1	Front Grille clips <i>new</i>		\$50.00 X
7	1	Front grille emble logo		\$65.00 X
8	1	Front bumper <i>Deformed</i>		\$1,377.00 679
9	2	Front bumper side bracket <i>RH New</i>	\$194.34	\$388.68 46
10	8	Front bumper clips <i>new</i>	\$12.90	\$103.20 30
11	1	front Bumper inner sponge <i>cauled</i>		\$297.57 97.60
12	1	Front bumper reinforcement <i>green</i>		\$534.90 X
13	1	Front bumper number plate		\$50.00 X
14	1	Front bumper lower center garnish <i>new new</i>		\$385.10 X
15	1	Front Bumper mud flap <i>green</i>		\$65.30 X
16	1	Front bumper fog lamp chome-RH		\$85.20 X
17	1	front fender-RH <i>Deformed</i>		\$820.00 690
18	1	Front fender lower logo <i>new</i>		\$35.00 ✓
19	1	front fender cowling-RH <i>Deformed</i>		\$221.30 ✓
20	8	Front R/H fender cowling clips <i>new</i>	\$12.90	\$103.20 20
21	1	Front water tank <i>Deformed</i>		\$285.30 ✓
22	1	front shock absorber-RH <i>Best</i>		\$425.30 ✓
23	1	front lower arm-RH <i>Best</i>		\$385.20 ✓
24	1	front knuckle arm-RH <i>Best</i>		\$368.20 ✓
25	1	front bearing-RH <i>new</i>		\$182.50 ✓
26	1	Front sport Rim -RH <i>wt</i>		\$500.00 ✓
27	1	front tyre -RH <i>new</i>		\$300.00 X

Subtotal :- \$9,404.35

Labour charges

To remove & re-fix fender side glass

\$120.00 X

Gum

To Remove & refix front undercarriage

\$50.00 X

To check wheel alignment computer

\$280.00 220

Tuff kote

\$120.00 80

Towing charges

\$120.00 X

Panel beating

\$100.00 X

Spray painting

\$800.00 500

subtotal:-

\$800.00 400

Total:-

\$2,390.00

\$11,794.35

5301

3975.75

total: 5175.75

4/8: 4.11C

05 hys