

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2019 Edit Reg		21 Oct 2019 00:00 Edit Adj Rpt	S\$3,950.00 Edit Estimates	S\$3,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Wong Wai Leong , ID: S7802131D									
Main Claimant: MOHAMAD FITRI SHAHREZA BIN SAZLI , ID: T0000844Z									
Vehicle Reg. No.:	FBP2957T	Date of Loss:	31/08/2019 14:00 - :59 [5 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900026159	Policy/Cover Note No.:	PNPV2018-00011105-01 (TP, Fire & Theft) Coverage: 25/08/2019 - 24/08/2020						
Vehicle Reg. No. (Insured):	SJV9648M	Policy No. (Claimant):	D19MTMC01001985						
		Excess:							
Repairer:	Chuan Motor Workshop (HQ) 25 KAKI BUKIT ROAD 4, #01-70 SYNERGY @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 31/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (17/04/2020): Alert - Adj Mandate Approved (S\$5900.00) - FBP2957T - Claim Handler: Lionel Tan - FWD_SG (18/03/2020): Alert - Adj Mandate Approved (S\$4760.00) - FBP2957T - Claim Handler: Lionel Tan - FWD_SG (06/12/2019): LOD									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBP2957T (1201900026159)**
[SJV9648M]

TP
MOHAMAD FITRI SHAHREZA BIN SAZLI
Aug 31 2019 2:00PM
[Wong Wai Leong]
Chuan Motor Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Letters/Correspondences					1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit		

Photos/Images					3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	30/10/19 15:48	Chassis Number	1	Load JPG	✓	
2	30/10/19 15:49	Odometer Reading	1	Load JPG	✓	
3	30/10/19 15:50	General View	1	Load JPG	✓	
4	30/10/19 15:50	General View	1	Load JPG	✓	
5	30/10/19 15:50	General View	1	Load JPG	✓	
6	30/10/19 15:50	General View	1	Load JPG	✓	
7	30/10/19 15:50	General View	1	Load JPG	✓	
8	30/10/19 15:50	General View	1	Load JPG	✓	
9	30/10/19 15:50	General View	1	Load JPG	✓	
10	30/10/19 15:50	General View	1	Load JPG	✓	
11	30/10/19 15:50	General View	1	Load JPG	✓	
12	30/10/19 15:50	General View	1	Load JPG	✓	
13	30/10/19 15:50	General View	1	Load JPG	✓	
14	30/10/19 15:50	General View	1	Load JPG	✓	
15	30/10/19 15:50	General View	1	Load JPG	✓	
16	30/10/19 15:50	General View	1	Load JPG	✓	
17	30/10/19 15:50	General View	1	Load JPG	✓	
18	30/10/19 15:50	General View	1	Load JPG	✓	
19	30/10/19 15:50	General View	1	Load JPG	✓	
20	30/10/19 15:50	General View	1	Load JPG	✓	
21	30/10/19 15:50	General View	1	Load JPG	✓	
22	30/10/19 15:50	General View	1	Load JPG	✓	
23	30/10/19 15:50	General View	1	Load JPG	✓	
24	30/10/19 15:50	General View	1	Load JPG	✓	
25	30/10/19 15:50	General View	1	Load JPG	✓	
26	30/10/19 15:50	General View	1	Load JPG	✓	
27	30/10/19 15:50	General View	1	Load JPG	✓	
28	30/10/19 15:50	General View	1	Load JPG	✓	
29	30/10/19 15:50	General View	1	Load JPG	✓	
30	30/10/19 15:50	General View	1	Load JPG	✓	
31	30/10/19 15:50	General View	1	Load JPG	✓	
32	30/10/19 15:51	General View	1	Load JPG	✓	
33	30/10/19 15:51	General View	1	Load JPG	✓	
34	30/10/19 15:51	General View	1	Load JPG	✓	
35	30/10/19 15:51	General View	1	Load JPG	✓	
36	30/10/19 15:51	General View	1	Load JPG	✓	
37	30/10/19 15:51	General View	1	Load JPG	✓	

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	30/10/19 15:51	General View		Load JPG	☒
39	30/10/19 15:51	General View		Load JPG	☒
40	30/10/19 15:51	General View		Load JPG	☒
41	30/10/19 15:51	General View		Load JPG	☒
42	30/10/19 15:51	General View		Load JPG	☒
43	30/10/19 15:51	General View		Load JPG	☒
44	30/10/19 15:51	General View		Load JPG	☒
45	30/10/19 15:51	General View		Load JPG	☒
46	30/10/19 15:51	General View		Load JPG	☒
47	30/10/19 15:51	General View		Load JPG	☒
48	30/10/19 15:51	General View		Load JPG	☒
49	30/10/19 15:51	General View		Load JPG	☒
50	30/10/19 15:51	General View		Load JPG	☒
51	30/10/19 15:51	General View		Load JPG	☒
52	30/10/19 15:52	General View		Load JPG	☒
53	30/10/19 15:52	General View		Load JPG	☒
54	30/10/19 15:52	General View		Load JPG	☒
55	30/10/19 15:52	General View		Load JPG	☒
56	30/10/19 15:52	General View		Load JPG	☒
57	30/10/19 15:52	General View		Load JPG	☒
58	30/10/19 15:52	General View		Load JPG	☒
59	30/10/19 15:52	General View		Load JPG	☒
60	30/10/19 15:52	General View		Load JPG	☒
61	30/10/19 15:52	General View		Load JPG	☒
62	30/10/19 15:53	General View		Load JPG	☒
63	30/10/19 15:53	General View		Load JPG	☒
64	30/10/19 15:53	General View		Load JPG	☒
65	30/10/19 15:53	General View		Load JPG	☒
66	30/10/19 15:53	General View		Load JPG	☒
67	30/10/19 15:53	General View		Load JPG	☒
68	30/10/19 15:53	General View		Load JPG	☒
69	30/10/19 15:53	General View		Load JPG	☒
70	30/10/19 15:53	General View		Load JPG	☒
71	30/10/19 15:53	General View		Load JPG	☒
72	30/10/19 15:53	General View		Load JPG	☒
73	30/10/19 15:53	General View		Load JPG	☒
74	30/10/19 15:53	General View		Load JPG	☒
75	30/10/19 15:53	General View		Load JPG	☒
76	30/10/19 15:53	General View		Load JPG	☒
77	30/10/19 15:53	General View		Load JPG	☒
78	30/10/19 15:53	General View		Load JPG	☒
79	30/10/19 15:53	General View		Load JPG	☒
80	30/10/19 15:53	General View		Load JPG	☒
81	30/10/19 15:53	General View		Load JPG	☒
82	30/10/19 15:54	General View		Load JPG	☒
83	30/10/19 15:54	General View		Load JPG	☒
84	30/10/19 15:54	General View		Load JPG	☒
85	30/10/19 15:54	General View		Load JPG	☒
86	30/10/19 15:54	General View		Load JPG	☒
87	30/10/19 15:54	General View		Load JPG	☒
88	30/10/19 15:54	General View		Load JPG	☒
89	30/10/19 15:54	General View		Load JPG	☒
90	30/10/19 15:54	General View		Load JPG	☒

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
91	30/10/19 15:54	General View		Load JPG	☒
92	30/10/19 15:54	General View		Load JPG	☒
93	30/10/19 15:54	General View		Load JPG	☒
94	30/10/19 15:54	General View		Load JPG	☒
95	30/10/19 15:54	General View		Load JPG	☒
96	30/10/19 15:54	General View		Load JPG	☒
97	30/10/19 15:54	General View		Load JPG	☒
98	30/10/19 15:54	General View		Load JPG	☒
99	30/10/19 15:54	General View		Load JPG	☒
100	30/10/19 15:54	General View		Load JPG	☒
101	30/10/19 15:54	General View		Load JPG	☒
102	30/10/19 15:54	General View		Load JPG	☒
103	30/10/19 15:54	General View		Load JPG	☒
104	30/10/19 15:54	General View		Load JPG	☒
105	30/10/19 15:54	General View		Load JPG	☒
106	30/10/19 15:54	General View		Load JPG	☒
107	30/10/19 15:54	General View		Load JPG	☒
108	30/10/19 15:54	General View		Load JPG	☒
109	30/10/19 15:54	General View		Load JPG	☒
110	30/10/19 15:54	General View		Load JPG	☒
111	30/10/19 15:54	General View		Load JPG	☒
112	30/10/19 15:55	General View		Load JPG	☒
113	30/10/19 15:55	General View		Load JPG	☒
114	30/10/19 15:55	General View		Load JPG	☒
115	30/10/19 15:55	General View		Load JPG	☒
116	30/10/19 15:55	General View		Load JPG	☒
117	30/10/19 15:55	General View		Load JPG	☒
118	30/10/19 15:55	General View		Load JPG	☒
119	30/10/19 15:55	General View		Load JPG	☒
120	30/10/19 15:55	General View		Load JPG	☒
121	30/10/19 15:55	General View		Load JPG	☒
122	30/10/19 15:55	General View		Load JPG	☒
123	30/10/19 15:55	General View		Load JPG	☒
124	30/10/19 15:55	General View		Load JPG	☒
125	30/10/19 15:55	General View		Load JPG	☒
126	30/10/19 15:55	General View		Load JPG	☒
127	30/10/19 15:55	General View		Load JPG	☒
128	30/10/19 15:55	General View		Load JPG	☒
129	30/10/19 15:55	General View		Load JPG	☒
130	30/10/19 15:55	General View		Load JPG	☒
131	30/10/19 15:55	General View		Load JPG	☒
132	30/10/19 15:55	General View		Load JPG	☒
133	30/10/19 15:55	General View		Load JPG	☒
134	30/10/19 15:55	General View		Load JPG	☒
135	30/10/19 15:55	General View		Load JPG	☒
136	30/10/19 15:55	General View		Load JPG	☒
137	30/10/19 15:55	General View		Load JPG	☒
138	30/10/19 15:55	General View		Load JPG	☒
139	30/10/19 15:55	General View		Load JPG	☒
140	21/11/19 09:59	Reinspection Photo		Load JPG	☒
141	21/11/19 09:59	Reinspection Photo		Load JPG	☒
142	21/11/19 09:59	Reinspection Photo		Load JPG	☒
143	21/11/19 09:59	Reinspection Photo		Load JPG	☒

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
144	21/11/19 09:59	Reinspection Photo		Load JPG	☒
145	21/11/19 09:59	Reinspection Photo		Load JPG	☒
146	21/11/19 09:59	Reinspection Photo		Load JPG	☒
147	21/11/19 09:59	Reinspection Photo		Load JPG	☒
148	21/11/19 09:59	Reinspection Photo		Load JPG	☒
149	21/11/19 09:59	Reinspection Photo		Load JPG	☒
150	21/11/19 09:59	Reinspection Photo		Load JPG	☒
151	21/11/19 09:59	Reinspection Photo		Load JPG	☒
152	21/11/19 09:59	Reinspection Photo		Load JPG	☒
153	21/11/19 09:59	Reinspection Photo		Load JPG	☒
154	21/11/19 09:59	Reinspection Photo		Load JPG	☒
155	21/11/19 09:59	Reinspection Photo		Load JPG	☒
156	21/11/19 09:59	Reinspection Photo		Load JPG	☒
157	21/11/19 09:59	Reinspection Photo		Load JPG	☒
158	21/11/19 09:59	Reinspection Photo		Load JPG	☒
159	21/11/19 09:59	Reinspection Photo		Load JPG	☒
160	21/11/19 09:59	Reinspection Photo		Load JPG	☒
161	21/11/19 09:59	Reinspection Photo		Load JPG	☒
162	21/11/19 09:59	Reinspection Photo		Load JPG	☒
163	21/11/19 09:59	Reinspection Photo		Load JPG	☒
164	21/11/19 09:59	Reinspection Photo		Load JPG	☒
165	21/11/19 09:59	Reinspection Photo		Load JPG	☒
166	21/11/19 09:59	Reinspection Photo		Load JPG	☒
167	21/11/19 09:59	Reinspection Photo		Load JPG	☒
168	21/11/19 09:59	Reinspection Photo		Load JPG	☒
169	21/11/19 09:59	Reinspection Photo		Load JPG	☒
170	21/11/19 09:59	Reinspection Photo		Load JPG	☒
171	21/11/19 09:59	Reinspection Photo		Load JPG	☒
172	21/11/19 09:59	Reinspection Photo		Load JPG	☒
173	21/11/19 09:59	Reinspection Photo		Load JPG	☒
174	21/11/19 09:59	Reinspection Photo		Load JPG	☒
175	21/11/19 09:59	Reinspection Photo		Load JPG	☒
176	21/11/19 09:59	Reinspection Photo		Load JPG	☒
177	21/11/19 09:59	Reinspection Photo		Load JPG	☒
178	21/11/19 09:59	Reinspection Photo		Load JPG	☒
179	21/11/19 09:59	Reinspection Photo		Load JPG	☒
180	21/11/19 09:59	Reinspection Photo		Load JPG	☒
181	21/11/19 09:59	Reinspection Photo		Load JPG	☒
182	21/11/19 09:59	Reinspection Photo		Load JPG	☒
183	21/11/19 09:59	Reinspection Photo		Load JPG	☒
184	21/11/19 09:59	Reinspection Photo		Load JPG	☒
185	21/11/19 09:59	Reinspection Photo		Load JPG	☒
186	21/11/19 09:59	Reinspection Photo		Load JPG	☒
187	21/11/19 09:59	Reinspection Photo		Load JPG	☒
188	21/11/19 09:59	Reinspection Photo		Load JPG	☒
189	21/11/19 09:59	Reinspection Photo		Load JPG	☒
190	21/11/19 10:00	Reinspection Photo		Load JPG	☒
191	21/11/19 10:00	Reinspection Photo		Load JPG	☒
192	21/11/19 10:00	Reinspection Photo		Load JPG	☒
193	21/11/19 10:00	Reinspection Photo		Load JPG	☒
194	21/11/19 10:00	Reinspection Photo		Load JPG	☒
195	21/11/19 10:00	Reinspection Photo		Load JPG	☒
196	21/11/19 10:00	Reinspection Photo		Load JPG	☒

Letters/Correspondences				1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
197	21/11/19 10:00	Reinspection Photo		Load JPG	✓
198	21/11/19 10:00	Reinspection Photo		Load JPG	✓
199	21/11/19 10:00	Reinspection Photo		Load JPG	✓
200	21/11/19 10:00	Reinspection Photo		Load JPG	✓
201	21/11/19 10:00	Reinspection Photo		Load JPG	✓
202	21/11/19 10:00	Reinspection Photo		Load JPG	✓
203	21/11/19 10:00	Reinspection Photo		Load JPG	✓
204	21/11/19 10:00	Reinspection Photo		Load JPG	✓
205	21/11/19 10:00	Reinspection Photo		Load JPG	✓
206	21/11/19 10:00	Reinspection Photo		Load JPG	✓
207	21/11/19 10:00	Reinspection Photo		Load JPG	✓
208	21/11/19 10:00	Reinspection Photo		Load JPG	✓
209	21/11/19 10:00	Reinspection Photo		Load JPG	✓
210	21/11/19 10:00	Reinspection Photo		Load JPG	✓
211	21/11/19 10:00	Reinspection Photo		Load JPG	✓
212	21/11/19 10:00	Reinspection Photo		Load JPG	✓
213	21/11/19 10:00	Reinspection Photo		Load JPG	✓
Documentation				1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/10/19 14:43	EMAIL FROM FWD DD 21102019.		Load PDF	
2	21/10/19 14:43	WKSP NOTICE		Load PDF	
3	21/10/19 14:43	FWD EMAIL TO INSURED DD 21102019		Load PDF	
4	17/04/20 09:15	EMAIL TO FWD DD 170420		Load PDF	
5	27/05/20 10:23	Authorisation to Act		Load PDF	
6	27/05/20 10:23	LOD		Load PDF	
7	27/05/20 10:23	Release Voucher		Load PDF	
8	27/05/20 10:23	WORKSHOP INVOICE		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	21/10/19 15:40	FBP2957T TP GIA		Load PDF	
2	21/10/19 15:40	SJV9648M OI GIA		Load PDF	
3	03/12/19 11:47	LOD		Load PDF	
4	03/12/19 12:07	SURVEY REPORT		Load PDF	
5	03/12/19 12:15	SURVEY PHOTOS PART 1		Load PDF	
6	03/12/19 12:15	SURVEY PHOTOS PART 2		Load PDF	
7	03/12/19 12:15	SURVEY PHOTOS PART 3		Load PDF	
8	03/12/19 12:15	SURVEY PHOTOS PART 4		Load PDF	
9	03/12/19 12:15	SURVEY PHOTOS PART 5		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJV9648M (Insd veh)	Model:	YAMAHA YZF-R155 155CC
	FBP2957T (TP veh)		
Date of Accident:	31/08/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	8,142.80
Final Repair Cost	:	\$	5,000.00
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	10.00 days at \$30.00 per day
LTA / GIA Search Fee	:	\$	days
Others:	:	\$	600.00
	:	\$	
Final Settlement Sum	:	\$	5,900.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Global Loss Adjusters	:	\$ 5,900.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

27 May
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD19018519/HPB3S2**Date:** 27/05/2020REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00011105-01
Claimant Vehicle No :	FBP2957T	Insured Vehicle No :	SJV9648M
Date of Loss:	31/08/2019	Nature of Claim:	TP
			Claim No: 1201900026159

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP2957T	Engine No:	G3J8E0181671
Make & Model:	YAMAHA YZF-R155, 155cc	Chassis No:	MH3RG4710KK097548
Reg. Date:	11/03/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/60-17	Rear Tyre Size:	150/60-17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,462.80	4,566.90	2,895.90	38.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	405.00	275.00	40.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,142.80	4,971.90	3,170.90	38.94
Approved Total (Overridden) (\$\$)		3,950.00		
Nett Amount (\$\$)	8,142.80	3,950.00	4,192.80	51.49
+ Loss of Use (10.0 x S\$30.00/day) (\$\$)		300.00		
+ Adjuster/Survey Fee (\$\$)		600.00		
Nett Liability (\$\$)		4,850.00		

INSPECTION

Date of Assignment:	21/10/2019	
Date Inspected:	21/10/2019 Inspected At:	Chuan Motor Workshop (HQ) 25 KAKI BUKIT ROAD 4, #01-70 SYNERGY @ KB Singapore 417800
Estimated Period of Repair:	5.0 days	

Adjuster: LEE HOCK ANN**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 May 2020)	
Parts:	N/A	YAMAHA YZF-R155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP2957T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR RH	Crushed	180.00 FN	*120.00 FN
2	1		*HANDLE BAR LH	Crushed	180.00 FN	*120.00 FN
3	1		*SET HANDLE BAR GRIPS	Bent	80.00 FN	*65.00 FN
4	1		*SET HANDLE BAR BALANCER	Scratched	95.00 FN	*50.00 FN
5	1		*FRONT WINDSCREEN	Serviceable	75.00 FN	*- FN
6	1		*BRAKE LEVER	Crushed	130.00 FN	*58.00 FN
7	1		*CLUTCH LEVER	Cut	140.00 FN	*75.00 FN
8	1		*FRONT SIDE FAIRING INNER GARNISH RH	Scratched	280.00 FN	*225.00 FN
9	1		*FRONT SIDE FAIRING INNER GARNISH LH	Scratched	280.00 FN	*225.00 FN
10	1		*FRONT SIDE FAIRING OUTER GARNISH RH	Scratched	370.00 FN	*250.00 FN
11	1		*FRONT SIDE FAIRING OUTER GARNISH LH	Scratched	370.00 FN	*250.00 FN
12	1		*FRONT WHEEL FENDER	Repair	250.00 FN	*- FN
13	1		*HEADLAMP ASSEMBLY	Scratched	450.00 FN	*380.00 FN
14	1		*HEADLAMP OUTER COVER	Cracked	182.00 FN	*105.00 FN
15	2		*FRONT SPRING FORK RH & LH	Bent	900.00 FN	*810.00 FN
16	1		*FRONT STEERING STEM UPPER	Repair	150.00 FN	*- FN
17	1		*FRONT STEERING STEM LOWER	Repair	230.00 FN	*- FN
18	2		*FRONT STEERING BEARING (UPPER & LOWER)	Necessary	210.00 FN	*120.00 FN
19	1		*RHS & LHS SIDE MIRROR	Cracked	190.00 FN	*95.00 FN
20	1		*RHS & LHS FRONT SIGNAL LAMP	Cracked	130.00 FN	*80.00 FN
21	1		*RH FRONT FOOTREST W/BACKET	Cracked	120.00 FN	*78.00 FN
22	1		*RH REAR FOOTREST W/BACKET	Cracked	120.00 FN	*78.00 FN
23	1		*RH & LH REAR SEAT SIDE FAIRING	N/s Scratched	500.00 FN	*200.00 FN
24	1		*REAR SWING ARM LHS	Cut	280.00 FN	*252.00 FN
25	1		*CENTRE FRONT COMPONENT (NPA)	Repair	0.00 FN	*- FN
26	1		*RHS SIDE STAND	Crushed	55.00 FN	*35.00 FN
27	1		*BRAKE PEDAL FOOT REST	Jammed	55.00 FN	*40.00 FN
28	1		*REAR EXHAUST MUFFLER PIPE ASSEMBLY	Cut	650.00 FN	*585.00 FN
29	1		*REAR EXHAUST HEAT COVER	Cracked	130.00 FN	*95.00 FN
30	1		*REAR BRAKE DISC PLATE	Repair	260.00 FN	*- FN
31	1		*FRONT LICENCE STICKER	Necessary	25.00 FS	*10.00 FS
32	1		*REAR SPORTS RIM	Cut	750.00 FS	*365.00 FS
33	1		*REAR TYRE (@ \$125.00 DISC 60%)	Cut	125.00 FS	*75.00 FS
34	1		*REAR NUMBER PLATE	Crushed	45.00 FS	*15.00 FS
35	1		*BOLTS / MICS / SEALS	Serviceable	30.00 FS	*- FS
36	1		*IU UNIT	Scratched	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	8,167.00	5,006.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	704.20	439.10
Total Parts (\$\$)	7,462.80	4,566.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND COMPONENTS.	New	500.00	300.00
2	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED.	New	60.00	20.00
3	TO ALIGN FRONT LEFT & RIGHT FORK.	New	60.00	40.00
4	TRANSPORT MOTORCYCLE TO WORKSHOP FOR REPAIRS.	New	60.00	45.00
Gross Labour Cost (\$\$)			680.00	405.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >