

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53066**
Date Estimated : **14/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
288B Bukit Batok Street 25
#09-04

Singapore 651288

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG2107	03/05/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front right door and attachments, front right fender, right wing mirror including to remove and install body parts in order to carry out painting job.	1,700.00 ✓	10.00	1,530.00
* To respray front right door, front right fender and right wing mirror cover.	2,063.00	10.00	1,856.70
To check electrical wiring systems at the front section for proper function.	150.00 ✓	10.00	135.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.	451.00 ✓	10.00	405.90
* To carry out body cavity preservation.	200.00 ✓	10.00	180.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT	2.10	2.00	3.00	4.07 ✓
# PLUG IN RETAINER	4.00	4.00	3.00	15.52 ✓
FRT RH DOOR	1,197.80	1.00	3.00	1,161.87 ✓
FRT RH SIDE PANEL	664.00	1.00	3.00	644.08 ✓
LETTERING S DRIVE 18i	96.65	1.00	3.00	93.75 ✓
RH MIRROR GLASS HEATED WIDE ANGLE	680.35	1.00	3.00	659.94 ✓
RH OUTSIDE MIRROR COVER CAP PRIMED	121.40	1.00	3.00	117.76 ✓
RH SUPPORTING RING	53.20	1.00	3.00	51.60 ✓
RH LOWER HOUSING SECTION	25.05	1.00	3.00	24.30 ✓
RH EXTERIOR MIRROR W/O MOUNTING PAR	488.55	1.00	3.00	473.89 ✓
# PLUG IN NUT	1.65	2.00	3.00	3.20 ✓
# EXPANDING RIVET BLACK	1.40	20.00	3.00	27.16 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,187.60
Total Parts :	3,277.14
Total Labour & Parts :	7,464.74
GST @7%:	522.53
Grand Total :	7,987.27

LOSS OF USE = \$80 X 5 DAYS
LTA SEARCH FEE - \$7.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53066**
Date Estimated : **14/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
288B Bukit Batok Street 25
#09-04

Singapore 651288

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG2107	03/05/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>ne</i>	2.10	2.00	3.00	4.07
# PLUG IN RETAINER <i>ne</i>	4.00	4.00	3.00	15.52
# PLUG IN NUT <i>ne</i>	1.65	2.00	3.00	3.20
# EXPANDING RIVET BLACK <i>ne</i>	1.40	20.00	3.00	27.16

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	49.95
Total Labour & Parts :	49.95