

Survey only
11/10 @ 10 am

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

14 OCT 2019

Estimate No.	: b1 53066	Page No. : 1 of 5
Date Estimated	: 14/10/2019	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - LIM KWANG JOO 288B Bukit Batok Street 25 #09-04 Singapore 651288	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace front right fender, front right door, wing mirror right and attachments.	1700 3400.00
Painting front right fender and front right door.	1996 2218.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).	451 531.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 150.00
Total Labour 1:	6,594.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH DOOR bt	1	1,197.80	1,197.80
FRT RH SIDE PANEL bt	1	664.00	664.00
FRT RH SIDE PANEL repeated x	1	664.00	664.00
LETTERING S DRIVE 18i re	1	96.15	96.15
RH MIRROR GLASS HEATED WIDE ANGLE cr	1	680.35	680.35
RH OUTSIDE MIRROR COVER CAP PRIMED repair	1	121.40	121.40
RH SUPPORTING RING re	1	53.20	53.20
RH LOWER HOUSING SECTION cr	1	25.05	25.05
RH EXTERIOR MIRROR W/O MOUNTING PAR bu	1	488.55	488.55
FRT DOOR EGDE PROTECTION re	1	171.00	171.00
FRT RH DOOR JOINT SEAL re	1	59.15	59.15
Total Parts :			4,220.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 04/11/19 @ 1050 Excess S\$ _____

Surveyor's Name Rafin Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	6,594.00
Parts	:	4,220.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	757.03
Grand Total	:	11,571.68

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **