



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23/10/2019

### Survey Details:

Date of loss	12-Oct-19
Date of appointment	21-Oct-19
Date of survey	22-Oct-19
Location of survey	VITAL AUTOWORKS PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLR 3847S
Make and Model	TOYOTA HARRIER 2.0
Date of registration	14/8/2017
Excess	
Market Value	\$105,000
Parf Rebate	\$65,386
Nett Loss	\$39,614

### Repair details:

Initial Estimate	\$ 15,217.50
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 6,301.50
Check items (estimate)	\$ 1,477.00
Labour	\$ 2,000.00
<b>Total</b>	<b>\$ 9,778.50</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>
<b>Number of days for repair</b>	<b>9</b>



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*We have not authorized repairs. We will seek mandate after our surveyor have verify the check items.*

**Mandate:**

Liability(TP)	%	
Proposed repair cost	TBA	
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
<b>Proposed Total</b>	<b>TBA</b>	