

 $51\; UBI\; AVE\; 1,\#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; UBI\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; PAYA\; UBI\; PAY$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 27/11/2019

Survey Details:

Date of loss	12-Oct-19
Date of appointment	21-Oct-19
Date of survey	22-Oct-19
Location of survey	VITAL AUTOWORKS PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLR 3847S
Make and Model	TOYOTA HARRIER 2.0
Date of registration	14/8/2017
Excess	
Market Value	\$105,000
Parf Rebate	\$65,386
Nett Loss	\$39,614

Repair details:

Initial Estimate	\$	15,217.50
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$ 5,143.38
Check items (estimate)	NIL
Labour	\$ 2,100.00
Supplementary	\$ 195.75
Total	\$ 7,439.13
Lump Sum(if applicable)	\$ -
Number of days for repair	10



Remarks:

OID rear-ended third party.	
10 repair days + 2Sunday + 1PH = 13days	

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 7,959.87	\$ 7,959.87
Loss of use (13days x \$100.00)	\$ 1,300.00	NIL
Loss of rental (13days x		
\$150.00)(w/GST)	NIL	\$ 2,086.50
Loss of income	NIL	NIL
LTA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 9,267.32	\$ 10,053.82